

Move Out

TaskMasters, 925 N Main St, Ste A, Meridian, ID, 83642

TASKMASTERS

1883 W Creek Ct

1883 W Creek Ct, Nampa, ID 83686, US

Move Out

2019-01-31

Inspector:

office@taskmastersid.com

Tenant:

CONDITION KEY

N - New

S - Satisfactory

! - Action


D - Damaged

Entry: Entry Way	CONDITION	ACTION	COMMENTS
Door/Knob/Lock	- S - -	None	
Doorbell	- S - -	None	
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- S - -	None	
Other	- - - D	None	door stop is stretched out, closet door in the entry way has a hole from the door stop, door trim is damaged
Security/Screen Door	- - - D	None	Holes in door
Switch/Outlet	- S - -	None	
Wall/Ceiling	- - - D	None	Holes



Taken on: 2019-01-29 11:04:47

Taken at: [43.56526059, -116.60377546](https://www.google.com/maps/place/43.56526059,-116.60377546)
[Image](#)



Door/Knob/Lock

Taken on: 2019-01-29 11:05:01

Taken at: [43.56532261, -116.60400052](https://www.google.com/maps/place/43.56532261,-116.60400052)
[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 11:05:16

Taken at: [43.56531073, -116.60382018](#)

[Image](#)



Light Fixture/Fan

Taken on: 2019-01-29 11:05:26

Taken at: [43.56533772, -116.60383395](#)

[Image](#)



Security/Screen Door

Taken on: 2019-01-29 11:05:42

Taken at: [43.56531829, -116.60383174](#)

[Image](#)



Switch/Outlet

Taken on: 2019-01-29 11:06:01

Taken at: [43.56527333, -116.6038437](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 11:06:19

Taken at: [43.5652713, -116.60384407](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 11:06:26

Taken at: [43.5652713, -116.60384407](#)

[Image](#)



Other

Taken on: 2019-01-29 11:07:15

Taken at: [43.56532743, -116.60386509](#)

[Image](#)



Other

Taken on: 2019-01-29 11:09:00

Taken at: [43.56530183, -116.60384424](#)

[Image](#)



Other

Taken on: 2019-01-29 14:08:06

Taken at: [43.56541617, -116.60375666](#)

[Image](#)



Other

Taken on: 2019-01-29 14:09:33

Taken at: [43.56535576, -116.60381229](#)

[Image](#)

Front Yard/Exterior: Front Yard and Exterior

CONDITION


ACTION

COMMENTS

Building Exterior	- S - -	None
Fence/Gate	- S - -	None
Landscaping	- S - -	None
Light Fixture	- S - -	None
Mailbox/Keyed Location	- S - -	None
Other	- S - -	None
Patio Cover	- S - -	None
Patio/Deck/Balcony	- S - -	None
Porch/Stairs	- S - -	None
Sprinkler/Timer	- S - -	None
Walk/Driveway	- S - -	None




Taken on: 2019-01-29 14:09:56
Taken at: [43.56538795, -116.60383994](#)
[Image](#)



Fence/Gate
Taken on: 2019-01-29 14:10:28
Taken at: [43.56542228, -116.60382999](#)
[Image](#)



Landscaping
Taken on: 2019-01-29 14:10:48
Taken at: [43.56545135, -116.60384511](#)
[Image](#)



Landscaping
Taken on: 2019-01-29 14:10:55
Taken at: [43.56545135, -116.60384511](#)
[Image](#)



Landscaping
Taken on: 2019-01-29 14:11:06
Taken at: [43.56557352, -116.60394612](#)
[Image](#)



Landscaping
Taken on: 2019-01-29 14:11:18
Taken at: [43.56555182, -116.60397738](#)
[Image](#)



Landscaping

Taken on: 2019-01-29 14:11:28

Taken at: [43.56534985, -116.60395297](#)

[Image](#)



Mailbox/Keyed Location

Taken on: 2019-01-29 14:11:50

Taken at: [43.56539978, -116.60384691](#)

[Image](#)

Bathroom 1: Master Bath #1	CONDITION	ACTION	COMMENTS
Cabinet/Counter/Shelving	- - - D	None	Cabinets are scratched and worn
Door/Knob/Lock	- - - D	None	Lock slider near top of door
Exhaust Fan	- - - D	None	Dirty
Flooring/Baseboard	- S - -	None	
Light Fixture	- S - -	None	
Medicine Cabinet/Mirror	- S - -	None	
Other	- S - -	None	
Plumbing/Drain	- S - -	None	
Shower Door/Rail/Curtain	- - - D	None	Command hook on shower glass, shower door has hard water spots
Sink/Faucet	- - - D	None	Clip missing on back of faucet hindering the stopper from working properly
Switch/Outlet	- - - D	None	small crack on outlet cover
Toilet	- S - -	None	
Toilet Paper Holder	- S - -	None	
Towel Rack	- S - -	None	
Tub/Shower	- S - -	None	Dirty
Wall/Ceiling	- - - D	None	Coat rack hooks left on wall, walls are dirty
Window Covering	- S - -	None	
Window/Lock/Screen	- S - -	None	



Taken on: 2019-01-29 11:10:03
 Taken at: [43.5653049, -116.6038507](#)
[Image](#)



Taken on: 2019-01-29 11:10:12
 Taken at: [43.56535559, -116.60377448](#)
[Image](#)



Taken on: 2019-01-29 11:10:35
 Taken at: [43.56529666, -116.60374568](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:10:50
 Taken at: [43.56535052, -116.60373878](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:11:47
 Taken at: [43.56531794, -116.6037958](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:11:56
 Taken at: [43.56532102, -116.60379345](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:12:09
 Taken at: [43.56531946, -116.60379639](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:12:28
 Taken at: [43.56531857, -116.60379614](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:12:36
 Taken at: [43.56531026, -116.60379295](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:12:58
 Taken at: [43.56530935, -116.60378673](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:15:24
 Taken at: [43.56528441, -116.60377973](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:15:44
 Taken at: [43.56528078, -116.60383461](#)
[Image](#)




Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:16:00
 Taken at: [43.56528078, -116.60383461](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:16:11
 Taken at: [43.56528078, -116.60383461](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:16:21
 Taken at: [43.56525281, -116.60383506](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:16:31
 Taken at: [43.56525609, -116.6038369](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:16:41
 Taken at: [43.56525609, -116.6038369](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:16:52
 Taken at: [43.56525609, -116.6038369](#)
[Image](#)



Door/Knob/Lock

Taken on: 2019-01-29 11:17:04

Taken at: [43.56526447, -116.60382064](#)

[Image](#)



Exhaust Fan

Taken on: 2019-01-29 11:17:21

Taken at: [43.56526497, -116.60381765](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 11:17:48

Taken at: [43.5653037, -116.60378661](#)

[Image](#)



Light Fixture

Taken on: 2019-01-29 11:17:59

Taken at: [43.56530613, -116.60378155](#)

[Image](#)



Light Fixture

Taken on: 2019-01-29 11:18:06

Taken at: [43.56530542, -116.60377901](#)

[Image](#)



Plumbing/Drain

Taken on: 2019-01-29 11:18:23

Taken at: [43.56530401, -116.60377584](#)

[Image](#)



Plumbing/Drain

Taken on: 2019-01-29 11:18:33

Taken at: [43.56530401, -116.60377584](#)

[Image](#)



Shower Door/Rail/Curtain

Taken on: 2019-01-29 11:18:53

Taken at: [43.56531024, -116.60376392](#)

[Image](#)



Sink/Faucet

Taken on: 2019-01-29 11:20:03

Taken at: [43.5653105, -116.60376253](#)

[Image](#)



Sink/Faucet

Taken on: 2019-01-29 11:20:12

Taken at: [43.56530773, -116.60376559](#)

[Image](#)



Sink/Faucet

Taken on: 2019-01-29 11:21:18

Taken at: [43.56529266, -116.60373506](#)

[Image](#)



Switch/Outlet

Taken on: 2019-01-29 11:21:30

Taken at: [43.56531038, -116.60378883](#)

[Image](#)



Toilet

Taken on: 2019-01-29 11:22:13

Taken at: [43.56530165, -116.60376573](#)

[Image](#)



Toilet Paper Holder

Taken on: 2019-01-29 11:22:23

Taken at: [43.56532418, -116.60373826](#)

[Image](#)




Towel Rack

Taken on: 2019-01-29 11:22:35

Taken at: [43.56527626, -116.60378457](#)

[Image](#)



Towel Rack

Taken on: 2019-01-29 11:22:41

Taken at: [43.56527981, -116.6037705](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-29 11:22:55

Taken at: [43.56527801, -116.60376288](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-29 11:23:03

Taken at: [43.56529052, -116.60376014](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-29 11:23:36

Taken at: [43.56533348, -116.60378325](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-29 11:23:53

Taken at: [43.56533162, -116.60378364](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-29 11:24:05

Taken at: [43.5653262, -116.60378575](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-29 11:24:18

Taken at: [43.56532911, -116.60378385](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-29 11:24:28

Taken at: [43.56532966, -116.60378207](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 11:24:56

Taken at: [43.56533284, -116.60377707](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 11:25:19

Taken at: [43.56533147, -116.60377036](#)

[Image](#)



Shower Door/Rail/Curtain

Taken on: 2019-01-29 11:26:21

Taken at: [43.56533862, -116.60374579](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 11:27:11

Taken at: [43.56532451, -116.60378223](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 11:27:28

Taken at: [43.5652448, -116.60376372](#)

[Image](#)



Door/Knob/Lock

Taken on: 2019-01-29 11:28:04

Taken at: [43.56527753, -116.60376685](#)

[Image](#)

Bathroom 2: On Suite

CONDITION

ACTION

COMMENTS

Cabinet/Counter/Shelving	- - - D	None	Bottom shelf has water damage, drawers are dirty, cabinets are worn and scratched
Door/Knob/Lock	- - - D	None	- Door that leads to the outside, weather stripping is damaged, sliding lock on door - Door that lease from bedroom to bath is scratched
Exhaust Fan	- S - -	None	Dirty
Flooring/Baseboard	- - - D	None	base board is scratched and damaged, floor grout dirty
Light Fixture	- - - D	None	broken
Medicine Cabinet/Mirror	- S - -	None	
Other	- S - -	None	
Plumbing/Drain	- S - -	None	
Shower Door/Rail/Curtain	- - - D	None	hard water stains
Sink/Faucet	- - - D	None	Clip missing on back of faucet hindering the stopper from working properly, stopper top is missing
Switch/Outlet	- S - -	None	
Toilet	- S - -	None	decorative toilet seat
Toilet Paper Holder	- S - -	None	mismatch toilet paper roller
Towel Rack	- S - -	None	
Tub/Shower	- S - -	None	
Wall/Ceiling	- - - D	None	dirty
Window Covering	- - - D	None	blind is missing
Window/Lock/Screen	- S - -	None	



Taken on: 2019-01-29 11:30:00
Taken at: [43.56527057, -116.60378712](#)
[Image](#)



Taken on: 2019-01-29 11:30:09
Taken at: [43.56529798, -116.60390303](#)
[Image](#)




Taken on: 2019-01-29 11:30:20
 Taken at: [43.56523072, -116.60390902](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:30:35
 Taken at: [43.56522506, -116.60391048](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:30:43
 Taken at: [43.5652225, -116.60391212](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:30:50
 Taken at: [43.56521976, -116.60391169](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:30:58
 Taken at: [43.56521548, -116.60391198](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:31:42
 Taken at: [43.56523419, -116.6039129](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:31:51
 Taken at: [43.56521715, -116.60399288](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:32:17
 Taken at: [43.56524551, -116.60395122](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:32:32
 Taken at: [43.56524551, -116.60395122](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:32:38
 Taken at: [43.56524876, -116.60393552](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:32:46
 Taken at: [43.56524876, -116.60393552](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:33:21
 Taken at: [43.56522859, -116.60393217](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:33:31
 Taken at: [43.56519908, -116.60390785](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:34:13
 Taken at: [43.56521093, -116.60389474](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:34:26
 Taken at: [43.56521093, -116.60389474](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:34:33
 Taken at: [43.56521124, -116.60389176](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:34:52
 Taken at: [43.56521194, -116.60388614](#)
[Image](#)



Door/Knob/Lock
 Taken on: 2019-01-29 11:35:09
 Taken at: [43.56521712, -116.60387059](#)
[Image](#)



Exhaust Fan

Taken on: 2019-01-29 11:35:56

Taken at: [43.56526789, -116.60391254](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 11:36:34

Taken at: [43.56518831, -116.60393788](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 11:37:16

Taken at: [43.56519436, -116.60384983](#)

[Image](#)



Light Fixture

Taken on: 2019-01-29 11:37:47

Taken at: [43.5651938, -116.60387879](#)

[Image](#)



Plumbing/Drain

Taken on: 2019-01-29 11:38:43

Taken at: [43.56522366, -116.60390741](#)

[Image](#)



Shower Door/Rail/Curtain

Taken on: 2019-01-29 11:39:12

Taken at: [43.56522678, -116.60390713](#)

[Image](#)



Shower Door/Rail/Curtain
Taken on: 2019-01-29 11:40:24
Taken at: [43.56522778, -116.6039127](#)
[Image](#)



Door/Knob/Lock
Taken on: 2019-01-29 11:40:59
Taken at: [43.56523398, -116.60388778](#)
[Image](#)



Door/Knob/Lock
Taken on: 2019-01-29 11:41:15
Taken at: [43.56523245, -116.60388972](#)
[Image](#)



Door/Knob/Lock
Taken on: 2019-01-29 11:41:26
Taken at: [43.56521938, -116.60388858](#)
[Image](#)



Door/Knob/Lock
Taken on: 2019-01-29 11:41:45
Taken at: [43.56522024, -116.60388762](#)
[Image](#)



Door/Knob/Lock
Taken on: 2019-01-29 11:43:01
Taken at: [43.5652322, -116.60391289](#)
[Image](#)



Sink/Faucet

Taken on: 2019-01-29 11:43:17

Taken at: [43.56523191](#), [-116.60391186](#)

[Image](#)



Sink/Faucet

Taken on: 2019-01-29 11:43:33

Taken at: [43.56522811](#), [-116.60390669](#)

[Image](#)



Sink/Faucet

Taken on: 2019-01-29 11:44:30

Taken at: [43.56522073](#), [-116.60391466](#)

[Image](#)



Switch/Outlet

Taken on: 2019-01-29 11:44:40

Taken at: [43.56522078](#), [-116.6039144](#)

[Image](#)



Toilet

Taken on: 2019-01-29 11:44:53

Taken at: [43.56523177](#), [-116.60392298](#)

[Image](#)



Toilet

Taken on: 2019-01-29 11:45:03

Taken at: [43.56520347](#), [-116.60391783](#)

[Image](#)



Toilet Paper Holder

Taken on: 2019-01-29 11:45:39

Taken at: [43.56520143, -116.60391452](#)

[Image](#)




Toilet Paper Holder

Taken on: 2019-01-29 11:46:53

Taken at: [43.56525153, -116.60392088](#)

[Image](#)



Towel Rack

Taken on: 2019-01-29 11:47:03

Taken at: [43.56523207, -116.6039207](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-29 11:47:17

Taken at: [43.56522548, -116.6038749](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-29 11:47:22

Taken at: [43.56542467, -116.60396995](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-29 11:47:29

Taken at: [43.56540327, -116.60396082](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 11:47:44

Taken at: [43.56528795, -116.60389754](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 11:47:57

Taken at: [43.5653953, -116.6039893](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 11:48:43

Taken at: [43.56526077, -116.60395337](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 11:48:51

Taken at: [43.56528851, -116.60398163](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 11:49:23

Taken at: [43.56529955, -116.60388538](#)

[Image](#)



Door/Knob/Lock

Taken on: 2019-01-29 11:49:57

Taken at: [43.56523654, -116.6038866](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 11:50:42

Taken at: [43.56522376, -116.60389537](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 11:51:06

Taken at: [43.56522338, -116.60389965](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 11:51:29

Taken at: [43.56522319, -116.60389476](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 11:54:13

Taken at: [43.56522804, -116.60390548](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 11:54:29

Taken at: [43.56522804, -116.60390548](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 11:54:45

Taken at: [43.56521335, -116.60391387](#)

[Image](#)

Cabinet/Counter/Shelving	- - - D	None	cabinets are worn and scratched
Door/Knob/Lock	- S - -	None	peeling paint
Exhaust Fan	- - - D	None	dirty
Flooring/Baseboard	- - - D	None	grout is cracked
Light Fixture	- S - -	None	
Medicine Cabinet/Mirror	- S - -	None	
Other	- S - -	None	
Plumbing/Drain	- S - -	None	
Shower Door/Rail/Curtain	- S - -	None	
Sink/Faucet	- - - D	None	grout is chipped and missing in places
Switch/Outlet	- S - -	None	
Toilet	- - - D	None	on bottom of toilet white cap is missing showing exposed screw
Toilet Paper Holder	- S - -	None	
Towel Rack	- S - -	None	
Tub/Shower	- - - D	None	Tub faucet is separating
Wall/Ceiling	- - - D	None	Holes, cracked and peeling paint, dirty
Window Covering	- S - -	None	
Window/Lock/Screen	- S - -	None	



Taken on: 2019-01-29 11:55:16

Taken at: [43.56522835, -116.60388902](https://www.google.com/maps/place/43.56522835,-116.60388902)
[Image](#)



Taken on: 2019-01-29 11:55:25

Taken at: [43.56527436, -116.60391653](https://www.google.com/maps/place/43.56527436,-116.60391653)
[Image](#)



Cabinet/Counter/Shelving
Taken on: 2019-01-29 11:56:23
Taken at: [43.56525787, -116.60392187](#)
[Image](#)



Cabinet/Counter/Shelving
Taken on: 2019-01-29 11:56:45
Taken at: [43.56535414, -116.60382216](#)
[Image](#)




Cabinet/Counter/Shelving
Taken on: 2019-01-29 11:56:53
Taken at: [43.56531099, -116.60389087](#)
[Image](#)



Cabinet/Counter/Shelving
Taken on: 2019-01-29 11:57:09
Taken at: [43.56531407, -116.60389369](#)
[Image](#)



Cabinet/Counter/Shelving
Taken on: 2019-01-29 11:57:19
Taken at: [43.56531781, -116.60389275](#)
[Image](#)



Cabinet/Counter/Shelving
Taken on: 2019-01-29 11:57:28
Taken at: [43.56531781, -116.60389275](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:57:35
 Taken at: [43.56531964, -116.60389091](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:57:47
 Taken at: [43.56531821, -116.60389231](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:57:56
 Taken at: [43.56531821, -116.60389231](#)
[Image](#)




Cabinet/Counter/Shelving
 Taken on: 2019-01-29 11:58:07
 Taken at: [43.56531651, -116.60389281](#)
[Image](#)



Door/Knob/Lock
 Taken on: 2019-01-29 11:58:23
 Taken at: [43.56530535, -116.6039053](#)
[Image](#)



Exhaust Fan
 Taken on: 2019-01-29 11:59:04
 Taken at: [43.56530939, -116.60391027](#)
[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 11:59:58

Taken at: [43.56531167, -116.60387797](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 12:00:17

Taken at: [43.56528946, -116.60389445](#)

[Image](#)



Light Fixture

Taken on: 2019-01-29 12:00:50

Taken at: [43.56528519, -116.60389617](#)

[Image](#)



Plumbing/Drain

Taken on: 2019-01-29 12:01:07

Taken at: [43.56528559, -116.6039116](#)

[Image](#)



Switch/Outlet

Taken on: 2019-01-29 12:01:21

Taken at: [43.5652885, -116.60390687](#)

[Image](#)



Toilet

Taken on: 2019-01-29 12:01:27

Taken at: [43.56529008, -116.60390786](#)

[Image](#)



Toilet Paper Holder

Taken on: 2019-01-29 12:01:35

Taken at: [43.56528992, -116.60390841](#)

[Image](#)



Towel Rack

Taken on: 2019-01-29 12:01:55

Taken at: [43.56529127, -116.60390925](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-29 12:02:09

Taken at: [43.56529178, -116.6039076](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-29 12:02:23

Taken at: [43.56526925, -116.60390725](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-29 12:02:31

Taken at: [43.56526883, -116.60389977](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-29 12:02:50

Taken at: [43.56527358, -116.60390767](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-29 12:03:04

Taken at: [43.56528361, -116.60391593](#)

[Image](#)



Toilet

Taken on: 2019-01-29 12:03:23

Taken at: [43.56528177, -116.60392217](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 12:03:55

Taken at: [43.56528335, -116.60392322](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:04:08

Taken at: [43.56529751, -116.60393229](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:04:18

Taken at: [43.56529401, -116.60397738](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:04:34

Taken at: [43.5652863, -116.60396527](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:04:40

Taken at: [43.56529234, -116.60395595](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:04:51

Taken at: [43.56529111, -116.6039528](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:05:06

Taken at: [43.5652899, -116.60395259](#)

[Image](#)



Sink/Faucet

Taken on: 2019-01-29 12:05:26

Taken at: [43.56528016, -116.60392952](#)

[Image](#)



Sink/Faucet

Taken on: 2019-01-29 12:05:33

Taken at: [43.56528016, -116.60392952](#)

[Image](#)



Sink/Faucet

Taken on: 2019-01-29 12:05:45

Taken at: [43.56527739, -116.60392414](#)

[Image](#)



Sink/Faucet

Taken on: 2019-01-29 12:06:00

Taken at: [43.56527739, -116.60392414](#)
[Image](#)



Sink/Faucet

Taken on: 2019-01-29 12:06:08

Taken at: [43.56527251, -116.60392192](#)
[Image](#)

Bedroom 1: Master Bedroom	CONDITION	ACTION	COMMENTS
Closet/Door/Track/Shelving	- - - D	None	Missing door stop cap, bottom shelf in closet is damaged
Door/Knob/Lock	- - - D	None	brushed nickel door handle (mismatched) original handle is in kitchen drawer
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- S - -	None	
Other	- S - -	None	
Switch/Outlet	- - - D	None	outlet cover does not cover entire hole
Wall/Ceiling	- S - -	None	
Window Covering	- - - D	None	hard to open
Window/Lock/Screen	- - - D	None	Damaged



Taken on: 2019-01-29 12:07:49

Taken at: [43.56530348, -116.60390476](#)
[Image](#)



Taken on: 2019-01-29 12:07:56

Taken at: [43.56530348, -116.60390476](#)
[Image](#)



Closet/Door/Track/Shelving

Taken on: 2019-01-29 12:08:19

Taken at: [43.56531451, -116.6037859](#)

[Image](#)



Closet/Door/Track/Shelving

Taken on: 2019-01-29 12:09:16

Taken at: [43.56532053, -116.60373776](#)

[Image](#)



Door/Knob/Lock

Taken on: 2019-01-29 12:12:21

Taken at: [43.56531825, -116.60373473](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 12:13:19

Taken at: [43.56532496, -116.60373383](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 12:13:57

Taken at: [43.56541572, -116.6037973](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 12:14:04

Taken at: [43.56541572, -116.6037973](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 12:14:26

Taken at: [43.56535129, -116.60378171](#)

[Image](#)



Light Fixture/Fan

Taken on: 2019-01-29 12:14:49

Taken at: [43.56528932, -116.60378946](#)

[Image](#)



Switch/Outlet

Taken on: 2019-01-29 12:15:16

Taken at: [43.56528813, -116.60378685](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:16:10

Taken at: [43.56531725, -116.60375855](#)

[Image](#)




Wall/Ceiling

Taken on: 2019-01-29 12:16:18

Taken at: [43.56527739, -116.60382613](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:16:30

Taken at: [43.5652933, -116.60380524](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:17:11

Taken at: [43.56518626, -116.60373352](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:17:18

Taken at: [43.56518626, -116.60373352](#)

[Image](#)




Wall/Ceiling

Taken on: 2019-01-29 12:17:27

Taken at: [43.56518626, -116.60373352](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:17:36

Taken at: [43.56518626, -116.60373352](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:17:48

Taken at: [43.56525337, -116.60378533](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:17:58

Taken at: [43.565185, -116.6037232](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:18:04

Taken at: [43.565185, -116.6037232](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:18:15

Taken at: [43.56528138, -116.60372179](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:18:24

Taken at: [43.56527033, -116.60371112](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:18:33

Taken at: [43.56527033, -116.60371112](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:18:45

Taken at: [43.56527033, -116.60371112](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:18:53

Taken at: [43.56527033, -116.60371112](#)

[Image](#)



Closet/Door/Track/Shelving

Taken on: 2019-01-29 12:19:21

Taken at: [43.56526627, -116.6037107](#)

[Image](#)



Door/Knob/Lock

Taken on: 2019-01-29 12:19:56

Taken at: [43.56524375, -116.60370891](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 12:20:21

Taken at: [43.56527251, -116.60378651](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 12:20:28

Taken at: [43.56527251, -116.60378651](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 12:20:42

Taken at: [43.56527383, -116.6037806](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 12:20:48

Taken at: [43.56527383, -116.6037806](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 12:20:55

Taken at: [43.56527383, -116.6037806](#)

[Image](#)



Other

Taken on: 2019-01-29 12:21:23

Taken at: [43.56527227, -116.60377583](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 12:22:28

Taken at: [43.5653035, -116.60375077](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 12:23:28

Taken at: [43.56528702, -116.60375951](#)

[Image](#)

Bedroom 2: Other Bedroom with On Suite

	CONDITION	ACTION	COMMENTS
Closet/Door/Track/Shelving	- - - D	None	light not attached to ceiling, shelving is broken, carpet is stained, screw holes on back of closet door, door stop missing, closet wall damaged
Door/Knob/Lock	- - - D	None	parts of door trim missing, door stop cap is missing, door paint is peeling
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- - - D	None	ceiling fan does not work
Other	- - - D	None	smoke detector not attach to ceiling, trash in crawl space
Switch/Outlet	- - - D	None	1 - broken
Wall/Ceiling	- - - D	None	dirty
Window Covering	- S - -	None	



Taken on: 2019-01-29 12:24:12

Taken at: [43.5652847, -116.60375434](#)
[Image](#)



Taken on: 2019-01-29 12:24:20

Taken at: [43.56534567, -116.60403944](#)
[Image](#)



Closet/Door/Track/Shelving

Taken on: 2019-01-29 12:24:57

Taken at: [43.56536721, -116.6038988](#)
[Image](#)



Closet/Door/Track/Shelving

Taken on: 2019-01-29 12:25:13

Taken at: [43.56529841, -116.60389098](#)
[Image](#)



Closet/Door/Track/Shelving

Taken on: 2019-01-29 12:25:40

Taken at: [43.56525286, -116.60394001](#)
[Image](#)



Closet/Door/Track/Shelving

Taken on: 2019-01-29 12:25:50

Taken at: [43.56525005, -116.60394484](#)
[Image](#)



Other

Taken on: 2019-01-29 12:26:33

Taken at: [43.56525207, -116.60394853](#)

[Image](#)



Closet/Door/Track/Shelving

Taken on: 2019-01-29 12:27:34

Taken at: [43.56525245, -116.60395656](#)

[Image](#)



Closet/Door/Track/Shelving

Taken on: 2019-01-29 12:27:47

Taken at: [43.5652495, -116.60396128](#)

[Image](#)



Closet/Door/Track/Shelving

Taken on: 2019-01-29 12:27:57

Taken at: [43.56524955, -116.6039596](#)

[Image](#)



Closet/Door/Track/Shelving

Taken on: 2019-01-29 12:28:16

Taken at: [43.56524955, -116.6039596](#)

[Image](#)



Closet/Door/Track/Shelving

Taken on: 2019-01-29 12:28:26

Taken at: [43.56524955, -116.6039596](#)

[Image](#)



Closet/Door/Track/Shelving
 Taken on: 2019-01-29 12:28:36
 Taken at: [43.56524955, -116.6039596](#)
[Image](#)



Closet/Door/Track/Shelving
 Taken on: 2019-01-29 12:28:43
 Taken at: [43.5654049, -116.6038708](#)
[Image](#)



Closet/Door/Track/Shelving
 Taken on: 2019-01-29 12:28:49
 Taken at: [43.5654049, -116.6038708](#)
[Image](#)



Closet/Door/Track/Shelving
 Taken on: 2019-01-29 12:29:24
 Taken at: [43.56525488, -116.60395752](#)
[Image](#)



Closet/Door/Track/Shelving
 Taken on: 2019-01-29 12:31:38
 Taken at: [43.56525541, -116.60395759](#)
[Image](#)



Door/Knob/Lock
 Taken on: 2019-01-29 12:32:03
 Taken at: [43.56523928, -116.60392086](#)
[Image](#)



Door/Knob/Lock

Taken on: 2019-01-29 12:32:33

Taken at: [43.56527396, -116.60395911](#)

[Image](#)



Door/Knob/Lock

Taken on: 2019-01-29 12:33:18

Taken at: [43.5652945, -116.60393459](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 12:33:31

Taken at: [43.56528328, -116.60392236](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 12:33:58

Taken at: [43.56528479, -116.60392292](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 12:34:06

Taken at: [43.56528479, -116.60392292](#)

[Image](#)



Light Fixture/Fan

Taken on: 2019-01-29 12:34:56

Taken at: [43.56528769, -116.60392308](#)

[Image](#)



Other

Taken on: 2019-01-29 12:35:26

Taken at: [43.56527642, -116.60394616](#)
[Image](#)



Switch/Outlet

Taken on: 2019-01-29 12:36:11


Taken at: [43.56525074, -116.60394768](#)
[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:36:43

Taken at: [43.56525161, -116.60393615](#)
[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:36:51

Taken at: [43.56525328, -116.60393088](#)
[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:37:00

Taken at: [43.56525328, -116.60393088](#)
[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:37:07

Taken at: [43.56525328, -116.60393088](#)
[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:37:14

Taken at: [43.56525328, -116.60393088](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:37:22

Taken at: [43.56525328, -116.60393088](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:37:35

Taken at: [43.56525328, -116.60393088](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:37:55

Taken at: [43.56525328, -116.60393088](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:38:03

Taken at: [43.56525328, -116.60393088](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:38:17

Taken at: [43.56532719, -116.60397355](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:38:24

Taken at: [43.56532719, -116.60397355](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:38:31

Taken at: [43.56531135, -116.6039674](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:38:40

Taken at: [43.56531135, -116.6039674](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:38:48

Taken at: [43.56531719, -116.60395748](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:38:58

Taken at: [43.56531719, -116.60395748](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:39:06

Taken at: [43.56531719, -116.60395748](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:39:16

Taken at: [43.56531789, -116.60396483](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:39:26

Taken at: [43.565243, -116.60390451](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:39:42

Taken at: [43.56528538, -116.60393858](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 12:40:05

Taken at: [43.56526017, -116.60392752](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 12:40:10

Taken at: [43.56526017, -116.60392752](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 12:40:35

Taken at: [43.56524652, -116.60395062](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 12:41:05

Taken at: [43.56525986, -116.60394443](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 12:41:40

Taken at: [43.56525986, -116.60394443](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 12:41:52

Taken at: [43.56525986, -116.60394443](#)

[Image](#)

Bedroom 3: Bedroom 3	CONDITION	ACTION	COMMENTS
Closet/Door/Track/Shelving	- - - D	None	closet door doesn't stay on track
Door/Knob/Lock	- S - -	None	
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- S - -	None	
Other	- S - -	None	
Switch/Outlet	- S - -	None	
Wall/Ceiling	- - - D	None	2 broken outlet covers
Window Covering	- S - -	None	
Window/Lock/Screen	- S - -	None	



Taken on: 2019-01-29 12:42:37
 Taken at: [43.56530807, -116.60397416](#)
[Image](#)



Taken on: 2019-01-29 12:43:50
 Taken at: [43.56533275, -116.60392102](#)
[Image](#)




Closet/Door/Track/Shelving
 Taken on: 2019-01-29 12:44:14
 Taken at: [43.56534254, -116.60394461](#)
[Image](#)



Closet/Door/Track/Shelving
 Taken on: 2019-01-29 12:44:25
 Taken at: [43.56534224, -116.60394244](#)
[Image](#)



Closet/Door/Track/Shelving
 Taken on: 2019-01-29 12:44:53
 Taken at: [43.56534315, -116.60394352](#)
[Image](#)



Closet/Door/Track/Shelving
 Taken on: 2019-01-29 12:45:09
 Taken at: [43.56534524, -116.60394271](#)
[Image](#)



Door/Knob/Lock

Taken on: 2019-01-29 12:45:27

Taken at: [43.56534523, -116.6039408](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 12:45:41

Taken at: [43.56534523, -116.6039408](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 12:45:57

Taken at: [43.56534523, -116.6039408](#)

[Image](#)



Light Fixture/Fan

Taken on: 2019-01-29 12:46:20

Taken at: [43.56534848, -116.60392379](#)

[Image](#)



Switch/Outlet

Taken on: 2019-01-29 12:46:35

Taken at: [43.56534751, -116.60392315](#)

[Image](#)



Switch/Outlet

Taken on: 2019-01-29 12:46:50

Taken at: [43.56534982, -116.60392296](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:47:28

Taken at: [43.56534975, -116.60393091](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:47:41

Taken at: [43.5653426, -116.60394302](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:47:58

Taken at: [43.56534297, -116.60394446](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:47:56

Taken at: [43.56534291, -116.60394312](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:48:03

Taken at: [43.56534291, -116.60394312](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:48:10

Taken at: [43.56534413, -116.60394235](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:48:17

Taken at: [43.56534518, -116.6039426](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:48:29

Taken at: [43.56534591, -116.60394262](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:48:42

Taken at: [43.56534591, -116.60394262](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:48:49

Taken at: [43.56534591, -116.60394262](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:49:03

Taken at: [43.56534591, -116.60394262](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:49:15

Taken at: [43.56534591, -116.60394262](#)

[Image](#)




Wall/Ceiling

Taken on: 2019-01-29 12:49:22

Taken at: [43.56534591](#), [-116.60394262](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:49:29

Taken at: [43.56534591](#), [-116.60394262](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:49:39

Taken at: [43.56534764](#), [-116.60393551](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 12:49:58

Taken at: [43.56534157](#), [-116.60390219](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 12:50:26

Taken at: [43.56534157](#), [-116.60390219](#)

[Image](#)

Closet/Door/Track/Shelving	- S - -	None	
Door/Knob/Lock	- - D	None	locking door knob - missing key
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- S - -	None	
Other	- S - -	None	
Switch/Outlet	- S - -	None	
Wall/Ceiling	- - D	None	holes have been patched
Window Covering	- S - -	None	mismatched blind wand
Window/Lock/Screen	- S - -	None	



Taken on: 2019-01-29 12:52:24
Taken at: [43.56534842, -116.60388482](#)
[Image](#)



Closet/Door/Track/Shelving
Taken on: 2019-01-29 12:53:07
Taken at: [43.56534217, -116.60387407](#)
[Image](#)



Door/Knob/Lock
Taken on: 2019-01-29 12:53:20
Taken at: [43.56532844, -116.60383927](#)
[Image](#)



Door/Knob/Lock
Taken on: 2019-01-29 12:53:27
Taken at: [43.56529047, -116.60384398](#)
[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 12:53:56

Taken at: [43.56528614, -116.6038031](#)

[Image](#)



Light Fixture/Fan

Taken on: 2019-01-29 12:54:05

Taken at: [43.56537557, -116.60385027](#)

[Image](#)




Wall/Ceiling

Taken on: 2019-01-29 12:54:45

Taken at: [43.5653798, -116.60389636](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:54:55

Taken at: [43.56536906, -116.60389597](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:55:02

Taken at: [43.56535414, -116.6039083](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:55:09

Taken at: [43.56535414, -116.6039083](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:55:19

Taken at: [43.56535414, -116.6039083](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:55:27

Taken at: [43.56535414, -116.6039083](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:55:32

Taken at: [43.56535414, -116.6039083](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 12:55:49

Taken at: [43.56534969, -116.60390784](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 12:55:55

Taken at: [43.56534969, -116.60390784](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 12:56:49

Taken at: [43.56534941, -116.60390584](#)

[Image](#)

Dining Room: Dining

CONDITION

ACTION

COMMENTS

Flooring/Baseboard	- - - D	None	vent cover rusted
Light Fixture/Fan	- S - -	None	
Other	- S - -	None	
Smoke/CO Detector	- S - -	None	
Switch/Outlet	- S - -	None	
Wall/Ceiling	- S - -	None	
Window Covering	- - - D	None	Blinding glass door blinds are hard to open, wand is bent, dirty, and missing 2 slats
Window/Lock/Screen	- - - D	None	screen door is leaning against the house, screen is damaged




Taken on: 2019-01-29 12:57:17
Taken at: [43.5653511, -116.60389288](#)
[Image](#)



Flooring/Baseboard
Taken on: 2019-01-29 12:57:31
Taken at: [43.5653511, -116.60389288](#)
[Image](#)



Light Fixture/Fan
Taken on: 2019-01-29 12:58:36
Taken at: [43.56527021, -116.60379613](#)
[Image](#)



Smoke/CO Detector
Taken on: 2019-01-29 12:58:59
Taken at: [43.56526951, -116.60379599](#)
[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:59:31

Taken at: [43.56527068, -116.60381902](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:59:36

Taken at: [43.56527068, -116.60381902](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:59:46

Taken at: [43.5652738, -116.6038132](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 12:59:51

Taken at: [43.5652738, -116.6038132](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:00:04

Taken at: [43.56526413, -116.60381208](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:00:13

Taken at: [43.56526343, -116.60381268](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:00:42

Taken at: [43.56526454, -116.60381162](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:00:49

Taken at: [43.56526454, -116.60381162](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:00:57

Taken at: [43.56526454, -116.60381162](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:01:05

Taken at: [43.5652658, -116.60381072](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 13:01:30

Taken at: [43.5652627, -116.60381286](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 13:01:49

Taken at: [43.56526128, -116.6038087](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 13:02:10

Taken at: [43.56523002, -116.60385992](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 13:02:17

Taken at: [43.56523002, -116.60385992](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 13:02:24

Taken at: [43.56523002, -116.60385992](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 13:02:56

Taken at: [43.56527013, -116.60381895](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 13:03:50

Taken at: [43.56525953, -116.6038153](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 13:04:11

Taken at: [43.56524689, -116.60383718](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 13:04:22

Taken at: [43.56524801, -116.60383775](#)
[Image](#)

Family Room: Family	CONDITION	ACTION	COMMENTS
Door/Knob/Lock	- S - -	None	
Flooring/Baseboard	- - - D	None	tiles are chipped and broken
Light Fixture	- - - D	None	light bulb above fireplace is burnt out
Other	- S - -	None	
Switch/Outlet	- S - -	None	
Wall/Ceiling	- S - -	None	
Window Covering	- - - D	None	Valance missing
Window/Lock/Screen	- S - -	None	tape on screen (no damage noted)



Taken on: 2019-01-29 13:05:58

Taken at: [43.56527243, -116.60386847](#)
[Image](#)



Taken on: 2019-01-29 13:06:05

Taken at: [43.56527243, -116.60386847](#)
[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 13:06:21

Taken at: [43.56526697, -116.60386481](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 13:06:30

Taken at: [43.56529517, -116.6038513](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 13:06:40

Taken at: [43.56529517, -116.6038513](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 13:06:48

Taken at: [43.56529517, -116.6038513](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 13:06:56

Taken at: [43.56529517, -116.6038513](#)

[Image](#)



Light Fixture

Taken on: 2019-01-29 13:07:44

Taken at: [43.56527238, -116.60382151](#)

[Image](#)




Wall/Ceiling

Taken on: 2019-01-29 13:08:37

Taken at: [43.5652511, -116.60383636](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:08:42

Taken at: [43.5652511, -116.60383636](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:08:50

Taken at: [43.5652511, -116.60383636](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:08:59

Taken at: [43.56525311, -116.60383896](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:09:05

Taken at: [43.56525311, -116.60383896](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:09:17

Taken at: [43.56525311, -116.60383896](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:09:27

Taken at: [43.56525311, -116.60383896](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:09:34

Taken at: [43.56525311, -116.60383896](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:09:42

Taken at: [43.56526178, -116.6038479](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:09:57

Taken at: [43.56526178, -116.6038479](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:10:04

Taken at: [43.56526178, -116.6038479](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:10:12

Taken at: [43.56526475, -116.60384746](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:10:19

Taken at: [43.56526765, -116.60385174](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:10:25

Taken at: [43.5652689, -116.60384589](#)

[Image](#)




Wall/Ceiling

Taken on: 2019-01-29 13:10:41

Taken at: [43.56527352, -116.60384724](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:10:47

Taken at: [43.56527568, -116.60385055](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:10:53

Taken at: [43.56527568, -116.60385055](#)

[Image](#)




Window Covering

Taken on: 2019-01-29 13:11:13

Taken at: [43.56527568, -116.60385055](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 13:11:20

Taken at: [43.56527568, -116.60385055](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 13:11:44

Taken at: [43.56527205, -116.60384729](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 13:11:59

Taken at: [43.56527887, -116.60386352](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 13:12:19

Taken at: [43.56527887, -116.60386352](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 13:12:36

Taken at: [43.56527887, -116.60386352](#)

[Image](#)

Hallway/Stairs: Hall/Stairs

CONDITION

ACTION

COMMENTS

Closet/Cabinet	- S - -	None	
Flooring/Baseboard	- S - -	None	
Light Fixture	- S - -	None	
Other	- - - D	None	Return vents are dirty
Railing/Banister	- S - -	None	
Smoke/CO Detector	- S - -	None	
Switch/Outlet	- S - -	None	
Wall/Ceiling	- - - D	None	patched but not painted



Taken on: 2019-01-29 13:13:13
Taken at: [43.56528029, -116.60386631](#)
[Image](#)



Closet/Cabinet
 Taken on: 2019-01-29 13:13:41
Taken at: [43.56529137, -116.60389785](#)
[Image](#)



Light Fixture
 Taken on: 2019-01-29 13:13:57
Taken at: [43.56526695, -116.60398646](#)
[Image](#)



Smoke/CO Detector
 Taken on: 2019-01-29 13:14:08
Taken at: [43.56529839, -116.60395282](#)
[Image](#)



Switch/Outlet

Taken on: 2019-01-29 13:14:49

Taken at: [43.56530408, -116.60394078](#)

[Image](#)



Switch/Outlet

Taken on: 2019-01-29 13:14:59

Taken at: [43.56530612, -116.60390142](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:15:06

Taken at: [43.56517426, -116.60386627](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:15:19

Taken at: [43.56527059, -116.60387036](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:15:28

Taken at: [43.56527059, -116.60387036](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:15:34

Taken at: [43.56527059, -116.60387036](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:15:44

Taken at: [43.56527059, -116.60387036](#)

[Image](#)



Other

Taken on: 2019-01-29 13:16:04

Taken at: [43.56529474, -116.60384025](#)

[Image](#)



Other

Taken on: 2019-01-29 13:16:12

Taken at: [43.56529131, -116.6038335](#)

[Image](#)

Kitchen: Kitchen	CONDITION	ACTION	COMMENTS
Cabinets/Drawers	- - - D	None	dirty
Counter	- S - -	None	Small stain on counter top by fridge
Dishwasher	- - - D	None	dirty, below dishwasher the kick plate is missing
Faucet/Plumbing	- S - -	None	
Flooring/Baseboard	- - - D	None	tile is chipped and broken, dirty
Light Fixture	- S - -	None	
Microwave	- - - D	None	dirty
Other	- S - -	None	
Oven	- S - -	None	
Oven/Microwave	- S - -	None	
Range/Fan/Hood/Filter	- S - -	None	
Refrigerator	- - - D	None	Fridge is in the garage, missing shelf and door bin
Sink/Disposal	- S - -	None	

Switch/Outlet - - - D
 Trash Compactor - S - -
 Wall/Ceiling - S - -
 Window Covering - S - -
 Window/Lock/Screen - S - -

None
 None
 None
 None
 None
 1 broken cover



Taken on: 2019-01-29 13:38:15
 Taken at: [43.56527505, -116.60378267](#)
[Image](#)



Taken on: 2019-01-29 13:38:45
 Taken at: [43.56527505, -116.60378267](#)
[Image](#)



Cabinets/Drawers
 Taken on: 2019-01-29 13:39:00
 Taken at: [43.56524173, -116.60380667](#)
[Image](#)



Cabinets/Drawers
 Taken on: 2019-01-29 13:39:09
 Taken at: [43.56524485, -116.60381297](#)
[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:39:18

Taken at: [43.56524457, -116.60381215](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:39:39

Taken at: [43.56524608, -116.60381103](#)

[Image](#)




Cabinets/Drawers

Taken on: 2019-01-29 13:40:04

Taken at: [43.56526431, -116.60380836](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:40:19

Taken at: [43.56528696, -116.6037983](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:40:34

Taken at: [43.56528541, -116.60380071](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:40:42

Taken at: [43.56528541, -116.60380071](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:40:59

Taken at: [43.56528541, -116.60380071](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:41:08

Taken at: [43.56528541, -116.60380071](#)

[Image](#)




Cabinets/Drawers

Taken on: 2019-01-29 13:41:24

Taken at: [43.56528541, -116.60380071](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:41:33

Taken at: [43.56528541, -116.60380071](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:41:41

Taken at: [43.56528541, -116.60380071](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:42:07

Taken at: [43.5652855, -116.60380212](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:42:18

Taken at: [43.56528544, -116.60380329](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:42:24

Taken at: [43.56528544, -116.60380329](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:42:41

Taken at: [43.56528544, -116.60380329](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:42:58

Taken at: [43.56528224, -116.60380391](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:43:12

Taken at: [43.56528585, -116.6038068](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:43:28

Taken at: [43.56526227, -116.60381323](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:43:46

Taken at: [43.56525772, -116.60378466](#)

[Image](#)



Faucet/Plumbing

Taken on: 2019-01-29 13:44:12

Taken at: [43.56522119, -116.60378134](#)

[Image](#)



Faucet/Plumbing

Taken on: 2019-01-29 13:44:21

Taken at: [43.56521851, -116.60377925](#)

[Image](#)



Faucet/Plumbing

Taken on: 2019-01-29 13:44:29

Taken at: [43.56521201, -116.60377828](#)

[Image](#)



Faucet/Plumbing

Taken on: 2019-01-29 13:44:51

Taken at: [43.56520986, -116.60378088](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:45:03

Taken at: [43.56520986, -116.60378088](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:45:09

Taken at: [43.56520986, -116.60378088](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:45:35

Taken at: [43.56520986, -116.60378088](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:45:43

Taken at: [43.56520986, -116.60378088](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:45:50

Taken at: [43.56521141, -116.60377631](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:45:57

Taken at: [43.56521141, -116.60377631](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:46:07

Taken at: [43.56521141, -116.60377631](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:46:19

Taken at: [43.56521161, -116.60377733](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:46:24

Taken at: [43.56521161, -116.60377733](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:46:38

Taken at: [43.56521848, -116.60378468](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:46:49

Taken at: [43.56521791, -116.60378409](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:47:06

Taken at: [43.56521951, -116.6037867](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:47:15

Taken at: [43.56522863, -116.60375189](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:47:21

Taken at: [43.56522863, -116.60375189](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:47:33

Taken at: [43.56519999, -116.60370947](#)

[Image](#)



Counter

Taken on: 2019-01-29 13:47:45

Taken at: [43.56524096, -116.60387798](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:47:52

Taken at: [43.56524186, -116.60388099](#)

[Image](#)



Counter

Taken on: 2019-01-29 13:48:03

Taken at: [43.56524738, -116.60386657](#)

[Image](#)



Counter

Taken on: 2019-01-29 13:48:08

Taken at: [43.56524676, -116.60385838](#)

[Image](#)



Counter

Taken on: 2019-01-29 13:48:15

Taken at: [43.56524723, -116.60386036](#)

[Image](#)



Counter

Taken on: 2019-01-29 13:48:21

Taken at: [43.56524723, -116.60386036](#)

[Image](#)



Counter

Taken on: 2019-01-29 13:48:36

Taken at: [43.5652562, -116.6038358](#)

[Image](#)



Dishwasher

Taken on: 2019-01-29 13:49:00

Taken at: [43.56525955, -116.6038039](#)

[Image](#)



Dishwasher

Taken on: 2019-01-29 13:49:07

Taken at: [43.56527439, -116.60381596](#)

[Image](#)



Dishwasher

Taken on: 2019-01-29 13:49:45

Taken at: [43.56527485, -116.60381258](#)

[Image](#)



Dishwasher

Taken on: 2019-01-29 13:50:02

Taken at: [43.56526506, -116.60378156](#)

[Image](#)



Dishwasher

Taken on: 2019-01-29 13:50:17

Taken at: [43.56526506, -116.60378156](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 13:51:04

Taken at: [43.56526282, -116.60378397](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 13:51:31

Taken at: [43.56526544, -116.60378683](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 13:51:37

Taken at: [43.56527263, -116.60378033](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 13:51:45

Taken at: [43.56527313, -116.60378001](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 13:51:52

Taken at: [43.56527488, -116.60378404](#)

[Image](#)



Light Fixture

Taken on: 2019-01-29 13:52:35

Taken at: [43.56525044, -116.60377725](#)

[Image](#)



Microwave

Taken on: 2019-01-29 13:52:53

Taken at: [43.5652513, -116.60378034](#)

[Image](#)



Microwave

Taken on: 2019-01-29 13:53:07

Taken at: [43.5652513, -116.60378034](#)

[Image](#)



Microwave

Taken on: 2019-01-29 13:53:13

Taken at: [43.5652513, -116.60378034](#)

[Image](#)



Microwave

Taken on: 2019-01-29 13:53:34

Taken at: [43.5652513, -116.60378034](#)

[Image](#)



Microwave

Taken on: 2019-01-29 13:53:49

Taken at: [43.5652513, -116.60378034](#)

[Image](#)



Microwave

Taken on: 2019-01-29 13:54:23

Taken at: [43.56535332, -116.60374386](#)

[Image](#)



Oven

Taken on: 2019-01-29 13:54:42

Taken at: [43.56530219, -116.60376087](#)

[Image](#)



Oven

Taken on: 2019-01-29 13:54:52

Taken at: [43.56528656, -116.60378036](#)

[Image](#)



Oven

Taken on: 2019-01-29 13:55:00

Taken at: [43.56528226, -116.60378208](#)

[Image](#)



Oven

Taken on: 2019-01-29 13:55:20

Taken at: [43.56527929, -116.60378191](#)

[Image](#)



Oven

Taken on: 2019-01-29 13:55:32

Taken at: [43.56527843, -116.60378082](#)

[Image](#)



Oven

Taken on: 2019-01-29 13:55:39

Taken at: [43.56527775, -116.60377916](#)

[Image](#)



Oven

Taken on: 2019-01-29 13:55:47

Taken at: [43.56527924, -116.60377834](#)

[Image](#)



Oven

Taken on: 2019-01-29 13:55:53

Taken at: [43.56527924, -116.60377834](#)

[Image](#)



Oven

Taken on: 2019-01-29 13:56:04

Taken at: [43.56527924, -116.60377834](#)

[Image](#)



Oven

Taken on: 2019-01-29 13:56:11

Taken at: [43.56528006, -116.6037798](#)

[Image](#)



Refrigerator

Taken on: 2019-01-29 13:57:08

Taken at: [43.5651936, -116.6037841](#)

[Image](#)



Refrigerator

Taken on: 2019-01-29 13:57:23

Taken at: [43.56526788, -116.60376963](#)

[Image](#)



Refrigerator

Taken on: 2019-01-29 13:57:36

Taken at: [43.56533411, -116.60377289](#)

[Image](#)



Refrigerator

Taken on: 2019-01-29 13:57:46

Taken at: [43.56533904, -116.60375987](#)

[Image](#)



Switch/Outlet

Taken on: 2019-01-29 13:58:23

Taken at: [43.56531911, -116.60374873](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-29 13:58:59

Taken at: [43.56531175, -116.60377397](#)

[Image](#)

Laundry Room: Laundry Room

CONDITION


ACTION

COMMENTS

Cabinet/Counter/Shelving	- - - D	None	door stop is bent and cap is missing
Door/Knob/Lock	- S - -	None	
Dryer	- - - D	None	lint and debris in dryer vent
Faucet/Valve	- S - -	None	
Flooring/Baseboard	- - - D	None	rusted vent cover
Light Fixture/Fan	- S - -	None	
Other	- S - -	None	
Plumbing/Drain	- S - -	None	
Switch/Outlet	- S - -	None	
Wall/Ceiling	- - - D	None	coat rack on wall
Washer	- S - -	None	
Window Covering	- S - -	None	
Window/Lock/Screen	- S - -	None	



Taken on: 2019-01-29 13:17:14
Taken at: [43.56530942, -116.60388377](#)
[Image](#)



Taken on: 2019-01-29 13:17:19
Taken at: [43.56530942, -116.60388377](#)
[Image](#)




Cabinet/Counter/Shelving
Taken on: 2019-01-29 13:17:30
Taken at: [43.56530942, -116.60388377](#)
[Image](#)



Cabinet/Counter/Shelving
Taken on: 2019-01-29 13:17:42
Taken at: [43.56540768, -116.60384881](#)
[Image](#)




Cabinet/Counter/Shelving
 Taken on: 2019-01-29 13:18:45
 Taken at: [43.56540768, -116.60384881](#)
[Image](#)



Door/Knob/Lock
 Taken on: 2019-01-29 13:19:14
 Taken at: [43.56540768, -116.60384881](#)
[Image](#)



Door/Knob/Lock
 Taken on: 2019-01-29 13:19:21
 Taken at: [43.56540768, -116.60384881](#)
[Image](#)



Dryer
 Taken on: 2019-01-29 13:19:31
 Taken at: [43.56532234, -116.60383072](#)
[Image](#)



Dryer
 Taken on: 2019-01-29 13:19:57
 Taken at: [43.56530919, -116.60380408](#)
[Image](#)



Faucet/Valve
 Taken on: 2019-01-29 13:20:30
 Taken at: [43.56532456, -116.60378885](#)
[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 13:20:43

Taken at: [43.56533813, -116.60378314](#)

[Image](#)



Cabinet/Counter/Shelving

Taken on: 2019-01-29 13:20:53

Taken at: [43.56532969, -116.60379275](#)

[Image](#)



Cabinet/Counter/Shelving

Taken on: 2019-01-29 13:20:59

Taken at: [43.56532973, -116.60379356](#)

[Image](#)



Light Fixture/Fan

Taken on: 2019-01-29 13:21:33

Taken at: [43.56533064, -116.60379288](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:21:48

Taken at: [43.56533275, -116.60379165](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:22:19

Taken at: [43.56532715, -116.60379953](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:22:24

Taken at: [43.56532776, -116.60380025](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:22:29

Taken at: [43.56532776, -116.60380025](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:22:37

Taken at: [43.56532788, -116.60380082](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:22:44

Taken at: [43.56532788, -116.60380082](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-29 13:22:51

Taken at: [43.56532802, -116.60380152](#)

[Image](#)


Living Room: Living Room

CONDITION

ACTION

COMMENTS

Door/Knob/Lock	- - - D	None	Slider door between dining room and bonus room is split on one panel and slider guides are broken
Fireplace Equipment	- S - -	None	
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- S - -	None	
Other	- S - -	None	
Switch/Outlet	- S - -	None	
Wall/Ceiling	- - - D	None	walls have been patched and stickers on ceiling
Window Covering	- - - D	None	caps are missing on all blinds, one blind has a damaged slat
Window/Lock/Screen	- - - D	None	Window lock is damaged



Taken on: 2019-01-29 13:23:39
Taken at: [43.56532426, -116.60380156](#)
[Image](#)



Taken on: 2019-01-29 13:25:07
Taken at: [43.56523798, -116.60384413](#)
[Image](#)



Door/Knob/Lock
Taken on: 2019-01-29 13:25:21
Taken at: [43.56527218, -116.60371061](#)
[Image](#)



Flooring/Baseboard
Taken on: 2019-01-29 13:26:15
Taken at: [43.56526833, -116.60381408](#)
[Image](#)



Light Fixture/Fan

Taken on: 2019-01-29 13:26:27

Taken at: [43.56525032, -116.60387639](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:26:53

Taken at: [43.56523982, -116.60376538](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:27:00

Taken at: [43.56522659, -116.60375145](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:27:05

Taken at: [43.56522659, -116.60375145](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:27:13

Taken at: [43.56522995, -116.60375236](#)

[Image](#)




Wall/Ceiling

Taken on: 2019-01-29 13:27:20

Taken at: [43.56522995, -116.60375236](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:27:28

Taken at: [43.56523365, -116.6037486](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:27:37

Taken at: [43.5652379, -116.60375084](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:27:43

Taken at: [43.5652379, -116.60375084](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:27:53

Taken at: [43.5652376, -116.60374979](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-29 13:28:11

Taken at: [43.56523738, -116.60375243](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 13:28:56

Taken at: [43.56519788, -116.60379395](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 13:29:04

Taken at: [43.56519788, -116.60379395](#)

[Image](#)



Window Covering

Taken on: 2019-01-29 13:29:34

Taken at: [43.56520346, -116.60380315](#)

[Image](#)




Window/Lock/Screen

Taken on: 2019-01-29 13:30:14

Taken at: [43.56523847, -116.60379727](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 13:30:24

Taken at: [43.56524379, -116.60380266](#)

[Image](#)

Office: Office	CONDITION	ACTION	COMMENTS
Closet/Door/Track/Shelving	- S - -	None	
Door/Knob/Lock	- S - -	None	
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- S - -	None	
Other	- S - -	None	
Switch/Outlet	- S - -	None	
Wall/Ceiling	- S - -	None	
Window Covering	- S - -	None	
Window/Lock/Screen	- S - -	None	
Back Yard/Exterior: Back Yard	CONDITION	ACTION	COMMENTS
Building Exterior	- S - -	None	
Fence/Gate	- S - -	None	

Landscaping	- S - -	None	
Light Fixture	- S - -	None	
Other	- - - D	None	Dog feces and holes throughout back yard
Patio Cover	- S - -	None	Wind chimes
Patio/Deck/Balcony	- S - -	None	
Pool/Heater/Equipment	- S - -	None	
Porch/Stairs	- S - -	None	
Spa/Cover/Equipment	- S - -	None	
Sprinkler/Timer	- S - -	None	
Walkway	- S - -	None	



Taken on: 2019-01-29 13:59:30
Taken at: [43.56525654, -116.60381221](#)
[Image](#)



Taken on: 2019-01-29 13:59:36
Taken at: [43.56521141, -116.6038782](#)
[Image](#)



Taken on: 2019-01-29 13:59:43
Taken at: [43.56521141, -116.6038782](#)
[Image](#)



Building Exterior
Taken on: 2019-01-29 14:00:06
Taken at: [43.56513629, -116.60381349](#)
[Image](#)



Building Exterior

Taken on: 2019-01-29 14:00:11

Taken at: [43.56513629, -116.60381349](#)

[Image](#)



Fence/Gate

Taken on: 2019-01-29 14:00:37

Taken at: [43.56516124, -116.60384193](#)

[Image](#)



Fence/Gate

Taken on: 2019-01-29 14:00:50

Taken at: [43.56521029, -116.60386893](#)

[Image](#)



Fence/Gate

Taken on: 2019-01-29 14:00:57

Taken at: [43.56519814, -116.60385933](#)

[Image](#)



Fence/Gate

Taken on: 2019-01-29 14:01:01

Taken at: [43.56518655, -116.60382793](#)

[Image](#)



Fence/Gate

Taken on: 2019-01-29 14:01:06

Taken at: [43.56518655, -116.60382793](#)

[Image](#)




Fence/Gate

Taken on: 2019-01-29 14:01:11

Taken at: [43.56518655, -116.60382793](#)

[Image](#)



Fence/Gate

Taken on: 2019-01-29 14:01:19

Taken at: [43.56517041, -116.60382062](#)

[Image](#)



Landscaping

Taken on: 2019-01-29 14:01:32

Taken at: [43.56519668, -116.60382763](#)

[Image](#)



Landscaping

Taken on: 2019-01-29 14:01:47

Taken at: [43.56527234, -116.60386605](#)

[Image](#)



Landscaping

Taken on: 2019-01-29 14:01:54

Taken at: [43.56527234, -116.60386605](#)

[Image](#)



Landscaping

Taken on: 2019-01-29 14:02:00

Taken at: [43.56523129, -116.60387324](#)

[Image](#)



Landscaping

Taken on: 2019-01-29 14:02:21

Taken at: [43.56523129, -116.60387324](#)

[Image](#)



Landscaping

Taken on: 2019-01-29 14:02:30

Taken at: [43.56523129, -116.60387324](#)

[Image](#)



Landscaping

Taken on: 2019-01-29 14:02:38

Taken at: [43.56521538, -116.60386557](#)

[Image](#)



Light Fixture

Taken on: 2019-01-29 14:02:55

Taken at: [43.56516907, -116.60378421](#)

[Image](#)



Patio Cover

Taken on: 2019-01-29 14:03:07

Taken at: [43.5651986, -116.60392099](#)

[Image](#)



Patio/Deck/Balcony

Taken on: 2019-01-29 14:03:17

Taken at: [43.5652312, -116.60390665](#)

[Image](#)

Side Yard/Exterior: Side Yard

CONDITION

ACTION

COMMENTS

Building Exterior	- S - -	None	
Fence/Gate	- - - D	None	hole in vinyl fence
Landscaping	- S - -	None	weeds on side yard, and trash and debris on left side of house
Light Fixture	- S - -	None	
Other	- - - D	None	Dog feces and holes throughout side yard
Patio Cover	- S - -	None	
Patio/Deck/Balcony	- S - -	None	
Pool/Heater/Equipment	- S - -	None	
Porch/Stairs	- S - -	None	
Spa/Cover/Equipment	- S - -	None	
Sprinkler/Timer	- S - -	None	
Walkway	- S - -	None	



Taken on: 2019-01-29 14:03:56
Taken at: [43.56522839, -116.60395973](#)
[Image](#)



Fence/Gate
 Taken on: 2019-01-29 14:04:10
Taken at: [43.56540357, -116.60399391](#)
[Image](#)



Building Exterior
 Taken on: 2019-01-29 14:04:39
Taken at: [43.56532391, -116.60392174](#)
[Image](#)



Landscaping
 Taken on: 2019-01-29 14:04:48
Taken at: [43.56532466, -116.60397545](#)
[Image](#)



Light Fixture

Taken on: 2019-01-29 14:05:20

Taken at: [43.56523541, -116.60373286](#)

[Image](#)



Patio/Deck/Balcony

Taken on: 2019-01-29 14:05:27

Taken at: [43.56527315, -116.60370059](#)

[Image](#)




Other

Taken on: 2019-01-29 14:05:48

Taken at: [43.56524445, -116.60362407](#)

[Image](#)



Other

Taken on: 2019-01-29 14:05:53

Taken at: [43.56524445, -116.60362407](#)

[Image](#)

Fireplace/Chimney: Fireplace	CONDITION	ACTION	COMMENTS
Other	- - - D	None	unknown substance on glass and screen



Taken on: 2019-01-29 13:31:20
 Taken at: [43.56529085, -116.60384239](#)
[Image](#)



Other
 Taken on: 2019-01-29 13:31:30
 Taken at: [43.56528857, -116.60384607](#)
[Image](#)

Garage/Parking: Garage	CONDITION	ACTION	COMMENTS
Cabinet/Counter	- S - -	None	
Driveway/Floor	- S - -	None	
Electrical/Exposed Wiring	- S - -	None	
Garage Door	- S - -	None	
Light Fixture	- S - -	None	
Other	- S - -	None	
Other Door/Knob/Lock	- S - -	None	
Other Storage/Shelving	- S - -	None	
Switch/Outlet	- S - -	None	
Window/Lock/Screen	- - - D	None	valance missing on blinds



Taken on: 2019-01-29 13:32:01
 Taken at: [43.56529281, -116.60384959](#)
[Image](#)



Cabinet/Counter
 Taken on: 2019-01-29 13:32:12
 Taken at: [43.56529281, -116.60384959](#)
[Image](#)



Driveway/Floor

Taken on: 2019-01-29 13:32:23

Taken at: [43.56529609, -116.60384604](#)

[Image](#)



Driveway/Floor

Taken on: 2019-01-29 13:32:29

Taken at: [43.56529791, -116.60384484](#)

[Image](#)



Driveway/Floor

Taken on: 2019-01-29 13:32:37

Taken at: [43.56529969, -116.60384398](#)

[Image](#)



Driveway/Floor

Taken on: 2019-01-29 13:32:44

Taken at: [43.56530596, -116.60383958](#)

[Image](#)



Driveway/Floor

Taken on: 2019-01-29 13:32:49

Taken at: [43.56530596, -116.60383958](#)

[Image](#)



Driveway/Floor

Taken on: 2019-01-29 13:32:55

Taken at: [43.56530596, -116.60383958](#)

[Image](#)



Garage Door

Taken on: 2019-01-29 13:33:22

Taken at: [43.56530514, -116.60383353](#)

[Image](#)



Light Fixture

Taken on: 2019-01-29 13:33:53

Taken at: [43.56534217, -116.6037834](#)

[Image](#)




Other Door/Knob/Lock

Taken on: 2019-01-29 13:34:09

Taken at: [43.56550509, -116.6037639](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 13:34:19

Taken at: [43.56546311, -116.60383321](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 13:34:34

Taken at: [43.56545153, -116.60383311](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-29 13:34:41

Taken at: [43.56538459, -116.60382962](#)

[Image](#)

Keys/Remotes/Devices:

Keys/Remotes

CONDITION

ACTION

COMMENTS

Keys	- S - -	None	1 key left at property
Other	- S - -	None	
Remotes/Devices	- S - -	None	1 remote



Keys

Taken on: 2019-01-29 13:35:12

Taken at: [43.56528948, -116.60378677](#)
[Image](#)



Remotes/Devices

Taken on: 2019-01-29 13:35:22

Taken at: [43.56528232, -116.60378649](#)
[Image](#)

Additional Comments

Final Comments

Thank you for being our tenant. We will process your security deposit return within 30 days.