

Move Out

TaskMasters, 925 N Main St, Ste A, Meridian, ID, 83642

TASKMASTERS

201 w 1st st

201 w 1st st, Middleton , ID, US

Move Out

2019-01-31

Inspector:

office@taskmastersid.com

Tenant:

CONDITION KEY

N - New

S - Satisfactory

! - Action

D - Damaged

Entry	CONDITION	ACTION	COMMENTS
Door/Knob/Lock	- S - -	None	
Doorbell	- S - -	None	
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- S - -	None	
Other	- S - -	None	
Security/Screen Door	- S - -	None	
Switch/Outlet	- S - -	None	
Wall/Ceiling	- S - -	None	



Taken on: 2019-01-30 10:13:39

Taken at: [43.70719486, -116.62561032](https://www.google.com/maps/place/43.70719486,-116.62561032)
[Image](#)



Door/Knob/Lock

Taken on: 2019-01-30 10:13:49

Taken at: [43.70719551, -116.6256112](https://www.google.com/maps/place/43.70719551,-116.6256112)
[Image](#)



Door/Knob/Lock

Taken on: 2019-01-30 10:13:54

Taken at: [43.7071955, -116.62561121](#)

[Image](#)



Doorbell

Taken on: 2019-01-30 10:14:08

Taken at: [43.70719959, -116.62561226](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 10:14:15

Taken at: [43.70719959, -116.62561226](#)

[Image](#)

Front Yard/Exterior	CONDITION	ACTION	COMMENTS
Building Exterior	- S - -	None	
Fence/Gate	- S - -	None	
Landscaping	- S - -	None	
Light Fixture	- S - -	None	
Mailbox/Keyed Location	- S - -	None	
Other	- S - -	None	
Patio Cover	- S - -	None	
Patio/Deck/Balcony	- S - -	None	
Porch/Stairs	- S - -	None	
Sprinkler/Timer	- S - -	None	
Walk/Driveway	- S - -	None	



Taken on: 2019-01-30 10:15:27
Taken at: [43.70718815, -116.62557684](#)
[Image](#)



Building Exterior
 Taken on: 2019-01-30 10:15:36
Taken at: [43.70728556, -116.62565546](#)
[Image](#)



Fence/Gate
 Taken on: 2019-01-30 10:15:50
Taken at: [43.70725805, -116.62562741](#)
[Image](#)



Landscaping
 Taken on: 2019-01-30 10:16:07
Taken at: [43.70724052, -116.62561547](#)
[Image](#)



Light Fixture
 Taken on: 2019-01-30 10:16:16
Taken at: [43.70724052, -116.62561547](#)
[Image](#)



Mailbox/Keyed Location
 Taken on: 2019-01-30 10:16:39
Taken at: [43.70722359, -116.62563174](#)
[Image](#)



Patio Cover

Taken on: 2019-01-30 10:16:52

Taken at: [43.70733246, -116.62572661](https://www.zillow.com/homedetails/43.70733246,-116.62572661/)

[Image](#)



Patio/Deck/Balcony

Taken on: 2019-01-30 10:17:04

Taken at: [43.70733246, -116.62572661](https://www.zillow.com/homedetails/43.70733246,-116.62572661/)

[Image](#)

Bathroom 1: master bath	CONDITION	ACTION	COMMENTS
Cabinet/Counter/Shelving	- S - -	None	
Door/Knob/Lock	- S - -	None	
Exhaust Fan	- - - D	None	dirty
Flooring/Baseboard	- S - -	None	
Light Fixture	- S - -	None	
Medicine Cabinet/Mirror	- S - -	None	
Other	- S - -	None	
Plumbing/Drain	- S - -	None	
Shower Door/Rail/Curtain	- S - -	None	
Sink/Faucet	- - - D	None	Stopper is damaged
Switch/Outlet	- S - -	None	
Toilet	- S - -	None	
Toilet Paper Holder	- S - -	None	
Towel Rack	- - - D	None	towel bar does not fit in brackets (length or thickness)
Tub/Shower	- - - D	None	tub is dirty and chipped
Wall/Ceiling	- S - -	None	
Window Covering	- S - -	None	
Window/Lock/Screen	- S - -	None	



Taken on: 2019-01-30 10:18:18
Taken at: [43.70717597, -116.62557567](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-30 10:18:29
Taken at: [43.70718751, -116.62555758](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-30 10:18:46
Taken at: [43.70718751, -116.62555758](#)
[Image](#)



Plumbing/Drain
 Taken on: 2019-01-30 10:19:00
Taken at: [43.70723881, -116.62572328](#)
[Image](#)



Door/Knob/Lock
 Taken on: 2019-01-30 10:19:10
Taken at: [43.70719786, -116.62565999](#)
[Image](#)



Door/Knob/Lock
 Taken on: 2019-01-30 10:19:15
Taken at: [43.70719786, -116.62565999](#)
[Image](#)



Exhaust Fan

Taken on: 2019-01-30 10:19:27

Taken at: [43.70719786, -116.62565999](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 10:19:50

Taken at: [43.70719194, -116.6256453](#)

[Image](#)



Light Fixture

Taken on: 2019-01-30 10:20:00

Taken at: [43.70707312, -116.62549058](#)

[Image](#)



Sink/Faucet

Taken on: 2019-01-30 10:20:33

Taken at: [43.70716379, -116.62550268](#)

[Image](#)



Switch/Outlet

Taken on: 2019-01-30 10:20:56

Taken at: [43.70726839, -116.62552613](#)

[Image](#)



Toilet

Taken on: 2019-01-30 10:21:06

Taken at: [43.7072407, -116.62557767](#)

[Image](#)



Toilet Paper Holder

Taken on: 2019-01-30 10:21:14

Taken at: [43.70721524, -116.62557699](#)

[Image](#)



Towel Rack

Taken on: 2019-01-30 10:21:44

Taken at: [43.70720384, -116.62557422](#)

[Image](#)



Towel Rack

Taken on: 2019-01-30 10:22:36

Taken at: [43.70721122, -116.62557959](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-30 10:22:47

Taken at: [43.70722094, -116.62557919](#)

[Image](#)




Tub/Shower

Taken on: 2019-01-30 10:23:03

Taken at: [43.70721953, -116.62557399](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-30 10:23:14

Taken at: [43.70722067, -116.62554619](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-30 10:23:43

Taken at: [43.70723028, -116.62552042](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-30 10:23:49

Taken at: [43.7072683, -116.62555301](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-30 10:24:00

Taken at: [43.7072683, -116.62555301](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-30 10:24:10

Taken at: [43.7072683, -116.62555301](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:24:18

Taken at: [43.7072683, -116.62555301](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:24:27

Taken at: [43.70726806, -116.62555846](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:24:35

Taken at: [43.70725987, -116.62555285](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:25:05

Taken at: [43.70725493, -116.62554907](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-30 10:25:22

Taken at: [43.70720618, -116.62556873](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:25:37

Taken at: [43.70720618, -116.62556873](#)

[Image](#)

Bathroom 2: bathroom 2	CONDITION	ACTION	COMMENTS
Cabinet/Counter/Shelving	- S - -	None	
Door/Knob/Lock	- S - -	None	
Exhaust Fan	- - - D	None	dirty
Flooring/Baseboard	- S - -	None	
Light Fixture	- S - -	None	
Medicine Cabinet/Mirror	- S - -	None	
Other	- S - -	None	
Plumbing/Drain	- S - -	None	
Shower Door/Rail/Curtain	- S - -	None	
Sink/Faucet	- S - -	None	
Switch/Outlet	- S - -	None	
Toilet	- - - D	None	caulking is missing around toilet
Toilet Paper Holder	- S - -	None	
Towel Rack	- - - D	None	towel rack is mismatched
Tub/Shower	- - - D	None	dirty
Wall/Ceiling	- - - D	None	holes in walls
Move Out for 201 w 1st st on 2019-01-31			

Window Covering - S - -
Window/Lock/Screen - S - -

None
None




Taken on: 2019-01-30 10:26:31
Taken at: [43.70718693, -116.62561072](#)
[Image](#)



Cabinet/Counter/Shelving
Taken on: 2019-01-30 10:26:40
Taken at: [43.70715212, -116.62553689](#)
[Image](#)



Cabinet/Counter/Shelving
Taken on: 2019-01-30 10:26:56
Taken at: [43.70706812, -116.62548941](#)
[Image](#)



Door/Knob/Lock
Taken on: 2019-01-30 10:27:09
Taken at: [43.70706812, -116.62548941](#)
[Image](#)



Door/Knob/Lock

Taken on: 2019-01-30 10:27:19

Taken at: [43.70706812, -116.62548941](https://www.google.com/maps/place/43.70706812,-116.62548941)

[Image](#)



Exhaust Fan

Taken on: 2019-01-30 10:27:29

Taken at: [43.70706812, -116.62548941](https://www.google.com/maps/place/43.70706812,-116.62548941)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 10:27:53

Taken at: [43.70710155, -116.62552411](https://www.google.com/maps/place/43.70710155,-116.62552411)

[Image](#)



Light Fixture

Taken on: 2019-01-30 10:28:08

Taken at: [43.70710155, -116.62552411](https://www.google.com/maps/place/43.70710155,-116.62552411)

[Image](#)



Plumbing/Drain

Taken on: 2019-01-30 10:28:22

Taken at: [43.70713727, -116.62557876](https://www.google.com/maps/place/43.70713727,-116.62557876)

[Image](#)



Sink/Faucet

Taken on: 2019-01-30 10:28:31

Taken at: [43.70714123, -116.62558605](https://www.google.com/maps/place/43.70714123,-116.62558605)

[Image](#)



Sink/Faucet

Taken on: 2019-01-30 10:28:46

Taken at: [43.70714683, -116.62558618](#)

[Image](#)



Switch/Outlet

Taken on: 2019-01-30 10:28:55

Taken at: [43.70715466, -116.62558773](#)

[Image](#)



Toilet

Taken on: 2019-01-30 10:29:03

Taken at: [43.70715279, -116.62558435](#)

[Image](#)



Toilet

Taken on: 2019-01-30 10:29:14

Taken at: [43.7071517, -116.6255797](#)

[Image](#)



Toilet Paper Holder

Taken on: 2019-01-30 10:29:31

Taken at: [43.70715586, -116.62557188](#)

[Image](#)



Towel Rack

Taken on: 2019-01-30 10:29:51

Taken at: [43.70716976, -116.62557084](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-30 10:30:01

Taken at: [43.70716976, -116.62557084](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-30 10:30:09

Taken at: [43.7069782, -116.6256216](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-30 10:30:18

Taken at: [43.7069782, -116.6256216](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-30 10:30:25

Taken at: [43.70716976, -116.62557084](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-30 10:30:31

Taken at: [43.70716976, -116.62557084](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-30 10:30:39

Taken at: [43.70719125, -116.62542606](#)

[Image](#)



Tub/Shower

Taken on: 2019-01-30 10:30:53

Taken at: [43.7071503, -116.62545431](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:31:26

Taken at: [43.70715974, -116.6255061](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:31:34

Taken at: [43.70712645, -116.6255027](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-30 10:32:27

Taken at: [43.70715313, -116.62555604](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:32:36

Taken at: [43.70712705, -116.62555979](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:32:42

Taken at: [43.70712705, -116.62555979](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:32:53

Taken at: [43.70718683, -116.62551167](https://www.zillow.com/homedetails/43.70718683,-116.62551167)
[Image](#)

Bedroom 1: master bedroom	CONDITION	ACTION	COMMENTS
Closet/Door/Track/Shelving	- - - D	None	27 nails in wood underneath the top shelf, coat rack in closet, closet door guide broken
Door/Knob/Lock	- S - -	None	
Flooring/Baseboard	- - - D	None	baseboard has missing sections and is dirty
Light Fixture/Fan	- S - -	None	
Other	- S - -	None	
Switch/Outlet	- S - -	None	
Wall/Ceiling	- - - D	None	mismatch paint, patching but not touch up
Window Covering	- - - D	None	string caps on blind are missing
Window/Lock/Screen	- S - -	None	



Taken on: 2019-01-30 10:33:16

Taken at: [43.70717084, -116.6255366](https://www.zillow.com/homedetails/43.70717084,-116.6255366)
[Image](#)



Taken on: 2019-01-30 10:33:31

Taken at: [43.70716843, -116.62559023](https://www.zillow.com/homedetails/43.70716843,-116.62559023)
[Image](#)



Closet/Door/Track/Shelving
 Taken on: 2019-01-30 10:33:46
 Taken at: [43.70717169, -116.62558597](#)
[Image](#)



Closet/Door/Track/Shelving
 Taken on: 2019-01-30 10:34:15
 Taken at: [43.70721527, -116.62556669](#)
[Image](#)



Door/Knob/Lock
 Taken on: 2019-01-30 10:34:25
 Taken at: [43.70723343, -116.62559528](#)
[Image](#)



Door/Knob/Lock
 Taken on: 2019-01-30 10:34:42
 Taken at: [43.70722721, -116.62559094](#)
[Image](#)



Flooring/Baseboard
 Taken on: 2019-01-30 10:34:57
 Taken at: [43.70722721, -116.62559094](#)
[Image](#)



Flooring/Baseboard
 Taken on: 2019-01-30 10:35:28
 Taken at: [43.70722721, -116.62559094](#)
[Image](#)



Light Fixture/Fan

Taken on: 2019-01-30 10:35:45

Taken at: [43.70725584, -116.62555472](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 10:36:16

Taken at: [43.70721109, -116.62555918](#)

[Image](#)




Wall/Ceiling

Taken on: 2019-01-30 10:36:27

Taken at: [43.70721799, -116.62557276](#)

[Image](#)




Wall/Ceiling

Taken on: 2019-01-30 10:36:36

Taken at: [43.70722393, -116.62557685](#)

[Image](#)




Wall/Ceiling

Taken on: 2019-01-30 10:36:50

Taken at: [43.70722393, -116.62557685](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:37:06

Taken at: [43.70722393, -116.62557685](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:37:17

Taken at: [43.70722393, -116.62557685](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:37:23

Taken at: [43.70722393, -116.62557685](#)

[Image](#)




Wall/Ceiling

Taken on: 2019-01-30 10:37:28

Taken at: [43.70722393, -116.62557685](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:37:48

Taken at: [43.70722793, -116.62556608](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:37:57

Taken at: [43.70722555, -116.62556001](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:38:15

Taken at: [43.70718817, -116.62557154](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:38:23

Taken at: [43.70724403, -116.6255305](#)

[Image](#)



Closet/Door/Track/Shelving

Taken on: 2019-01-30 10:38:38

Taken at: [43.70722138, -116.62540912](#)

[Image](#)



Closet/Door/Track/Shelving

Taken on: 2019-01-30 10:38:47

Taken at: [43.70722138, -116.62540912](#)

[Image](#)




Wall/Ceiling

Taken on: 2019-01-30 10:39:59

Taken at: [43.70722122, -116.62553577](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:40:04

Taken at: [43.70722122, -116.62553577](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:40:09

Taken at: [43.70722122, -116.62553577](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:40:18

Taken at: [43.707194, -116.62568153](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:40:28

Taken at: [43.70723257, -116.62559415](#)

[Image](#)




Flooring/Baseboard

Taken on: 2019-01-30 10:41:14

Taken at: [43.70721531, -116.62556187](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 10:41:32

Taken at: [43.70722285, -116.62555835](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 10:41:44

Taken at: [43.7072492, -116.62553149](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-30 10:42:52

Taken at: [43.70719719, -116.62555036](#)

[Image](#)



Window Covering

Taken on: 2019-01-30 10:43:00

Taken at: [43.70719719, -116.62555036](#)

[Image](#)



Window Covering

Taken on: 2019-01-30 10:43:07

Taken at: [43.70719719, -116.62555036](#)

[Image](#)

Bedroom 2: bedroom 2	CONDITION	ACTION	COMMENTS
Closet/Door/Track/Shelving	- S - -	None	
Door/Knob/Lock	- - - D	None	locking door, key not present
Flooring/Baseboard	- - - D	None	chips in baseboard, carpet is stained
Light Fixture/Fan	- - - D	None	fan blade upside down
Other	- S - -	None	
Switch/Outlet	- S - -	None	
Wall/Ceiling	- S - -	None	
Window Covering	- - - D	None	blinds are dirty, and missing string caps
Window/Lock/Screen	- - - D	None	bent screen



Taken on: 2019-01-30 10:44:07

Taken at: [43.70720722, -116.62555064](#)

[Image](#)



Closet/Door/Track/Shelving

Taken on: 2019-01-30 10:44:23

Taken at: [43.70716261, -116.62555356](#)

[Image](#)




Closet/Door/Track/Shelving
 Taken on: 2019-01-30 10:44:31
 Taken at: [43.70716177, -116.62555097](#)
[Image](#)



Closet/Door/Track/Shelving
 Taken on: 2019-01-30 10:44:36
 Taken at: [43.70715948, -116.62555005](#)
[Image](#)




Closet/Door/Track/Shelving
 Taken on: 2019-01-30 10:45:01
 Taken at: [43.70715992, -116.62555051](#)
[Image](#)



Closet/Door/Track/Shelving
 Taken on: 2019-01-30 10:45:07
 Taken at: [43.70715992, -116.62555051](#)
[Image](#)



Closet/Door/Track/Shelving
 Taken on: 2019-01-30 10:45:19
 Taken at: [43.70715957, -116.62555176](#)
[Image](#)



Door/Knob/Lock
 Taken on: 2019-01-30 10:45:58
 Taken at: [43.70715838, -116.62558043](#)
[Image](#)




Door/Knob/Lock

Taken on: 2019-01-30 10:46:06

Taken at: [43.70715838, -116.62558043](#)

[Image](#)



Door/Knob/Lock

Taken on: 2019-01-30 10:46:13

Taken at: [43.70715838, -116.62558043](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 10:46:32

Taken at: [43.70716092, -116.6254652](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 10:46:39

Taken at: [43.70709562, -116.62553629](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 10:46:53

Taken at: [43.70709562, -116.62553629](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 10:47:11

Taken at: [43.7071097, -116.62553031](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 10:47:19

Taken at: [43.7071097, -116.62553031](#)

[Image](#)



Light Fixture/Fan

Taken on: 2019-01-30 10:47:35

Taken at: [43.70711259, -116.62552959](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:48:22

Taken at: [43.70711102, -116.62554235](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:48:28

Taken at: [43.70711102, -116.62554235](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:48:39

Taken at: [43.70711666, -116.6255352](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:48:45

Taken at: [43.70711666, -116.6255352](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:48:54

Taken at: [43.70711666, -116.6255352](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:49:01

Taken at: [43.70711666, -116.6255352](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:49:10

Taken at: [43.70711666, -116.6255352](#)

[Image](#)



Light Fixture/Fan

Taken on: 2019-01-30 10:50:06

Taken at: [43.70715422, -116.62553619](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:50:15

Taken at: [43.7071686, -116.6255656](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:50:24

Taken at: [43.70716647, -116.62556341](#)

[Image](#)




Wall/Ceiling

Taken on: 2019-01-30 10:50:29

Taken at: [43.70716647, -116.62556341](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:50:36

Taken at: [43.70716647, -116.62556341](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:50:45

Taken at: [43.70716647, -116.62556341](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:50:53

Taken at: [43.70716647, -116.62556341](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:51:03

Taken at: [43.7069491, -116.625617](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:51:13

Taken at: [43.70716611, -116.62555708](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:51:23

Taken at: [43.70716697, -116.62555315](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:51:31

Taken at: [43.70716697, -116.62555315](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 10:51:55

Taken at: [43.70716697, -116.62555315](#)

[Image](#)



Window Covering

Taken on: 2019-01-30 10:52:02

Taken at: [43.70716232, -116.62555575](#)

[Image](#)



Window Covering

Taken on: 2019-01-30 10:52:31

Taken at: [43.70717185, -116.62557372](#)

[Image](#)



Window Covering

Taken on: 2019-01-30 10:52:47

Taken at: [43.70717535, -116.62558737](#)

[Image](#)



Window Covering

Taken on: 2019-01-30 10:52:58

Taken at: [43.70716877, -116.62555605](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-30 10:53:27

Taken at: [43.70716425, -116.62555596](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-30 10:53:43

Taken at: [43.70716327, -116.62555451](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 10:54:36

Taken at: [43.70715878, -116.62555834](#)

[Image](#)




Flooring/Baseboard

Taken on: 2019-01-30 10:54:44

Taken at: [43.70717876, -116.62555419](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 10:54:50

Taken at: [43.70718657, -116.62555053](#)

[Image](#)




Flooring/Baseboard

Taken on: 2019-01-30 10:54:58

Taken at: [43.70718098, -116.6255544](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 10:55:03

Taken at: [43.70718098, -116.6255544](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 10:55:10

Taken at: [43.70714439, -116.62553892](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 10:55:17

Taken at: [43.70714439, -116.62553892](#)

[Image](#)

Dining Room	CONDITION	ACTION	COMMENTS
Flooring/Baseboard	- - - D	None	scratches on floor, floor pulling up next to sliding glass door
Light Fixture/Fan	- S - -	None	
Other	- S - -	None	
Smoke/CO Detector	- S - -	None	
Switch/Outlet	- S - -	None	
Wall/Ceiling	- - - D	None	some walls have patched but not painted
Window Covering	- - - D	None	blind are stuck in close position
Window/Lock/Screen	- S - -	None	



2019-01-30 11:19:51 MST

Taken on: 2019-01-30 11:19:51
Taken at: [43.70715951, -116.62555296](#)
[Image](#)



2019-01-30 11:19:59 MST

Taken on: 2019-01-30 11:19:59
Taken at: [43.70715951, -116.62555296](#)
[Image](#)



2019-01-30 11:20:19 MST

Flooring/Baseboard
Taken on: 2019-01-30 11:20:19
Taken at: [43.70715624, -116.62555273](#)
[Image](#)



2019-01-30 11:20:27 MST

Flooring/Baseboard
Taken on: 2019-01-30 11:20:27
Taken at: [43.70715624, -116.62555273](#)
[Image](#)




2019-01-30 11:21:13 MST

Light Fixture/Fan
Taken on: 2019-01-30 11:21:13
Taken at: [43.70717817, -116.62558898](#)
[Image](#)



2019-01-30 11:21:24 MST

Switch/Outlet
Taken on: 2019-01-30 11:21:24
Taken at: [43.70726136, -116.62566132](#)
[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 11:21:34

Taken at: [43.707196, -116.62556794](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 11:21:47

Taken at: [43.70716698, -116.62555691](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 11:21:56

Taken at: [43.7071551, -116.62550868](#)

[Image](#)



Window Covering

Taken on: 2019-01-30 11:22:32

Taken at: [43.707189, -116.62558335](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-30 11:23:29

Taken at: [43.70713421, -116.62556371](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 11:24:39

Taken at: [43.70715826, -116.62558155](#)

[Image](#)


Hallway/Stairs

CONDITION

ACTION

COMMENTS

Closet/Cabinet	- S - -	None	
Flooring/Baseboard	- - D	None	chips in baseboard
Light Fixture	- S - -	None	
Other	- - D	None	filter is dirty
Railing/Banister	- S - -	None	
Smoke/CO Detector	- - D	None	missing CO detector in hallway
Switch/Outlet	- S - -	None	
Wall/Ceiling	- S - -	None	



Taken on: 2019-01-30 10:54:12
Taken at: [43.70710686, -116.62556455](#)
[Image](#)



Switch/Outlet
 Taken on: 2019-01-30 11:18:50
Taken at: [43.70714458, -116.62559279](#)
[Image](#)



Other
 Taken on: 2019-01-30 11:18:57
Taken at: [43.70728131, -116.6255936](#)
[Image](#)



Flooring/Baseboard
 Taken on: 2019-01-30 11:19:18
Taken at: [43.70722885, -116.62553588](#)
[Image](#)



Other

Taken on: 2019-01-30 12:07:34

Taken at: [43.70720913, -116.62554835](#)

[Image](#)

Kitchen	CONDITION	ACTION	COMMENTS
Cabinets/Drawers	- - - D	None	scratched and worn
Counter	- - - D	None	dirty and chip on front side of counter when you walk into kitchen
Dishwasher	- - - D	None	food in bottom of dishwasher
Faucet/Plumbing	- - - D	None	water damage under kitchen sink
Flooring/Baseboard	- S - -	None	
Light Fixture	- - - D	None	florescent bulb takes a while to fully turn on
Microwave	- - - D	None	counter top microwave
Other	- - - D	None	cap missing on door stop
Oven	- - - D	None	drip pan are dirty oven dirty
Oven/Microwave	- S - -	None	
Range/Fan/Hood/Filter	- - - D	None	dirty filter
Refrigerator	- - - D	None	missing 1 door rack, butter door is cracked, dirty
Sink/Disposal	- S - -	None	
Switch/Outlet	- S - -	None	
Trash Compactor	- S - -	None	
Wall/Ceiling	- S - -	None	
Window Covering	- - - D	None	dirty blinds, missing plastic cap ends
Window/Lock/Screen	- S - -	None	



Taken on: 2019-01-30 11:25:35
Taken at: [43.70716014, -116.62558413](#)
[Image](#)



Taken on: 2019-01-30 11:25:41
Taken at: [43.7073207, -116.62567117](#)
[Image](#)



Cabinets/Drawers
Taken on: 2019-01-30 11:25:56
Taken at: [43.70731434, -116.62566599](#)
[Image](#)



Cabinets/Drawers
Taken on: 2019-01-30 11:26:00
Taken at: [43.70731434, -116.62566599](#)
[Image](#)



Cabinets/Drawers
Taken on: 2019-01-30 11:26:06
Taken at: [43.70721775, -116.6256529](#)
[Image](#)



Cabinets/Drawers
Taken on: 2019-01-30 11:26:14
Taken at: [43.70721251, -116.62565074](#)
[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:26:20

Taken at: [43.70721251, -116.62565074](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:26:26

Taken at: [43.70721251, -116.62565074](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:26:33

Taken at: [43.70721251, -116.62565074](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:26:50

Taken at: [43.70720793, -116.6256516](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:27:01

Taken at: [43.70720793, -116.6256516](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:27:21

Taken at: [43.70720793, -116.6256516](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:27:29

Taken at: [43.70720793, -116.6256516](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:27:52

Taken at: [43.7070148, -116.6257255](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:27:59

Taken at: [43.7070148, -116.6257255](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:28:04

Taken at: [43.7070148, -116.6257255](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:28:13

Taken at: [43.7070148, -116.6257255](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:28:24

Taken at: [43.7070148, -116.6257255](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:28:33

Taken at: [43.7070148, -116.6257255](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:28:47

Taken at: [43.7070148, -116.6257255](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:28:51

Taken at: [43.7070148, -116.6257255](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:29:01

Taken at: [43.7070148, -116.6257255](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:29:08

Taken at: [43.7070148, -116.6257255](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:29:16

Taken at: [43.7070148, -116.6257255](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:29:28

Taken at: [43.70706852, -116.62561937](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:29:38

Taken at: [43.70706852, -116.62561937](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:29:50

Taken at: [43.70706852, -116.62561937](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:29:57

Taken at: [43.70706852, -116.62561937](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:30:07

Taken at: [43.70706852, -116.62561937](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:30:30

Taken at: [43.70712621, -116.62562028](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:30:35

Taken at: [43.7071539, -116.62563613](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:30:46

Taken at: [43.70725481, -116.6256216](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:30:58

Taken at: [43.70725481, -116.6256216](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:31:04

Taken at: [43.70725481, -116.6256216](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:31:20

Taken at: [43.70725481, -116.6256216](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:31:27

Taken at: [43.70725481, -116.6256216](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:31:36

Taken at: [43.70725481, -116.6256216](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:31:44

Taken at: [43.70725481, -116.6256216](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:32:04

Taken at: [43.7071966, -116.62561887](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:32:17

Taken at: [43.7071966, -116.62561887](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:32:22

Taken at: [43.7071966, -116.62561887](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:33:26

Taken at: [43.7071966, -116.62561887](#)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:33:37

Taken at: [43.7071966, -116.62561887](https://www.zillow.com/homedetails/43.7071966,-116.62561887)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:33:43

Taken at: [43.7071966, -116.62561887](https://www.zillow.com/homedetails/43.7071966,-116.62561887)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:34:04

Taken at: [43.7071966, -116.62561887](https://www.zillow.com/homedetails/43.7071966,-116.62561887)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:34:17

Taken at: [43.7071966, -116.62561887](https://www.zillow.com/homedetails/43.7071966,-116.62561887)

[Image](#)



Cabinets/Drawers

Taken on: 2019-01-30 11:34:26

Taken at: [43.7071966, -116.62561887](https://www.zillow.com/homedetails/43.7071966,-116.62561887)

[Image](#)



Counter

Taken on: 2019-01-30 11:34:34

Taken at: [43.7071966, -116.62561887](https://www.zillow.com/homedetails/43.7071966,-116.62561887)

[Image](#)



Counter

Taken on: 2019-01-30 11:35:18

Taken at: [43.70712685, -116.62561573](#)

[Image](#)



Counter

Taken on: 2019-01-30 11:35:24

Taken at: [43.70712886, -116.62561843](#)

[Image](#)



Counter

Taken on: 2019-01-30 11:35:30

Taken at: [43.70712292, -116.62562137](#)

[Image](#)



Counter

Taken on: 2019-01-30 11:35:36

Taken at: [43.70712292, -116.62562137](#)

[Image](#)



Dishwasher

Taken on: 2019-01-30 11:36:05

Taken at: [43.70714606, -116.62559403](#)

[Image](#)



Dishwasher

Taken on: 2019-01-30 11:36:22

Taken at: [43.70716264, -116.62560156](#)

[Image](#)



Faucet/Plumbing

Taken on: 2019-01-30 11:36:55

Taken at: [43.7071553, -116.62560739](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 11:37:27

Taken at: [43.70714429, -116.6256102](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 11:37:33

Taken at: [43.70714074, -116.62560675](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 11:37:59

Taken at: [43.70714036, -116.62560665](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 11:38:11

Taken at: [43.70714036, -116.62560665](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 11:38:25

Taken at: [43.70714036, -116.62560665](#)

[Image](#)



Light Fixture

Taken on: 2019-01-30 11:38:44

Taken at: [43.70713942, -116.6256064](#)

[Image](#)



Microwave

Taken on: 2019-01-30 11:39:17

Taken at: [43.70719454, -116.62567268](#)

[Image](#)



Microwave

Taken on: 2019-01-30 11:39:24

Taken at: [43.70719158, -116.62567215](#)

[Image](#)



Microwave

Taken on: 2019-01-30 11:39:32

Taken at: [43.70719158, -116.62567215](#)

[Image](#)



Oven

Taken on: 2019-01-30 11:39:47

Taken at: [43.70717428, -116.62563355](#)

[Image](#)



Oven

Taken on: 2019-01-30 11:39:55

Taken at: [43.70716902, -116.62562177](#)

[Image](#)



Oven

Taken on: 2019-01-30 11:40:00

Taken at: [43.70716987, -116.6256192](#)

[Image](#)



Oven

Taken on: 2019-01-30 11:40:06

Taken at: [43.70716834, -116.62561608](#)

[Image](#)



Oven

Taken on: 2019-01-30 11:40:17

Taken at: [43.70717518, -116.6256195](#)

[Image](#)



Oven

Taken on: 2019-01-30 11:40:43

Taken at: [43.7071571, -116.62562831](#)

[Image](#)



Oven

Taken on: 2019-01-30 11:40:52

Taken at: [43.70715985, -116.62562372](#)

[Image](#)



Oven

Taken on: 2019-01-30 11:41:01

Taken at: [43.70715788, -116.62562239](#)

[Image](#)



Oven

Taken on: 2019-01-30 11:41:11

Taken at: [43.70715788, -116.62562239](#)

[Image](#)



Range/Fan/Hood/Filter

Taken on: 2019-01-30 11:41:20

Taken at: [43.70716351, -116.62561381](#)

[Image](#)



Range/Fan/Hood/Filter

Taken on: 2019-01-30 11:41:32

Taken at: [43.70715498, -116.62564479](#)

[Image](#)



Refrigerator

Taken on: 2019-01-30 11:41:56

Taken at: [43.70715931, -116.62564289](#)

[Image](#)



Refrigerator

Taken on: 2019-01-30 11:42:07

Taken at: [43.70713493, -116.62570359](#)

[Image](#)



Refrigerator

Taken on: 2019-01-30 11:42:15

Taken at: [43.70715663, -116.6256824](#)

[Image](#)



Refrigerator

Taken on: 2019-01-30 11:42:38

Taken at: [43.70715663, -116.6256824](#)

[Image](#)



Refrigerator

Taken on: 2019-01-30 11:43:01

Taken at: [43.70715663, -116.6256824](#)

[Image](#)



Refrigerator

Taken on: 2019-01-30 11:43:11

Taken at: [43.70710019, -116.62572789](#)

[Image](#)



Refrigerator

Taken on: 2019-01-30 11:43:19

Taken at: [43.70710686, -116.62571703](#)

[Image](#)



Refrigerator

Taken on: 2019-01-30 11:43:28

Taken at: [43.70711614, -116.62570645](#)

[Image](#)



Refrigerator

Taken on: 2019-01-30 11:43:35

Taken at: [43.70711608, -116.62570023](#)

[Image](#)



Refrigerator

Taken on: 2019-01-30 11:43:47

Taken at: [43.70711608, -116.62570023](#)

[Image](#)



Sink/Disposal

Taken on: 2019-01-30 11:43:55

Taken at: [43.7071151, -116.62569163](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 11:44:22

Taken at: [43.70705836, -116.62558896](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 11:44:29

Taken at: [43.70705836, -116.62558896](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 11:44:36

Taken at: [43.70705836, -116.62558896](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 11:44:42

Taken at: [43.70705836, -116.62558896](#)

[Image](#)



Other

Taken on: 2019-01-30 11:45:01

Taken at: [43.70716311, -116.6256579](#)

[Image](#)



Window Covering

Taken on: 2019-01-30 11:46:21

Taken at: [43.70717976, -116.6256473](#)

[Image](#)



Window Covering

Taken on: 2019-01-30 11:46:39

Taken at: [43.70712457, -116.62565378](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-30 11:47:11

Taken at: [43.70712874, -116.62563636](#)

[Image](#)



Window Covering

Taken on: 2019-01-30 11:47:37

Taken at: [43.70713217, -116.62563704](#)

[Image](#)

Laundry Room

CONDITION

ACTION

COMMENTS

Cabinet/Counter/Shelving	- - - D	None	dirty
Door/Knob/Lock	- S - -	None	
Dryer	- S - -	None	
Faucet/Valve	- S - -	None	
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- S - -	None	
Other	- - - D	None	debris behind washer and dryer
Plumbing/Drain	- S - -	None	
Switch/Outlet	- S - -	None	
Wall/Ceiling	- S - -	None	
Washer	- S - -	None	
Window Covering	- S - -	None	
Window/Lock/Screen	- S - -	None	



Taken on: 2019-01-30 11:48:21
Taken at: [43.70713434, -116.62563599](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-30 11:48:30
Taken at: [43.70716086, -116.62565149](#)
[Image](#)



Cabinet/Counter/Shelving
 Taken on: 2019-01-30 11:48:36
Taken at: [43.70715978, -116.62564899](#)
[Image](#)



Door/Knob/Lock
 Taken on: 2019-01-30 11:48:56
Taken at: [43.70716061, -116.62564883](#)
[Image](#)



Dryer

Taken on: 2019-01-30 11:49:08

Taken at: [43.70715217, -116.62563754](#)

[Image](#)



Light Fixture/Fan

Taken on: 2019-01-30 11:49:18

Taken at: [43.70715158, -116.62563511](#)

[Image](#)



Plumbing/Drain

Taken on: 2019-01-30 11:49:29

Taken at: [43.7071757, -116.62563704](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 11:49:44

Taken at: [43.70718035, -116.62562841](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 11:49:51

Taken at: [43.70718035, -116.62562841](#)

[Image](#)



Washer

Taken on: 2019-01-30 11:49:58

Taken at: [43.70717293, -116.62563145](#)

[Image](#)



Other

Taken on: 2019-01-30 11:50:17

Taken at: [43.70717396, -116.62563271](#)

[Image](#)

Living Room	CONDITION	ACTION	COMMENTS
Door/Knob/Lock	- S - -	None	
Fireplace Equipment	- - - D	None	unknown substance on fireplace glass and screen
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- S - -	None	
Other	- S - -	None	
Switch/Outlet	- S - -	None	
Wall/Ceiling	- - - D	None	mismatch paint, patched but not painted in some areas
Window Covering	- S - -	None	
Window/Lock/Screen	- S - -	None	



Taken on: 2019-01-30 11:51:43

Taken at: [43.70717259, -116.62561656](#)

[Image](#)



Taken on: 2019-01-30 11:51:53

Taken at: [43.70717139, -116.62561553](#)

[Image](#)



Fireplace Equipment

Taken on: 2019-01-30 11:52:16

Taken at: [43.707172, -116.62561439](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 11:52:38

Taken at: [43.70716753, -116.62561238](#)

[Image](#)



Flooring/Baseboard

Taken on: 2019-01-30 11:52:49

Taken at: [43.70716753, -116.62561238](#)

[Image](#)



Light Fixture/Fan

Taken on: 2019-01-30 11:52:55

Taken at: [43.70714031, -116.62560847](#)

[Image](#)




Wall/Ceiling

Taken on: 2019-01-30 11:53:07

Taken at: [43.7072274, -116.62557189](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 11:53:16

Taken at: [43.7072274, -116.62557189](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 11:53:25

Taken at: [43.7072274, -116.62557189](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 11:53:31

Taken at: [43.7072274, -116.62557189](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 11:53:35

Taken at: [43.70723105, -116.62560091](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 11:53:41

Taken at: [43.70722851, -116.62561064](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 11:53:47

Taken at: [43.70724699, -116.62560319](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 11:54:10

Taken at: [43.70724365, -116.62559976](#)

[Image](#)




Window Covering

Taken on: 2019-01-30 11:55:09

Taken at: [43.70724019, -116.62557755](#)

[Image](#)



Window/Lock/Screen

Taken on: 2019-01-30 11:55:16

Taken at: [43.70724019, -116.62557755](#)

[Image](#)




Wall/Ceiling

Taken on: 2019-01-30 11:55:39

Taken at: [43.70723428, -116.62557463](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 11:55:49

Taken at: [43.70721102, -116.62559887](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 11:55:55

Taken at: [43.70721238, -116.62560082](#)

[Image](#)



Wall/Ceiling

Taken on: 2019-01-30 11:56:01

Taken at: [43.70721238, -116.62560082](#)

[Image](#)

Back Yard/Exterior

CONDITION

ACTION

COMMENTS

Building Exterior	- S - -	None
Fence/Gate	- S - -	None
Landscaping	- - - D	None
Light Fixture	- S - -	None
Other	- S - -	None
Patio Cover	- S - -	None
Patio/Deck/Balcony	- S - -	None
Pool/Heater/Equipment	- S - -	None
Porch/Stairs	- S - -	None
Spa/Cover/Equipment	- S - -	None
Sprinkler/Timer	- S - -	None
Walkway	- S - -	None

weeds next to house, in corner
wood is strapped to back fence,
trash and leaves throughout yard,
holes throughout yard



Taken on: 2019-01-30 11:56:28
Taken at: [43.70721512, -116.62560616](#)
[Image](#)



Building Exterior
Taken on: 2019-01-30 11:56:39
Taken at: [43.70721512, -116.62560616](#)
[Image](#)



Landscaping
Taken on: 2019-01-30 11:56:50
Taken at: [43.70716356, -116.62567877](#)
[Image](#)



Landscaping
Taken on: 2019-01-30 11:56:56
Taken at: [43.70708842, -116.62568289](#)
[Image](#)



Landscaping

Taken on: 2019-01-30 11:57:09

Taken at: [43.70707466, -116.62567687](#)

[Image](#)



Landscaping

Taken on: 2019-01-30 11:57:16

Taken at: [43.70707466, -116.62567687](#)

[Image](#)



Fence/Gate

Taken on: 2019-01-30 11:57:50

Taken at: [43.70697738, -116.62557974](#)

[Image](#)



Landscaping

Taken on: 2019-01-30 11:58:07

Taken at: [43.70696733, -116.62548055](#)

[Image](#)



Landscaping

Taken on: 2019-01-30 11:58:18

Taken at: [43.70712612, -116.62561683](#)

[Image](#)



Landscaping

Taken on: 2019-01-30 11:58:33

Taken at: [43.70712612, -116.62561683](#)

[Image](#)



Landscaping

Taken on: 2019-01-30 12:05:08

Taken at: [43.70717031, -116.62565829](#)

[Image](#)



Landscaping

Taken on: 2019-01-30 12:05:18

Taken at: [43.70717031, -116.62565829](#)

[Image](#)

Garage/Parking	CONDITION	ACTION	COMMENTS
Cabinet/Counter	- S - -	None	
Driveway/Floor	- - - D	None	near garage door chucks are missing in cement, rust and oil stains
Electrical/Exposed Wiring	- S - -	None	
Garage Door	- - - D	None	weather stripping is damaged
Light Fixture	- S - -	None	
Other	- S - -	None	
Other Door/Knob/Lock	- S - -	None	
Other Storage/Shelving	- S - -	None	
Switch/Outlet	- S - -	None	
Window/Lock/Screen	- S - -	None	



Taken on: 2019-01-30 12:02:04

Taken at: [43.70719335, -116.62558467](#)

[Image](#)



Cabinet/Counter

Taken on: 2019-01-30 12:02:12

Taken at: [43.70719335, -116.62558467](#)

[Image](#)




Driveway/Floor

Taken on: 2019-01-30 12:02:21

Taken at: [43.70718134, -116.6256047](#)

[Image](#)



Driveway/Floor

Taken on: 2019-01-30 12:02:29

Taken at: [43.70718134, -116.6256047](#)

[Image](#)




Driveway/Floor

Taken on: 2019-01-30 12:02:35

Taken at: [43.70718134, -116.6256047](#)

[Image](#)



Driveway/Floor

Taken on: 2019-01-30 12:03:05

Taken at: [43.70718681, -116.62560455](#)

[Image](#)



Garage Door

Taken on: 2019-01-30 12:03:22

Taken at: [43.70718681, -116.62560455](#)

[Image](#)



Light Fixture

Taken on: 2019-01-30 12:03:30

Taken at: [43.7070369, -116.6256649](#)

[Image](#)

Keys/Remotes/Devices

CONDITION

ACTION

COMMENTS

Keys	- - - D	None	no keys left a property
Other	- S - -	None	
Remotes/Devices	- - - D	None	Missing garage remotes

Personal Property	CONDITION	ACTION	COMMENTS
-------------------	-----------	--------	----------

Other	- S - -	None	
-------	---------	------	--

Safety/Security	CONDITION	ACTION	COMMENTS
-----------------	-----------	--------	----------

Other	- S - -	None	
Security System	- S - -	None	
Security Window Bars	- S - -	None	
Smoke/CO Detector	- S - -	None	

Systems	CONDITION	ACTION	COMMENTS
---------	-----------	--------	----------

Air Conditioning/Filter	- S - -	None	
Breaker Box	- S - -	None	
Furnace	- S - -	None	
Other	- S - -	None	
Sewer Cleanout	- S - -	None	
Sprinkler/Timer	- S - -	None	
Thermostat	- S - -	None	
Water Heater	- S - -	None	
Water Softener	- S - -	None	
Whole House Fan	- S - -	None	



Air Conditioning/Filter

Taken on: 2019-01-30 12:04:53

Taken at: [43.70715856, -116.62561058](https://www.zillow.com/homedetails/43.70715856,-116.62561058/)
[Image](#)



Breaker Box

Taken on: 2019-01-30 12:06:24

Taken at: [43.7071519, -116.62565773](https://www.zillow.com/homedetails/43.7071519,-116.62565773/)
[Image](#)



Furnace

Taken on: 2019-01-30 12:06:49

Taken at: [43.70716229, -116.62561286](#)

[Image](#)



Water Heater

Taken on: 2019-01-30 12:07:07

Taken at: [43.70719906, -116.62554975](#)

[Image](#)

Additional Comments

Final Comments

Thank you for being our tenant. We will process your security deposit return within 30 days.