

Move In

Property	Tenant(s)	Date	Agent / Inspector
385 E 42nd St Unit 304		2022-06-13	Savanna Hales

Move-In Conditions

S=Satisfactory
 F=Fair

Entry	CONDITION	COMMENTS
Door/Knob/Lock	- S -	
Doorbell	- S -	
Flooring/Baseboard	- S -	Scratches on floor
Switch/Outlet	- S -	
Wall/Ceiling	- S -	



Door/Knob/Lock

2022-06-13 10:11:31

43.6342393, -116.2467981

Image



Door/Knob/Lock

2022-06-13 10:11:38

43.6342393, -116.2467981

Image



Doorbell

📅 2022-06-13 10:11:43

📍 [43.6342393, -116.2467981](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2022-06-13 10:12:00

📍 [43.6342393, -116.2467981](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2022-06-13 10:12:05

📍 [43.6342393, -116.2467981](#)


🖼️ [Image](#)



📅 2022-06-13 10:11:25

📍 [43.6342393, -116.2467981](#)

🖼️ [Image](#)



Switch/Outlet

📅 2022-06-13 10:12:25

📍 [43.6342838, -116.2468292](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:12:34

📍 [43.6342838, -116.2468292](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:12:36

📍 [43.6342838, -116.2468292](#)

🖼️ [Image](#)

🏠 Bathroom

🔗 CONDITION

💬 COMMENTS

	🔗 CONDITION	💬 COMMENTS
Cabinet/Counter/Shelving	- S -	
Door/Knob/Lock	- S -	
Exhaust Fan	- S -	
Flooring/Baseboard	- S -	
Light Fixture	- S -	
Medicine Cabinet/Mirror	- S -	
Sink/Faucet	- S -	
Switch/Outlet	- S -	
Toilet	- S -	
Toilet Paper Holder	- S -	
Towel Rack	- S -	
Tub/Shower	- S -	
Wall/Ceiling	- S -	



Cabinet/Counter/Shelving

📅 2022-06-13 10:26:51

📍 [43.6341858, -116.246765](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2022-06-13 10:26:57

📍 [43.6341858, -116.246765](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2022-06-13 10:27:03

📍 [43.6341858, -116.246765](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2022-06-13 10:27:08

📍 [43.6341858, -116.246765](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2022-06-13 10:27:13

📍 [43.6341858, -116.246765](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2022-06-13 10:27:19

📍 [43.6341858, -116.246765](#)

🖼️ [Image](#)



2022-06-13 10:27:27 MDT

Cabinet/Counter/Shelving

📅 2022-06-13 10:27:27

📍 [43.6341858, -116.246765](#)

🖼️ [Image](#)



2022-06-13 10:27:33 MDT

Cabinet/Counter/Shelving

📅 2022-06-13 10:27:33

📍 [43.6341858, -116.246765](#)

🖼️ [Image](#)



2022-06-13 10:27:37 MDT

Cabinet/Counter/Shelving

📅 2022-06-13 10:27:37

📍 [43.6341858, -116.246765](#)

🖼️ [Image](#)



2022-06-13 10:27:44 MDT

Cabinet/Counter/Shelving

📅 2022-06-13 10:27:44

📍 [43.6341858, -116.246765](#)

🖼️ [Image](#)



2022-06-13 10:27:50 MDT

Cabinet/Counter/Shelving

📅 2022-06-13 10:27:50

📍 [43.6341858, -116.246765](#)

🖼️ [Image](#)



2022-06-13 10:27:54 MDT

Cabinet/Counter/Shelving

📅 2022-06-13 10:27:54

📍 [43.6341858, -116.246765](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2022-06-13 10:28:04

📍 [43.6341858, -116.246765](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2022-06-13 10:28:10

📍 [43.6342412, -116.2467704](#)

🖼️ [Image](#)



Exhaust Fan

📅 2022-06-13 10:28:16

📍 [43.6342412, -116.2467704](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2022-06-13 10:28:32

📍 [43.6342412, -116.2467704](#)

🖼️ [Image](#)



Light Fixture

📅 2022-06-13 10:28:41

📍 [43.6342412, -116.2467704](#)

🖼️ [Image](#)



Medicine Cabinet/Mirror

📅 2022-06-13 10:28:47

📍 [43.6342412, -116.2467704](#)

🖼️ [Image](#)



2022-06-13 10:26:46 MDT

📅 2022-06-13 10:26:46

📍 [43.6341858, -116.246765](#)

🖼️ [Image](#)



2022-06-13 10:28:58 MDT

Sink/Faucet

📅 2022-06-13 10:28:58

📍 [43.6342412, -116.2467704](#)

🖼️ [Image](#)



2022-06-13 10:29:02 MDT

Sink/Faucet

📅 2022-06-13 10:29:02

📍 [43.6342412, -116.2467704](#)

🖼️ [Image](#)



2022-06-13 10:29:17 MDT

Switch/Outlet

📅 2022-06-13 10:29:17

📍 [43.6342412, -116.2467704](#)

🖼️ [Image](#)



2022-06-13 10:29:23 MDT

Toilet

📅 2022-06-13 10:29:23

📍 [43.6342412, -116.2467704](#)

🖼️ [Image](#)



2022-06-13 10:29:31 MDT

Toilet

📅 2022-06-13 10:29:31

📍 [43.6342412, -116.2467704](#)

🖼️ [Image](#)



Toilet Paper Holder

📅 2022-06-13 10:29:34

🔍 [43.6342412, -116.2467704](#)

🖼️ [Image](#)



Towel Rack

📅 2022-06-13 10:29:40

🔍 [43.6342412, -116.2467704](#)

🖼️ [Image](#)



Tub/Shower

📅 2022-06-13 10:29:46

🔍 [43.6342412, -116.2467704](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:29:52

🔍 [43.6342412, -116.2467704](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:29:55

🔍 [43.6342412, -116.2467704](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:30:00

🔍 [43.6342412, -116.2467704](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:30:05

📍 [43.6342412, -116.2467704](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:30:12

📍 [43.6342526, -116.2467919](#)

🖼️ [Image](#)

📖 Bathroom 2

📌 CONDITION

💬 COMMENTS

📖 Bathroom 2	📌 CONDITION	💬 COMMENTS
Cabinet/Counter/Shelving	- S -	
Door/Knob/Lock	- S -	
Exhaust Fan	- S -	
Flooring/Baseboard	- S -	
Light Fixture	- S -	
Medicine Cabinet/Mirror	- S -	
Sink/Faucet	- S -	
Switch/Outlet	- S -	
Toilet	- S -	
Toilet Paper Holder	- S -	
Towel Rack	- S -	
Tub/Shower	- S -	
Wall/Ceiling	- S -	



Cabinet/Counter/Shelving

📅 2022-06-13 10:34:06

📍 [43.6342921, -116.2468156](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2022-06-13 10:34:13

📍 [43.6342921, -116.2468156](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2022-06-13 10:34:18

📍 [43.6342921, -116.2468156](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2022-06-13 10:34:26

📍 [43.6342921, -116.2468156](#)

🖼️ [Image](#)




Door/Knob/Lock

📅 2022-06-13 10:34:34

📍 [43.6342921, -116.2468156](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2022-06-13 10:34:39

📍 [43.6342921, -116.2468156](#)

🖼️ [Image](#)



Exhaust Fan

📅 2022-06-13 10:34:44

📍 [43.6342921, -116.2468156](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2022-06-13 10:34:52

📍 [43.6342921, -116.2468156](#)

🖼️ [Image](#)



Light Fixture

📅 2022-06-13 10:35:00

📍 [43.6342921, -116.2468156](#)

🖼️ [Image](#)



Medicine Cabinet/Mirror

📅 2022-06-13 10:35:03

📍 [43.6342921, -116.2468156](#)

🖼️ [Image](#)



📅 2022-06-13 10:33:57

📍 [43.6342921, -116.2468156](#)

🖼️ [Image](#)



Sink/Faucet

📅 2022-06-13 10:35:12

📍 [43.6342921, -116.2468156](#)

🖼️ [Image](#)



Switch/Outlet

📅 2022-06-13 10:35:23

📍 [43.6342921, -116.2468156](#)

🖼️ [Image](#)



Toilet

📅 2022-06-13 10:35:31

📍 [43.6342921, -116.2468156](#)

🖼️ [Image](#)



Toilet

📅 2022-06-13 10:35:37

📍 [43.6342921, -116.2468156](#)

🖼️ [Image](#)



Toilet Paper Holder

📅 2022-06-13 10:35:41

📍 [43.6342921, -116.2468156](#)

🖼️ [Image](#)



Towel Rack

📅 2022-06-13 10:35:44

📍 [43.634312, -116.2468376](#)

🖼️ [Image](#)



Tub/Shower

📅 2022-06-13 10:35:53

📍 [43.634312, -116.2468376](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:36:17

📍 [43.634312, -116.2468376](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:36:24

📍 [43.634312, -116.2468376](#)

🖼️ [Image](#)




Wall/Ceiling

📅 2022-06-13 10:36:28

📍 [43.634312, -116.2468376](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:36:32

📍 [43.634312, -116.2468376](#)

🖼️ [Image](#)

🏠 Bedroom

📍 CONDITION

💬 COMMENTS

🏠 Bedroom	📍 CONDITION	💬 COMMENTS
Closet/Door/Track/Shelving	- S -	
Door/Knob/Lock	- S -	
Flooring/Baseboard	- S -	
Light Fixture/Fan	- S -	
Smoke / CO detector	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	
Window Covering	- S -	
Window/Lock/Screen	- S -	




Closet/Door/Track/Shelving

📅 2022-06-13 10:23:24

🔍 [43.6342812, -116.2468153](#)

🖼️ [Image](#)



Closet/Door/Track/Shelving

📅 2022-06-13 10:23:27

🔍 [43.6342812, -116.2468153](#)

🖼️ [Image](#)



Closet/Door/Track/Shelving

📅 2022-06-13 10:23:40

🔍 [43.6342812, -116.2468153](#)

🖼️ [Image](#)




Door/Knob/Lock

📅 2022-06-13 10:23:47

🔍 [43.6342812, -116.2468153](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2022-06-13 10:23:57

🔍 [43.6342812, -116.2468153](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2022-06-13 10:24:00

🔍 [43.6342812, -116.2468153](#)

🖼️ [Image](#)



Light Fixture/Fan

📅 2022-06-13 10:24:26

📍 [43.6341771, -116.2467575](#)

🖼️ [Image](#)



📅 2022-06-13 10:23:07

📍 [43.6342812, -116.2468153](#)

🖼️ [Image](#)



Smoke / CO detector

📅 2022-06-13 10:24:45

📍 [43.6341771, -116.2467575](#)

🖼️ [Image](#)



Smoke / CO detector

📅 2022-06-13 10:52:15

📍 [43.6343031, -116.2468247](#)

🖼️ [Image](#)



Switch/Outlet

📅 2022-06-13 10:24:59

📍 [43.6341771, -116.2467575](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:25:14

📍 [43.6341771, -116.2467575](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:25:16

📍 [43.6341771, -116.2467575](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:25:25

📍 [43.6341771, -116.2467575](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:25:27

📍 [43.6341771, -116.2467575](#)

🖼️ [Image](#)



Window Covering

📅 2022-06-13 10:25:36

📍 [43.6341771, -116.2467575](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2022-06-13 10:25:58

📍 [43.6341771, -116.2467575](#)

🖼️ [Image](#)

🏠 Bedroom 2

🔧 CONDITION

💬 COMMENTS

Closet/Door/Track/Shelving	- S -	
Door/Knob/Lock	- S -	

📖 Bedroom 2**📌 CONDITION****🗨️ COMMENTS**

Flooring/Baseboard	- S -	
Light Fixture/Fan	- S -	
Smoke / CO detector	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	
Window Covering	- S -	
Window/Lock/Screen	- S -	

**Closet/Door/Track/Shelving**

📅 2022-06-13 10:39:09

📍 [43.6343086, -116.2468242](#)🖼️ [Image](#)**Closet/Door/Track/Shelving**

📅 2022-06-13 10:39:17

📍 [43.6343086, -116.2468242](#)🖼️ [Image](#)**Closet/Door/Track/Shelving**

📅 2022-06-13 10:39:25

📍 [43.6343086, -116.2468242](#)🖼️ [Image](#)**Door/Knob/Lock**

📅 2022-06-13 10:41:55

📍 [43.634295, -116.2468349](#)🖼️ [Image](#)



Door/Knob/Lock

📅 2022-06-13 10:42:01

📍 [43.634295, -116.2468349](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2022-06-13 10:42:09

📍 [43.634295, -116.2468349](#)

🖼️ [Image](#)



Light Fixture/Fan

📅 2022-06-13 10:42:23

📍 [43.634295, -116.2468349](#)

🖼️ [Image](#)



📅 2022-06-13 10:39:00

📍 [43.6343086, -116.2468242](#)

🖼️ [Image](#)



Smoke / CO detector

📅 2022-06-13 10:42:32

📍 [43.634295, -116.2468349](#)

🖼️ [Image](#)



Smoke / CO detector

📅 2022-06-13 10:50:01

📍 [43.6342757, -116.2461973](#)

🖼️ [Image](#)



Switch/Outlet

📅 2022-06-13 10:42:48

📍 [43.634295, -116.2468349](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:43:00

📍 [43.634295, -116.2468349](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:43:03

📍 [43.634295, -116.2468349](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:44:06

📍 [43.6342939, -116.2468128](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:44:10

📍 [43.6342939, -116.2468128](#)

🖼️ [Image](#)



Window Covering

📅 2022-06-13 10:44:18

📍 [43.6342939, -116.2468128](#)

🖼️ [Image](#)



Window/Lock/Screen
 2022-06-13 10:44:38
[43.6342939, -116.2468128](#)
[Image](#)

📖 Kitchen	🔗 CONDITION	💬 COMMENTS
Burner Pans	- S -	
Cabinets/Drawers	- S -	Drawer worn
Counter	- S -	
Dishwasher	- S -	
Faucet/Plumbing	- S -	
Flooring/Baseboard	- S -	
Light Fixture	- S -	
Microwave	- S -	
Oven	- S -	
Range/Fan/Hood/Filter	- S -	
Refrigerator	- S -	
Sink/Disposal	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	



Burner Pans

📅 2022-06-13 10:14:25

📍 [43.634287, -116.2468035](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-06-13 10:14:33

📍 [43.634287, -116.2468035](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-06-13 10:14:37

📍 [43.634287, -116.2468035](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-06-13 10:14:43

📍 [43.634287, -116.2468035](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-06-13 10:14:50

📍 [43.634287, -116.2468035](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-06-13 10:14:57

📍 [43.634287, -116.2468035](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-06-13 10:15:05

📍 [43.634287, -116.2468035](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-06-13 10:15:11

📍 [43.634287, -116.2468035](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-06-13 10:15:18

📍 [43.634287, -116.2468035](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-06-13 10:15:24

📍 [43.634287, -116.2468035](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-06-13 10:15:28

📍 [43.634287, -116.2468035](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-06-13 10:15:33

📍 [43.634287, -116.2468035](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-06-13 10:15:39

📍 [43.634287, -116.2468035](#)

[Image](#)



Cabinets/Drawers

📅 2022-06-13 10:15:49

📍 [43.634287, -116.2468035](#)

[Image](#)



Cabinets/Drawers

📅 2022-06-13 10:15:56

📍 [43.634287, -116.2468035](#)

[Image](#)



Counter

📅 2022-06-13 10:16:03

📍 [43.634287, -116.2468035](#)

[Image](#)



Counter

📅 2022-06-13 10:16:09

📍 [43.6342657, -116.2468114](#)

[Image](#)



Counter

📅 2022-06-13 10:16:13

📍 [43.6342657, -116.2468114](#)

[Image](#)



Dishwasher

📅 2022-06-13 10:16:18

📍 [43.6342657, -116.2468114](#)

🖼️ [Image](#)



Dishwasher

📅 2022-06-13 10:16:25

📍 [43.6342657, -116.2468114](#)

🖼️ [Image](#)



Dishwasher

📅 2022-06-13 10:16:29

📍 [43.6342657, -116.2468114](#)

🖼️ [Image](#)



Dishwasher

📅 2022-06-13 10:16:35

📍 [43.6342657, -116.2468114](#)

🖼️ [Image](#)



Faucet/Plumbing

📅 2022-06-13 10:16:42

📍 [43.6342657, -116.2468114](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2022-06-13 10:16:51

📍 [43.6342657, -116.2468114](#)

🖼️ [Image](#)



Light Fixture

📅 2022-06-13 10:17:01

📍 [43.6342657, -116.2468114](#)

🖼️ [Image](#)



Microwave

📅 2022-06-13 10:17:07

📍 [43.6342657, -116.2468114](#)

🖼️ [Image](#)



Microwave

📅 2022-06-13 10:17:11

📍 [43.6342657, -116.2468114](#)

🖼️ [Image](#)



📅 2022-06-13 10:14:15

📍 [43.634287, -116.2468035](#)

🖼️ [Image](#)



Oven

📅 2022-06-13 10:17:19

📍 [43.6342657, -116.2468114](#)

🖼️ [Image](#)



Oven

📅 2022-06-13 10:17:24

📍 [43.6342657, -116.2468114](#)

🖼️ [Image](#)



Oven

📅 2022-06-13 10:17:30

📍 [43.6342657, -116.2468114](#)

🖼️ [Image](#)



Range/Fan/Hood/Filter

📅 2022-06-13 10:17:39

📍 [43.6342657, -116.2468114](#)

🖼️ [Image](#)



Refrigerator

📅 2022-06-13 10:17:55

📍 [43.6342657, -116.2468114](#)

🖼️ [Image](#)



Refrigerator

📅 2022-06-13 10:18:00

📍 [43.6342657, -116.2468114](#)

🖼️ [Image](#)



Refrigerator

📅 2022-06-13 10:18:04

📍 [43.6342657, -116.2468114](#)

🖼️ [Image](#)



Sink/Disposal

📅 2022-06-13 10:18:13

📍 [43.6342612, -116.2468238](#)

🖼️ [Image](#)



Switch/Outlet

📅 2022-06-13 10:18:35

📍 [43.6342612, -116.2468238](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:18:49

📍 [43.6342612, -116.2468238](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:18:56

📍 [43.6342612, -116.2468238](#)

🖼️ [Image](#)

📖 Laundry Room

📍 CONDITION

💬 COMMENTS

📖 Laundry Room	📍 CONDITION	💬 COMMENTS
Door/Knob/Lock	- S -	Paint chipping
Dryer	- S -	
Washer	- S -	



Door/Knob/Lock

📅 2022-06-13 10:12:57

📍 [43.6342838, -116.2468292](#)

[Image](#)



Door/Knob/Lock

📅 2022-06-13 10:13:07

📍 [43.6342838, -116.2468292](#)

[Image](#)



Door/Knob/Lock

📅 2022-06-13 10:13:11

📍 [43.6342838, -116.2468292](#)

[Image](#)



Dryer

📅 2022-06-13 10:13:20

📍 [43.6342838, -116.2468292](#)

[Image](#)



Dryer

📅 2022-06-13 10:13:25

📍 [43.6342838, -116.2468292](#)

[Image](#)



Dryer

📅 2022-06-13 10:13:29

📍 [43.6342838, -116.2468292](#)

[Image](#)



📅 2022-06-13 10:55:25
 🔍 [43.634283, -116.2468123](#)
 🖼️ Image



Washer
 📅 2022-06-13 10:13:38
 🔍 [43.6342838, -116.2468292](#)
 🖼️ Image



Washer
 📅 2022-06-13 10:13:43
 🔍 [43.6342838, -116.2468292](#)
 🖼️ Image



Washer
 📅 2022-06-13 10:13:54
 🔍 [43.6342838, -116.2468292](#)
 🖼️ Image

📖 Living Room	📌 CONDITION	💬 COMMENTS
Flooring/Baseboard	- F -	Cut in floor
Light Fixture/Fan	- S -	
Smoke/CO Detector	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- F -	Paint chipping, holes in walls
Window Covering	- S -	
Window/Lock/Screen	- S -	



Flooring/Baseboard

📅 2022-06-13 10:19:21

📍 [43.6342612, -116.2468238](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2022-06-13 10:19:31

📍 [43.6342612, -116.2468238](#)

🖼️ [Image](#)



Light Fixture/Fan

📅 2022-06-13 10:19:45

📍 [43.6342612, -116.2468238](#)

🖼️ [Image](#)



📅 2022-06-13 10:19:14

📍 [43.6342612, -116.2468238](#)

🖼️ [Image](#)



Smoke/CO Detector

📅 2022-06-13 10:20:01

📍 [43.6342612, -116.2468238](#)

🖼️ [Image](#)



Smoke/CO Detector

📅 2022-06-13 10:50:59

📍 [43.6343031, -116.2468247](#)

🖼️ [Image](#)




Switch/Outlet

📅 2022-06-13 10:20:15

📍 [43.6342679, -116.2467888](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:20:31

📍 [43.6342679, -116.2467888](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:20:48

📍 [43.6342679, -116.2467888](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:20:55

📍 [43.6342679, -116.2467888](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-06-13 10:20:59

📍 [43.6342679, -116.2467888](#)

🖼️ [Image](#)



Window Covering

📅 2022-06-13 10:21:10


📍 [43.6342679, -116.2467888](#)

🖼️ [Image](#)



Window/Lock/Screen
 2022-06-13 10:21:55
[43.6342679, -116.2467888](#)
[Image](#)

Balcony	CONDITION	COMMENTS
Flooring	- S -	
Light Fixture	- S -	
Railing	- S -	
Switch/Outlet	- S -	



Flooring
 2022-06-13 10:22:29
[43.6342812, -116.2468153](#)
[Image](#)



Light Fixture
 2022-06-13 10:22:35
[43.6342812, -116.2468153](#)
[Image](#)



2022-06-13 10:22:24 MDT

📅 2022-06-13 10:22:24

📍 [43.6342812, -116.2468153](#)

🖼️ [Image](#)



2022-06-13 10:22:41 MDT

Railing

📅 2022-06-13 10:22:41

📍 [43.6342812, -116.2468153](#)

🖼️ [Image](#)



2022-06-13 10:22:48 MDT

Switch/Outlet

📅 2022-06-13 10:22:48

📍 [43.6342812, -116.2468153](#)

🖼️ [Image](#)

📖 Keys/Remotes/Devices	📍 CONDITION	💬 COMMENTS
Keys	- S -	
Other	- S -	
Remotes/Devices	- S -	23686
Swag	- S -	



📅 2022-06-13 11:03:43

📍 [43.6342845, -116.2467892](#)

🖼️ [Image](#)



Remotes/Devices

📅 2022-06-13 11:03:39

📍 [43.6342845, -116.2467892](#)

🖼️ [Image](#)



Swag

📅 2022-06-13 11:03:47

📍 [43.6342845, -116.2467892](#)

🖼️ [Image](#)

🏠 Systems	🔧 CONDITION	💬 COMMENTS
Air Conditioning/Filter	- S -	
Breaker Box	- S -	
Evidence of Pest Issue	- S -	
Furnace	- S -	14x18x1
Other	- S -	
Sewer Cleanout	- S -	
Sprinkler/Timer	- S -	
Thermostat	- S -	
Water Heater	- S -	
Water Softener	- S -	
Whole House Fan	- S -	



Furnace

📅 2022-06-13 10:37:51

📍 [43.6343086, -116.2468242](#)

🖼️ [Image](#)



📅 2022-06-13 10:36:47

📍 [43.634312, -116.2468376](#)

🖼️ [Image](#)

Additional Comments

Final Comments

To dispute any findings of this inspection please notify us within 3 business days.

Agent / Technician Signature

