



















































## 📄 Move Out










Property	Tenant(s)	Date	Agent / Inspector
[REDACTED]		2023-12-04	

### 👤 Move Out Condition Summary

📁 AREA	📍 DETAIL	🔴	💬 COMMENTS	📷 MEDIA
Entry	Flooring/Baseboard	D	The flooring is showing signs of wear.	<a href="#">Image</a>
Front Yard/Exterior	Building Exterior	D	A solar floodlight was installed on the home.	<a href="#">Image</a>
Bathroom	Door/Knob/Lock	D	Black marks were observed on the door.	<a href="#">Image</a> <a href="#">Image</a>
Bathroom	Sink/Faucet	D	The drain stopper is stuck down and the flange is cracked.	<a href="#">Image</a> <a href="#">Image</a> <a href="#">Image</a>
Bathroom	Tub/Shower	D	Chips in the tub finish were observed.	<a href="#">Image</a> <a href="#">Image</a> <a href="#">Image</a> <a href="#">Image</a> <a href="#">Image</a>
Bathroom 2	Cabinet/Counter/Shelving	D	Dirty	<a href="#">Image</a> <a href="#">Image</a> <a href="#">Image</a> <a href="#">Image</a> <a href="#">Image</a> <a href="#">Image</a> <a href="#">Image</a> <a href="#">Image</a> <a href="#">Image</a> <a href="#">Image</a>
Bathroom 2	Light Fixture	D	The vanity light fixture is loose.	<a href="#">Image</a>

 AREA	 DETAIL		 COMMENTS	 MEDIA
Bathroom 2	Tub/Shower	D	Chips in the tub finish were observed.	 Image  Image  Image
Bedroom	Wall/Ceiling	D	Photo hooks were observed on the walls.	 Image  Image  Image  Image  Image  Image  Image
Bedroom 2	Closet/Door/Track/Shelving	D	The closet door guide is broken and non-functioning.	 Image  Image
Bedroom 2	Wall/Ceiling	D	Black marks and holes were observed on the walls.	 Image  Image  Image  Image  Image  Image  Image
Bedroom 2	Window Covering	D	A warped blind valance was observed.	 Image  Image
Bedroom 3	Closet/Door/Track/Shelving	D	Chipped paint was observed on the door.	 Image  Image  Image
Bedroom 3	Flooring/Baseboard	D	Pink tape was observed on the baseboard.	 Image  Image  Image  Image  Image
Bedroom 3	Light Fixture/Fan	D	Burnt-out lightbulbs were observed.	 Image  Image
Bedroom 3	Switch/Outlet	D	The phone jack is not mounted to the wall.	 Image  Image
Dining Room	Flooring/Baseboard	D	The flooring is showing signs of wear.	 Image  Image  Image
Dining Room	Wall/Ceiling	D	Mismatched paint was observed on the walls.	 Image  Image  Image  Image
Hallway/Stair s	Closet/Cabinet	D	The bathroom towel rack is being stored in the closet.	 Image  Image  Image
Hallway/Stair s	Flooring/Baseboard	D	A gap in the baseboard was observed.	 Image  Image

 AREA	 DETAIL		 COMMENTS	 MEDIA
Hallway/Stair s	Wall/Ceiling	<b>D</b>	Mismatched paint was observed on the walls.	 Image  Image
Kitchen	Counter	<b>D</b>	A burn on the countertop was observed.	 Image  Image  Image  Image  Image  Image
Kitchen	Dishwasher	<b>D</b>	Dirty	 Image  Image  Image
Kitchen	Flooring/Baseboard	<b>D</b>	The floor is showing signs of wear.	 Image  Image
Kitchen	Wall/Ceiling	<b>D</b>	Unpainted patches and mismatched paint were observed on the walls.	 Image  Image  Image
Laundry Room	Cabinet/Counter/Shelving	<b>D</b>	A stain was observed on the countertop.	 Image  Image  Image
Laundry Room	Flooring/Baseboard	<b>D</b>	A tear in the vinyl flooring was observed.	 Image  Image  Image
Laundry Room	Wall/Ceiling	<b>D</b>	Unpainted patches and mismatched paint were observed on the walls.	 Image  Image  Image  Image  Image
Living Room	Light Fixture/Fan	<b>D</b>	Burnt-out lightbulbs were observed.	 Image
Living Room	Window Covering	<b>D</b>	A mismatched blind slat was observed.	 Image  Image
Back Yard/Exterior	Building Exterior	<b>D</b>	Damage to the siding was observed.	 Image
Back Yard/Exterior	Landscaping	<b>D</b>	Personal property left behind	 Image  Image  Image  Image
Garage/Park ing	Cabinet/Counter	<b>D</b>	Dirty + The bottom of a drawer was missing and broken.	 Image  Image  Image  Image  Image

AREA	DETAIL		COMMENTS	MEDIA
Garage/Parking	Driveway/Floor	D	Dirty	 Image  Image  Image  Image  Image
Garage/Parking	Other Door/Knob/Lock	D	A gap was observed in the exterior garage door.	 Image  Image
Keys/Remotes/Devices	Keys	D	Missing keys	 Image
Keys/Remotes/Devices	Remotes/Devices	D	Missing remotes	 Image

## 🔒 Move-Out Conditions

S=Satisfactory

D=Damaged

📖 Entry	🔒 CONDITION	💬 COMMENTS
Door/Knob/Lock	- S -	
Doorbell	- S -	
Flooring/Baseboard	- - D	The flooring is showing signs of wear.
Light Fixture/Fan	- S -	
Security/Screen Door	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	



📅 2023-12-04 13:18:33

📍 [43.6958857, -116.4917958](#)

🖼️ [Image](#)



📅 2023-12-04 13:18:37

Door/Knob/Lock

📍 [43.6958857, -116.4917958](#)

🖼️ [Image](#)



📅 2023-12-04 13:18:47

Door/Knob/Lock

📍 [43.6958857, -116.4917958](#)

🖼️ [Image](#)



📅 2023-12-04 13:18:57

Doorbell

📍 [43.6958857, -116.4917958](#)

🖼️ [Image](#)




2023-12-04 13:19:16 MST  
Flooring/Baseboard

📅 2023-12-04 13:19:16

📍 [43.6957767, -116.4918157](https://www.google.com/maps?q=43.6957767,-116.4918157)

🖼️ [Image](#)



2023-12-04 13:19:31 MST  
Light Fixture/Fan

📅 2023-12-04 13:19:31

📍 [43.6957767, -116.4918157](https://www.google.com/maps?q=43.6957767,-116.4918157)

🖼️ [Image](#)



2023-12-04 13:19:45 MST  
Security/Screen Door

📅 2023-12-04 13:19:45

📍 [43.6957767, -116.4918157](https://www.google.com/maps?q=43.6957767,-116.4918157)

🖼️ [Image](#)



2023-12-04 13:19:53 MST  
Security/Screen Door

📅 2023-12-04 13:19:53

📍 [43.6957767, -116.4918157](https://www.google.com/maps?q=43.6957767,-116.4918157)

🖼️ [Image](#)



2023-12-04 13:20:02 MST  
Switch/Outlet

📅 2023-12-04 13:20:02

📍 [43.6957767, -116.4918157](https://www.google.com/maps?q=43.6957767,-116.4918157)

🖼️ [Image](#)



2023-12-04 13:20:10 MST  
Wall/Ceiling

📅 2023-12-04 13:20:10

📍 [43.6957767, -116.4918157](https://www.google.com/maps?q=43.6957767,-116.4918157)

🖼️ [Image](#)

🏠 Front Yard/Exterior

📌 CONDITION

💬 COMMENTS

Building Exterior	- - D	A solar floodlight was installed on the home.
Landscaping	- S -	

Front Yard/Exterior

CONDITION

COMMENTS

Light Fixture	- S -	
Walk/Driveway	- S -	



2023-12-04 13:20:53 MST

2023-12-04 13:20:53

43.6957767, -116.4918157

Image



2023-12-04 13:21:54 MST

Building Exterior

2023-12-04 13:21:54

43.6960777, -116.4917439

Image



2023-12-04 13:21:12 MST

Landscaping

2023-12-04 13:21:12

43.6957767, -116.4918157

Image



2023-12-04 13:21:15 MST

Landscaping

2023-12-04 13:21:15

43.6960777, -116.4917439

Image




2023-12-04 13:21:16 MST

Landscaping

2023-12-04 13:21:16

43.6960777, -116.4917439

Image



2023-12-04 13:21:25 MST

Landscaping

2023-12-04 13:21:25

43.6960777, -116.4917439

Image



**Landscaping**

📅 2023-12-04 13:21:34

📍 [43.6960777, -116.4917439](#)

🖼️ [Image](#)

**🏠 Bathroom**

**🔧 CONDITION**

**💬 COMMENTS**

<b>🏠 Bathroom</b>	<b>🔧 CONDITION</b>	<b>💬 COMMENTS</b>
Cabinet/Counter/Shelving	- S -	
Door/Knob/Lock	- - D	Black marks were observed on the door.
Exhaust Fan	- S -	
Flooring/Baseboard	- S -	
Light Fixture	- S -	
Medicine Cabinet/Mirror	- S -	
Shower Door/Rail/Curtain	- S -	
Sink/Faucet	- - D	The drain stopper is stuck down and the flange is cracked.
Switch/Outlet	- S -	
Toilet	- S -	
Toilet Paper Holder	- S -	
Towel Rack	- S -	
Tub/Shower	- - D	Chips in the tub finish were observed.
Wall/Ceiling	- S -	
Window/Lock/Screen	- S -	





2023-12-04 13:48:52 MST

📅 2023-12-04 13:48:52

📍 [43.6961222, -116.4916638](#)

🖼️ [Image](#)



2023-12-04 13:48:55 MST

📅 2023-12-04 13:48:55

📍 [43.6961222, -116.4916638](#)

🖼️ [Image](#)



2023-12-04 13:49:01 MST

Cabinet/Counter/Shelving

📅 2023-12-04 13:49:01

📍 [43.6961222, -116.4916638](#)

🖼️ [Image](#)



2023-12-04 13:49:06 MST

Cabinet/Counter/Shelving

📅 2023-12-04 13:49:06

📍 [43.6961222, -116.4916638](#)

🖼️ [Image](#)



2023-12-04 13:49:08 MST

Cabinet/Counter/Shelving

📅 2023-12-04 13:49:08

📍 [43.6961222, -116.4916638](#)

🖼️ [Image](#)



2023-12-04 13:49:11 MST

Cabinet/Counter/Shelving

📅 2023-12-04 13:49:11

📍 [43.6961222, -116.4916638](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2023-12-04 13:49:12

🔍 [43.6961222, -116.4916638](#)

🖼️ Image



Cabinet/Counter/Shelving

📅 2023-12-04 13:49:16

🔍 [43.6961222, -116.4916638](#)

🖼️ Image



Cabinet/Counter/Shelving

📅 2023-12-04 13:49:21

🔍 [43.6961222, -116.4916638](#)

🖼️ Image



Cabinet/Counter/Shelving

📅 2023-12-04 13:49:28

🔍 [43.6961222, -116.4916638](#)

🖼️ Image



Door/Knob/Lock

📅 2023-12-04 13:49:40

🔍 [43.6961222, -116.4916638](#)

🖼️ Image



Door/Knob/Lock

📅 2023-12-04 13:49:47

🔍 [43.6961222, -116.4916638](#)

🖼️ Image




Exhaust Fan

📅 2023-12-04 13:50:09

📍 [43.696067, -116.4917964](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2023-12-04 13:50:22

📍 [43.696067, -116.4917964](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2023-12-04 13:50:25

📍 [43.696067, -116.4917964](#)

🖼️ [Image](#)



Light Fixture

📅 2023-12-04 13:50:29

📍 [43.696067, -116.4917964](#)

🖼️ [Image](#)



Medicine Cabinet/Mirror

📅 2023-12-04 13:50:32

📍 [43.696067, -116.4917964](#)

🖼️ [Image](#)



Shower Door/Rail/Curtain

📅 2023-12-04 13:50:37

📍 [43.696067, -116.4917964](#)

🖼️ [Image](#)



Sink/Faucet

📅 2023-12-04 13:50:47

📍 [43.696067, -116.4917964](#)

[Image](#)



Sink/Faucet

📅 2023-12-04 13:50:50

📍 [43.696067, -116.4917964](#)

[Image](#)



Sink/Faucet

📅 2023-12-04 13:50:55

📍 [43.696067, -116.4917964](#)

[Image](#)



Switch/Outlet

📅 2023-12-04 13:51:19

📍 [43.696067, -116.4917964](#)

[Image](#)



Toilet

📅 2023-12-04 13:51:25

📍 [43.696067, -116.4917964](#)

[Image](#)



Toilet

📅 2023-12-04 13:51:29

📍 [43.696067, -116.4917964](#)

[Image](#)



**Toilet Paper Holder**

📅 2023-12-04 13:51:33

📍 [43.696067, -116.4917964](#)

🖼️ [Image](#)



**Towel Rack**

📅 2023-12-04 13:51:37

📍 [43.696067, -116.4917964](#)

🖼️ [Image](#)



**Towel Rack**

📅 2023-12-04 13:51:40

📍 [43.696067, -116.4917964](#)

🖼️ [Image](#)



**Towel Rack**

📅 2023-12-04 13:51:42

📍 [43.696067, -116.4917964](#)

🖼️ [Image](#)



**Tub/Shower**

📅 2023-12-04 13:51:47

📍 [43.696067, -116.4917964](#)

🖼️ [Image](#)



**Tub/Shower**

📅 2023-12-04 13:51:51

📍 [43.696067, -116.4917964](#)

🖼️ [Image](#)




Tub/Shower

2023-12-04 13:51:53

43.696067, -116.4917964

Image



Tub/Shower

2023-12-04 13:51:54

43.696067, -116.4917964

Image



Tub/Shower

2023-12-04 13:51:56

43.696067, -116.4917964

Image



Wall/Ceiling

2023-12-04 13:52:14

43.6961382, -116.4913452

Image



Window/Lock/Screen

2023-12-04 13:52:19

43.6961382, -116.4913452

Image

Bathroom 2

CONDITION

COMMENTS

Bathroom 2	CONDITION	COMMENTS
Cabinet/Counter/Shelving	- - D	Dirty
Door/Knob/Lock	- S -	

Bathroom 2	CONDITION	COMMENTS
Exhaust Fan	- S -	
Flooring/Baseboard	- S -	
Light Fixture	- - D	The vanity light fixture is loose.
Medicine Cabinet/Mirror	- S -	
Sink/Faucet	- S -	
Switch/Outlet	- S -	
Toilet	- S -	
Toilet Paper Holder	- S -	
Towel Rack	- S -	
Tub/Shower	- - D	Chips in the tub finish were observed.
Wall/Ceiling	- S -	
Window/Lock/Screen	- S -	



2023-12-04 13:09:59

📍 [43.6957811, -116.4918048](#)

[Image](#)



2023-12-04 13:10:02

📍 [43.6957811, -116.4918048](#)

[Image](#)



Cabinet/Counter/Shelving

2023-12-04 13:10:05

📍 [43.6957811, -116.4918048](#)

[Image](#)



Cabinet/Counter/Shelving

2023-12-04 13:10:11

📍 [43.6957811, -116.4918048](#)

[Image](#)



Cabinet/Counter/Shelving

📅 2023-12-04 13:10:16

📍 [43.6957811, -116.4918048](#)

[Image](#)



Cabinet/Counter/Shelving

📅 2023-12-04 13:10:22

📍 [43.6957811, -116.4918048](#)

[Image](#)



Cabinet/Counter/Shelving

📅 2023-12-04 13:10:25

📍 [43.6957811, -116.4918048](#)

[Image](#)



Cabinet/Counter/Shelving

📅 2023-12-04 13:10:30

📍 [43.6957811, -116.4918048](#)

[Image](#)



Cabinet/Counter/Shelving

📅 2023-12-04 13:10:33

📍 [43.6957811, -116.4918048](#)

[Image](#)



Cabinet/Counter/Shelving

📅 2023-12-04 13:10:35

📍 [43.6957811, -116.4918048](#)

[Image](#)





Cabinet/Counter/Shelving

📅 2023-12-04 13:10:39

📍 [43.6959521, -116.49177](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2023-12-04 13:10:46

📍 [43.6959521, -116.49177](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2023-12-04 13:10:59

📍 [43.6959521, -116.49177](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2023-12-04 13:11:03

📍 [43.6959521, -116.49177](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2023-12-04 13:11:13

📍 [43.6959521, -116.49177](#)

🖼️ [Image](#)



Exhaust Fan

📅 2023-12-04 13:11:21

📍 [43.6959521, -116.49177](#)

🖼️ [Image](#)




**Flooring/Baseboard**

📅 2023-12-04 13:11:28

📍 [43.6959521, -116.49177](#)

🖼️ [Image](#)



**Flooring/Baseboard**

📅 2023-12-04 13:11:32

📍 [43.6959521, -116.49177](#)

🖼️ [Image](#)



**Light Fixture**

📅 2023-12-04 13:11:38

📍 [43.6959521, -116.49177](#)

🖼️ [Image](#)



**Medicine Cabinet/Mirror**

📅 2023-12-04 13:11:57

📍 [43.6959521, -116.49177](#)

🖼️ [Image](#)



**Sink/Faucet**

📅 2023-12-04 13:12:06

📍 [43.6959521, -116.49177](#)

🖼️ [Image](#)



**Switch/Outlet**

📅 2023-12-04 13:12:12

📍 [43.6959521, -116.49177](#)

🖼️ [Image](#)



**Toilet**

📅 2023-12-04 13:12:17

📍 [43.6959521, -116.49177](https://www.google.com/maps?q=43.6959521,-116.49177)

🖼️ [Image](#)



**Toilet**

📅 2023-12-04 13:12:25

📍 [43.6959521, -116.49177](https://www.google.com/maps?q=43.6959521,-116.49177)

🖼️ [Image](#)




**Toilet Paper Holder**

📅 2023-12-04 13:12:29

📍 [43.6959521, -116.49177](https://www.google.com/maps?q=43.6959521,-116.49177)

🖼️ [Image](#)



**Towel Rack**

📅 2023-12-04 13:12:34

📍 [43.6959521, -116.49177](https://www.google.com/maps?q=43.6959521,-116.49177)

🖼️ [Image](#)




**Towel Rack**

📅 2023-12-04 13:12:36

📍 [43.6959521, -116.49177](https://www.google.com/maps?q=43.6959521,-116.49177)

🖼️ [Image](#)



**Tub/Shower**

📅 2023-12-04 13:12:40

📍 [43.6959521, -116.49177](https://www.google.com/maps?q=43.6959521,-116.49177)

🖼️ [Image](#)



2023-12-04 13:12:44 MST

Tub/Shower

📅 2023-12-04 13:12:44

📍 [43.6959521, -116.49177](#)

🖼️ [Image](#)




2023-12-04 13:12:51 MST

Tub/Shower

📅 2023-12-04 13:12:51

📍 [43.6959521, -116.49177](#)

🖼️ [Image](#)




2023-12-04 13:13:13 MST

Wall/Ceiling

📅 2023-12-04 13:13:13

📍 [43.6959006, -116.4917711](#)

🖼️ [Image](#)



2023-12-04 13:13:15 MST

Wall/Ceiling

📅 2023-12-04 13:13:15

📍 [43.6959006, -116.4917711](#)

🖼️ [Image](#)



2023-12-04 13:13:19 MST

Window/Lock/Screen

📅 2023-12-04 13:13:19

📍 [43.6959006, -116.4917711](#)

🖼️ [Image](#)

🏠 Bedroom

🔒 CONDITION

💬 COMMENTS

🏠 Bedroom	🔒 CONDITION	💬 COMMENTS
Closet/Door/Track/Shelving	- S -	
Door/Knob/Lock	- S -	

**Bedroom**

**CONDITION**

**COMMENTS**

Bedroom	CONDITION	COMMENTS
Flooring/Baseboard	- S -	
Light Fixture/Fan	- S -	
Smoke / CO detector	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- - D	Photo hooks were observed on the walls.
Window Covering	- S -	
Window/Lock/Screen	- S -	



2023-12-04 13:44:23 MST  
 2023-12-04 13:44:23  
[43.6961764, -116.4917787](#)  
 Image



2023-12-04 13:44:28 MST  
 2023-12-04 13:44:28  
[43.6961764, -116.4917787](#)  
 Image



2023-12-04 13:44:34 MST  
 2023-12-04 13:44:34  
[43.6961764, -116.4917787](#)  
 Image



2023-12-04 13:44:40 MST  
 2023-12-04 13:44:40  
[43.6961764, -116.4917787](#)  
 Image



Closet/Door/Track/Shelving

📅 2023-12-04 13:44:48

📍 [43.6961764, -116.4917787](#)

🖼️ [Image](#)



Closet/Door/Track/Shelving

📅 2023-12-04 13:44:52

📍 [43.6961764, -116.4917787](#)

🖼️ [Image](#)



Closet/Door/Track/Shelving

📅 2023-12-04 13:44:54

📍 [43.6961764, -116.4917787](#)

🖼️ [Image](#)



Closet/Door/Track/Shelving

📅 2023-12-04 13:44:56

📍 [43.6961764, -116.4917787](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2023-12-04 13:45:50

📍 [43.6957462, -116.4917717](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2023-12-04 13:45:55

📍 [43.6957462, -116.4917717](#)

🖼️ [Image](#)



**Flooring/Baseboard**

📅 2023-12-04 13:46:00

📍 [43.6957462, -116.4917717](#)

🖼️ [Image](#)



**Flooring/Baseboard**

📅 2023-12-04 13:46:03

📍 [43.6957462, -116.4917717](#)

🖼️ [Image](#)



**Flooring/Baseboard**

📅 2023-12-04 13:46:06

📍 [43.6957462, -116.4917717](#)

🖼️ [Image](#)



**Flooring/Baseboard**

📅 2023-12-04 13:46:09

📍 [43.6957462, -116.4917717](#)

🖼️ [Image](#)



**Light Fixture/Fan**

📅 2023-12-04 13:46:14

📍 [43.6957462, -116.4917717](#)

🖼️ [Image](#)



**Smoke / CO detector**

📅 2023-12-04 13:46:19

📍 [43.6957462, -116.4917717](#)

🖼️ [Image](#)



Switch/Outlet

📅 2023-12-04 13:46:23

🔍 [43.6957462, -116.4917717](https://www.google.com/maps/@43.6957462,-116.4917717)

🖼️ Image



Wall/Ceiling

📅 2023-12-04 13:46:32

🔍 [43.6957462, -116.4917717](https://www.google.com/maps/@43.6957462,-116.4917717)

🖼️ Image



Wall/Ceiling

📅 2023-12-04 13:46:33

🔍 [43.6957462, -116.4917717](https://www.google.com/maps/@43.6957462,-116.4917717)

🖼️ Image



Wall/Ceiling

📅 2023-12-04 13:46:35

🔍 [43.6957462, -116.4917717](https://www.google.com/maps/@43.6957462,-116.4917717)

🖼️ Image



Wall/Ceiling

📅 2023-12-04 13:46:39

🔍 [43.6957462, -116.4917717](https://www.google.com/maps/@43.6957462,-116.4917717)

🖼️ Image



Wall/Ceiling

📅 2023-12-04 13:46:42

🔍 [43.6957462, -116.4917717](https://www.google.com/maps/@43.6957462,-116.4917717)

🖼️ Image






Wall/Ceiling

📅 2023-12-04 13:46:44

🔍 [43.6957462, -116.4917717](#)

🖼️ Image



Wall/Ceiling

📅 2023-12-04 13:46:46

🔍 [43.6957462, -116.4917717](#)

🖼️ Image



Wall/Ceiling

📅 2023-12-04 13:46:50

🔍 [43.6957462, -116.4917717](#)

🖼️ Image



Window Covering

📅 2023-12-04 13:47:05

🔍 [43.6957462, -116.4917717](#)

🖼️ Image



Window/Lock/Screen

📅 2023-12-04 13:47:16

🔍 [43.6957462, -116.4917717](#)

🖼️ Image

📖 Bedroom 2

📌 CONDITION

💬 COMMENTS

📖 Bedroom 2	📌 CONDITION	💬 COMMENTS
Closet/Door/Track/Shelving	- - D	The closet door guide is broken and non-functioning.
Door/Knob/Lock	- S -	

📖 Bedroom 2

📌 CONDITION

💬 COMMENTS

	📌 CONDITION	💬 COMMENTS
Flooring/Baseboard	- S -	
Light Fixture/Fan	- S -	
Smoke / CO detector	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- - D	Black marks and holes were observed on the walls.
Window Covering	- - D	A warped blind valance was observed.
Window/Lock/Screen	- S -	



Closet/Door/Track/Shelving

📅 2023-12-04 13:14:10

📍 [43.6959006, -116.4917711](https://www.google.com/maps?q=43.6959006,-116.4917711)

🖼️ Image



Closet/Door/Track/Shelving

📅 2023-12-04 13:14:18

📍 [43.6959006, -116.4917711](https://www.google.com/maps?q=43.6959006,-116.4917711)

🖼️ Image



Door/Knob/Lock

📅 2023-12-04 13:14:45

📍 [43.6959006, -116.4917711](https://www.google.com/maps?q=43.6959006,-116.4917711)

🖼️ Image



Door/Knob/Lock

📅 2023-12-04 13:14:56

📍 [43.6959006, -116.4917711](https://www.google.com/maps?q=43.6959006,-116.4917711)

🖼️ Image



**Flooring/Baseboard**  
📅 2023-12-04 13:15:17  
🔍 [43.6960637, -116.491778](https://www.google.com/maps?q=43.6960637,-116.491778)  
🖼️ [Image](#)



**Flooring/Baseboard**  
📅 2023-12-04 13:15:19  
🔍 [43.6960637, -116.491778](https://www.google.com/maps?q=43.6960637,-116.491778)  
🖼️ [Image](#)



**Flooring/Baseboard**  
📅 2023-12-04 13:15:21  
🔍 [43.6960637, -116.491778](https://www.google.com/maps?q=43.6960637,-116.491778)  
🖼️ [Image](#)



**Flooring/Baseboard**  
📅 2023-12-04 13:15:23  
🔍 [43.6960637, -116.491778](https://www.google.com/maps?q=43.6960637,-116.491778)  
🖼️ [Image](#)



**Light Fixture/Fan**  
📅 2023-12-04 13:15:27  
🔍 [43.6960637, -116.491778](https://www.google.com/maps?q=43.6960637,-116.491778)  
🖼️ [Image](#)



**Smoke / CO detector**  
📅 2023-12-04 13:15:33  
🔍 [43.6960637, -116.491778](https://www.google.com/maps?q=43.6960637,-116.491778)  
🖼️ [Image](#)



Switch/Outlet

📅 2023-12-04 13:15:43

📍 [43.6960637, -116.491778](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2023-12-04 13:15:48

📍 [43.6960637, -116.491778](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2023-12-04 13:15:50

📍 [43.6960637, -116.491778](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2023-12-04 13:15:53

📍 [43.6960637, -116.491778](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2023-12-04 13:15:56

📍 [43.6960637, -116.491778](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2023-12-04 13:16:01

📍 [43.6960637, -116.491778](#)

🖼️ [Image](#)



2023-12-04 13:16:06 MST

Wall/Ceiling

📅 2023-12-04 13:16:06

📍 [43.6960637, -116.491778](#)

🖼️ [Image](#)



2023-12-04 13:16:08 MST

Wall/Ceiling

📅 2023-12-04 13:16:08

📍 [43.6960637, -116.491778](#)

🖼️ [Image](#)



2023-12-04 13:16:25 MST

Window Covering

📅 2023-12-04 13:16:25

📍 [43.6960637, -116.491778](#)

🖼️ [Image](#)



2023-12-04 13:16:31 MST

Window Covering

📅 2023-12-04 13:16:31

📍 [43.6960637, -116.491778](#)

🖼️ [Image](#)



2023-12-04 13:17:26 MST

Window/Lock/Screen

📅 2023-12-04 13:17:26

📍 [43.6958857, -116.4917958](#)

🖼️ [Image](#)

📖 Bedroom 3

🔗 CONDITION

💬 COMMENTS

📖 Bedroom 3	🔗 CONDITION	💬 COMMENTS
Closet/Door/Track/Shelving	- - D	Chipped paint was observed on the door.
Door/Knob/Lock	- S -	

**Bedroom 3**

**CONDITION**

**COMMENTS**

	CONDITION	COMMENTS
Flooring/Baseboard	- - D	Pink tape was observed on the baseboard.
Light Fixture/Fan	- - D	Burnt-out lightbulbs were observed.
Smoke / CO detector	- S -	
Switch/Outlet	- - D	The phone jack is not mounted to the wall.
Wall/Ceiling	- S -	
Window Covering	- S -	
Window/Lock/Screen	- S -	



2023-12-04 13:02:16 MST  
 2023-12-04 13:02:16  
[43.6962153, -116.491404](#)  
[Image](#)




2023-12-04 13:02:23 MST  
 2023-12-04 13:02:23  
[43.6962153, -116.491404](#)  
[Image](#)



2023-12-04 13:02:29 MST  
 2023-12-04 13:02:29  
[43.6962153, -116.491404](#)  
[Image](#)



2023-12-04 13:02:35 MST  
 2023-12-04 13:02:35  
[43.6962153, -116.491404](#)  
[Image](#)



2023-12-04 13:03:28 MST  
Closet/Door/Track/Shelving

📅 2023-12-04 13:03:28

📍 [43.6962153, -116.491404](#)

🖼️ [Image](#)



2023-12-04 13:03:32 MST  
Closet/Door/Track/Shelving

📅 2023-12-04 13:03:32

📍 [43.6962153, -116.491404](#)

🖼️ [Image](#)



2023-12-04 13:04:55 MST  
Closet/Door/Track/Shelving

📅 2023-12-04 13:04:55

📍 [43.695974, -116.4918027](#)

🖼️ [Image](#)



2023-12-04 13:05:09 MST  
Door/Knob/Lock

📅 2023-12-04 13:05:09

📍 [43.695974, -116.4918027](#)

🖼️ [Image](#)



2023-12-04 13:05:20 MST  
Door/Knob/Lock

📅 2023-12-04 13:05:20

📍 [43.695974, -116.4918027](#)

🖼️ [Image](#)



2023-12-04 13:05:29 MST  
Flooring/Baseboard

📅 2023-12-04 13:05:29

📍 [43.695974, -116.4918027](#)

🖼️ [Image](#)



**Flooring/Baseboard**  
📅 2023-12-04 13:05:31  
📍 [43.695974, -116.4918027](#)  
🖼️ [Image](#)



**Flooring/Baseboard**  
📅 2023-12-04 13:05:34  
📍 [43.695974, -116.4918027](#)  
🖼️ [Image](#)



**Flooring/Baseboard**  
📅 2023-12-04 13:05:36  
📍 [43.695974, -116.4918027](#)  
🖼️ [Image](#)



**Flooring/Baseboard**  
📅 2023-12-04 13:05:40  
📍 [43.695974, -116.4918027](#)  
🖼️ [Image](#)



**Light Fixture/Fan**  
📅 2023-12-04 13:06:16  
📍 [43.6959292, -116.4917973](#)  
🖼️ [Image](#)



**Light Fixture/Fan**  
📅 2023-12-04 13:06:24  
📍 [43.6959292, -116.4917973](#)  
🖼️ [Image](#)






Smoke / CO detector

📅 2023-12-04 13:06:36

📍 [43.6959292, -116.4917973](#)

🖼️ [Image](#)




Switch/Outlet

📅 2023-12-04 13:06:41

📍 [43.6959292, -116.4917973](#)

🖼️ [Image](#)



Switch/Outlet

📅 2023-12-04 13:07:01

📍 [43.6959292, -116.4917973](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2023-12-04 13:06:48

📍 [43.6959292, -116.4917973](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2023-12-04 13:06:49

📍 [43.6959292, -116.4917973](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2023-12-04 13:06:54

📍 [43.6959292, -116.4917973](#)

🖼️ [Image](#)



2023-12-04 13:07:35 MST

Window Covering

📅 2023-12-04 13:07:35

📍 [43.6959292, -116.4917973](#)

🖼️ [Image](#)



2023-12-04 13:07:21 MST

Window/Lock/Screen

📅 2023-12-04 13:07:21

📍 [43.6959292, -116.4917973](#)

🖼️ [Image](#)

📖 Dining Room	📌 CONDITION	💬 COMMENTS
Flooring/Baseboard	- - D	The flooring is showing signs of wear.
Light Fixture/Fan	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- - D	Mismatched paint was observed on the walls.
Window Covering	- S -	
Window/Lock/Screen	- S -	




2023-12-04 13:29:18 MST

📅 2023-12-04 13:29:18

📍 [43.6963165, -116.4918275](#)

🖼️ [Image](#)



2023-12-04 13:29:23 MST

Flooring/Baseboard

📅 2023-12-04 13:29:23

📍 [43.6963165, -116.4918275](#)

🖼️ [Image](#)



**Flooring/Baseboard**

📅 2023-12-04 13:29:24

📍 [43.6963165, -116.4918275](#)

🖼️ [Image](#)



**Flooring/Baseboard**

📅 2023-12-04 13:29:26

📍 [43.6963165, -116.4918275](#)

🖼️ [Image](#)



**Light Fixture/Fan**

📅 2023-12-04 13:30:01

📍 [43.6963165, -116.4918275](#)

🖼️ [Image](#)



**Switch/Outlet**

📅 2023-12-04 13:30:07

📍 [43.6963165, -116.4918275](#)

🖼️ [Image](#)



**Wall/Ceiling**

📅 2023-12-04 13:30:13

📍 [43.6963165, -116.4918275](#)

🖼️ [Image](#)



**Wall/Ceiling**

📅 2023-12-04 13:30:16

📍 [43.6963165, -116.4918275](#)

🖼️ [Image](#)




Wall/Ceiling

📅 2023-12-04 13:30:20

📍 [43.6963165, -116.4918275](https://www.google.com/maps/@43.6963165,-116.4918275)

🖼️ [Image](#)




Wall/Ceiling

📅 2023-12-04 13:30:23

📍 [43.6963165, -116.4918275](https://www.google.com/maps/@43.6963165,-116.4918275)

🖼️ [Image](#)




Window Covering

📅 2023-12-04 13:30:33

📍 [43.6963165, -116.4918275](https://www.google.com/maps/@43.6963165,-116.4918275)

🖼️ [Image](#)



Window/Lock/Screen

📅 2023-12-04 13:30:57

📍 [43.6963165, -116.4918275](https://www.google.com/maps/@43.6963165,-116.4918275)

🖼️ [Image](#)

📖 Hallway/Stairs	📌 CONDITION	💬 COMMENTS
Closet/Cabinet	- - D	The bathroom towel rack is being stored in the closet.
Flooring/Baseboard	- - D	A gap in the baseboard was observed.
Light Fixture	- S -	
Smoke/CO Detector	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- - D	Mismatched paint was observed on the walls.



2023-12-04 13:08:15 MST

📅 2023-12-04 13:08:15

📍 [43.6959292, -116.4917973](#)

🖼️ [Image](#)



2023-12-04 13:08:22 MST

**Closet/Cabinet**

📅 2023-12-04 13:08:22

📍 [43.6959292, -116.4917973](#)

🖼️ [Image](#)



2023-12-04 13:08:31 MST

**Closet/Cabinet**

📅 2023-12-04 13:08:31

📍 [43.6957811, -116.4918048](#)

🖼️ [Image](#)



2023-12-04 13:08:36 MST

**Closet/Cabinet**

📅 2023-12-04 13:08:36

📍 [43.6957811, -116.4918048](#)

🖼️ [Image](#)



2023-12-04 13:08:59 MST

**Flooring/Baseboard**

📅 2023-12-04 13:08:59

📍 [43.6957811, -116.4918048](#)

🖼️ [Image](#)




2023-12-04 13:18:09 MST

**Flooring/Baseboard**

📅 2023-12-04 13:18:09

📍 [43.6958857, -116.4917958](#)

🖼️ [Image](#)



2023-12-04 13:09:02 MST  
Light Fixture

📅 2023-12-04 13:09:02

📍 [43.6957811, -116.4918048](#)

🖼️ [Image](#)



2023-12-04 13:09:12 MST  
Smoke/CO Detector

📅 2023-12-04 13:09:12

📍 [43.6957811, -116.4918048](#)

🖼️ [Image](#)



2023-12-04 13:09:15 MST  
Smoke/CO Detector

📅 2023-12-04 13:09:15

📍 [43.6957811, -116.4918048](#)

🖼️ [Image](#)



2023-12-04 13:09:19 MST  
Switch/Outlet

📅 2023-12-04 13:09:19

📍 [43.6957811, -116.4918048](#)

🖼️ [Image](#)



2023-12-04 13:09:36 MST  
Wall/Ceiling

📅 2023-12-04 13:09:36

📍 [43.6957811, -116.4918048](#)

🖼️ [Image](#)



2023-12-04 13:09:38 MST  
Wall/Ceiling

📅 2023-12-04 13:09:38

📍 [43.6957811, -116.4918048](#)




🖼️ [Image](#)

📖 Kitchen

📌 CONDITION


💬 COMMENTS

📖 Kitchen	📌 CONDITION	💬 COMMENTS
Cabinets/Drawers	- S -	
Counter	- - D	A burn on the countertop was observed.

 Kitchen	 CONDITION	 COMMENTS
Dishwasher	- - D	Dirty
Faucet/Plumbing	- S -	
Flooring/Baseboard	- - D	The floor is showing signs of wear.
Light Fixture	- S -	
Oven	- S -	
Pantry / Shelves	- S -	
Range/Fan/Hood/Filter	- S -	
Refrigerator	- S -	
Sink/Disposal	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- - D	Unpainted patches and mismatched paint were observed on the walls.



2023-12-04 13:38:29 MST

 2023-12-04 13:38:29


 [43.6959453, -116.4916455](https://www.google.com/maps/@43.6959453,-116.4916455)

 Image



2023-12-04 13:38:40 MST

Cabinets/Drawers

 2023-12-04 13:38:40


 [43.6959453, -116.4916455](https://www.google.com/maps/@43.6959453,-116.4916455)


 Image



2023-12-04 13:38:46 MST

Cabinets/Drawers

 2023-12-04 13:38:46


 [43.6959453, -116.4916455](https://www.google.com/maps/@43.6959453,-116.4916455)


 Image



2023-12-04 13:38:55 MST

Cabinets/Drawers

 2023-12-04 13:38:55

 [43.6959453, -116.4916455](https://www.google.com/maps/@43.6959453,-116.4916455)

 Image



Cabinets/Drawers

📅 2023-12-04 13:39:01

📍 [43.6959453, -116.4916455](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2023-12-04 13:39:07

📍 [43.6959453, -116.4916455](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2023-12-04 13:39:11

📍 [43.6959453, -116.4916455](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2023-12-04 13:39:17

📍 [43.6961348, -116.491644](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2023-12-04 13:39:22

📍 [43.6961348, -116.491644](#)

🖼️ [Image](#)



Counter

📅 2023-12-04 13:39:26

📍 [43.6961348, -116.491644](#)

🖼️ [Image](#)





Counter

📅 2023-12-04 13:39:28

📍 [43.6961348, -116.491644](#)

🖼️ [Image](#)



Counter

📅 2023-12-04 13:39:30

📍 [43.6961348, -116.491644](#)

🖼️ [Image](#)



Counter

📅 2023-12-04 13:39:31

📍 [43.6961348, -116.491644](#)

🖼️ [Image](#)



Counter

📅 2023-12-04 13:39:33

📍 [43.6961348, -116.491644](#)

🖼️ [Image](#)



Counter

📅 2023-12-04 13:39:35

📍 [43.6961348, -116.491644](#)

🖼️ [Image](#)



Counter

📅 2023-12-04 13:39:53

📍 [43.6961348, -116.491644](#)

🖼️ [Image](#)



Dishwasher

📅 2023-12-04 13:40:12

📍 [43.6961348, -116.491644](#)

🖼️ [Image](#)



Dishwasher

📅 2023-12-04 13:40:27

📍 [43.6961348, -116.491644](#)

🖼️ [Image](#)



Dishwasher

📅 2023-12-04 13:40:32

📍 [43.6961348, -116.491644](#)

🖼️ [Image](#)



Faucet/Plumbing

📅 2023-12-04 13:40:43

📍 [43.6961348, -116.491644](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2023-12-04 13:40:59

📍 [43.6961348, -116.491644](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2023-12-04 13:41:02

📍 [43.6961348, -116.491644](#)

🖼️ [Image](#)



**Light Fixture**

📅 2023-12-04 13:41:16

📍 [43.6961078, -116.4918229](#)

🖼️ [Image](#)



**Oven**

📅 2023-12-04 13:41:24

📍 [43.6961078, -116.4918229](#)

🖼️ [Image](#)



**Oven**

📅 2023-12-04 13:41:28

📍 [43.6961078, -116.4918229](#)

🖼️ [Image](#)



**Oven**

📅 2023-12-04 13:41:30

📍 [43.6961078, -116.4918229](#)

🖼️ [Image](#)



**Pantry / Shelves**

📅 2023-12-04 13:41:36

📍 [43.6961078, -116.4918229](#)

🖼️ [Image](#)



**Pantry / Shelves**

📅 2023-12-04 13:41:43

📍 [43.6961078, -116.4918229](#)

🖼️ [Image](#)



Pantry / Shelves

📅 2023-12-04 13:41:46

📍 [43.6961078, -116.4918229](#)

🖼️ [Image](#)



Pantry / Shelves

📅 2023-12-04 13:41:49

📍 [43.6961078, -116.4918229](#)

🖼️ [Image](#)



Pantry / Shelves

📅 2023-12-04 13:41:51

📍 [43.6961078, -116.4918229](#)

🖼️ [Image](#)



Range/Fan/Hood/Filter

📅 2023-12-04 13:42:15

📍 [43.6961078, -116.4918229](#)

🖼️ [Image](#)



Range/Fan/Hood/Filter

📅 2023-12-04 13:42:21

📍 [43.6961078, -116.4918229](#)

🖼️ [Image](#)



Refrigerator

📅 2023-12-04 13:42:28

📍 [43.6961078, -116.4918229](#)

🖼️ [Image](#)



Refrigerator

📅 2023-12-04 13:42:34

📍 [43.6961078, -116.4918229](#)

🖼️ [Image](#)



Refrigerator

📅 2023-12-04 13:42:35

📍 [43.6961078, -116.4918229](#)

🖼️ [Image](#)



Refrigerator

📅 2023-12-04 13:42:43

📍 [43.6961078, -116.4918229](#)

🖼️ [Image](#)



Refrigerator

📅 2023-12-04 13:42:44

📍 [43.6961078, -116.4918229](#)

🖼️ [Image](#)



Sink/Disposal

📅 2023-12-04 13:42:50

📍 [43.6961078, -116.4918229](#)

🖼️ [Image](#)



Switch/Outlet

📅 2023-12-04 13:42:55

📍 [43.6961078, -116.4918229](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2023-12-04 13:43:02

📍 [43.6961078, -116.4918229](https://www.google.com/maps?q=43.6961078,-116.4918229)

🖼️ [Image](#)



Wall/Ceiling

📅 2023-12-04 13:43:07

📍 [43.6961078, -116.4918229](https://www.google.com/maps?q=43.6961078,-116.4918229)

🖼️ [Image](#)



Wall/Ceiling

📅 2023-12-04 13:43:09

📍 [43.6961078, -116.4918229](https://www.google.com/maps?q=43.6961078,-116.4918229)

🖼️ [Image](#)

📖 Laundry Room	📍 CONDITION	💬 COMMENTS
Cabinet/Counter/Shelving	- - D	A stain was observed on the countertop.
Door/Knob/Lock	- S -	
Faucet/Valve	- S -	
Flooring/Baseboard	- - D	A tear in the vinyl flooring was observed.
Light Fixture/Fan	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- - D	Unpainted patches and mismatched paint were observed on the walls.



📅 2023-12-04 13:34:18

📍 [43.6962097, -116.4915961](#)

🖼️ [Image](#)



📅 2023-12-04 13:34:24

📍 [43.6962097, -116.4915961](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2023-12-04 13:34:29

📍 [43.6962097, -116.4915961](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2023-12-04 13:34:32

📍 [43.6962097, -116.4915961](#)

🖼️ [Image](#)




Cabinet/Counter/Shelving

📅 2023-12-04 13:34:39

📍 [43.6962097, -116.4915961](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2023-12-04 13:34:59

📍 [43.6962097, -116.4915961](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2023-12-04 13:35:05

📍 [43.6962097, -116.4915961](#)

🖼️ [Image](#)



Faucet/Valve

📅 2023-12-04 13:35:10

📍 [43.6962097, -116.4915961](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2023-12-04 13:35:15

📍 [43.6961592, -116.4914934](#)

🖼️ [Image](#)




Flooring/Baseboard

📅 2023-12-04 13:35:18

📍 [43.6961592, -116.4914934](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2023-12-04 13:35:22

📍 [43.6961592, -116.4914934](#)

🖼️ [Image](#)



Light Fixture/Fan

📅 2023-12-04 13:35:37

📍 [43.6961592, -116.4914934](#)

🖼️ [Image](#)





Switch/Outlet

📅 2023-12-04 13:35:42

📍 [43.6961592, -116.4914934](#)

[Image](#)



Wall/Ceiling

📅 2023-12-04 13:35:47

📍 [43.6961592, -116.4914934](#)

[Image](#)



Wall/Ceiling

📅 2023-12-04 13:35:48

📍 [43.6961592, -116.4914934](#)

[Image](#)



Wall/Ceiling

📅 2023-12-04 13:35:51

📍 [43.6961592, -116.4914934](#)

[Image](#)




Wall/Ceiling

📅 2023-12-04 13:35:55

📍 [43.6961592, -116.4914934](#)

[Image](#)



Wall/Ceiling

📅 2023-12-04 13:35:56

📍 [43.6961592, -116.4914934](#)

[Image](#)



Wall/Ceiling

2023-12-04 13:35:57

43.6961592, -116.4914934

Image

**Living Room**

**CONDITION**

**COMMENTS**

	CONDITION	COMMENTS
Fireplace Equipment	- S -	
Flooring/Baseboard	- S -	
Light Fixture/Fan	- - D	Burnt-out lightbulbs were observed.
Smoke/CO Detector	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	Mismatched paint on walls, TV mount on wall and no brackets left behind
Window Covering	- - D	A mismatched blind slat was observed.
Window/Lock/Screen	- S -	



2023-12-04 13:22:58

43.6960777, -116.4917439

Image



Fireplace Equipment

2023-12-04 13:23:20

43.6961446, -116.4916476

Image



Fireplace Equipment

📅 2023-12-04 13:23:23

📍 [43.6961446, -116.4916476](#)

🖼️ [Image](#)



Fireplace Equipment

📅 2023-12-04 13:23:26

📍 [43.6961446, -116.4916476](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2023-12-04 13:23:52

📍 [43.6961446, -116.4916476](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2023-12-04 13:23:54

📍 [43.6961446, -116.4916476](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2023-12-04 13:23:55

📍 [43.6961446, -116.4916476](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2023-12-04 13:23:57

📍 [43.6961446, -116.4916476](#)

🖼️ [Image](#)



**Flooring/Baseboard**

📅 2023-12-04 13:23:59

📍 [43.6961446, -116.4916476](#)

🖼️ [Image](#)



**Flooring/Baseboard**

📅 2023-12-04 13:24:00

📍 [43.6961446, -116.4916476](#)

🖼️ [Image](#)



**Flooring/Baseboard**

📅 2023-12-04 13:24:01

📍 [43.6961446, -116.4916476](#)

🖼️ [Image](#)




**Light Fixture/Fan**

📅 2023-12-04 13:24:09

📍 [43.6961446, -116.4916476](#)

🖼️ [Image](#)



**Smoke/CO Detector**

📅 2023-12-04 13:24:23

📍 [43.6961446, -116.4916476](#)

🖼️ [Image](#)



**Switch/Outlet**

📅 2023-12-04 13:24:29

📍 [43.6961446, -116.4916476](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2023-12-04 13:24:33

🔍 [43.6961446, -116.4916476](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2023-12-04 13:24:37

🔍 [43.6961446, -116.4916476](#)

🖼️ [Image](#)




Wall/Ceiling

📅 2023-12-04 13:24:40

🔍 [43.6961446, -116.4916476](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2023-12-04 13:24:47

🔍 [43.6961446, -116.4916476](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2023-12-04 13:24:48

🔍 [43.6961446, -116.4916476](#)

🖼️ [Image](#)



Window Covering

📅 2023-12-04 13:25:36

🔍 [43.696007, -116.4917279](#)

🖼️ [Image](#)



Window Covering

📅 2023-12-04 13:25:43

📍 [43.696007, -116.4917279](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2023-12-04 13:25:22

📍 [43.696007, -116.4917279](#)


🖼️ [Image](#)

📁 Personal Property

🔒 CONDITION

💬 COMMENTS

Other	- S -	
-------	-------	--




📅 2023-12-04 13:37:37 MST

📅 2023-12-04 13:37:37

📍 [43.6959453, -116.4916455](#)

🖼️ [Image](#)




📅 2023-12-04 13:37:40 MST

📅 2023-12-04 13:37:40

📍 [43.6959453, -116.4916455](#)

🖼️ [Image](#)



📅 2023-12-04 13:37:43 MST

📅 2023-12-04 13:37:43

📍 [43.6959453, -116.4916455](#)

🖼️ [Image](#)

📁 Back Yard/Exterior

🔒 CONDITION

💬 COMMENTS

Building Exterior	- - D	Damage to the siding was observed.
-------------------	-------	------------------------------------

Back Yard/Exterior

CONDITION

COMMENTS

Fence/Gate	- S -	
Landscaping	- - D	Personal property left behind



2023-12-04 13:26:44 MST

2023-12-04 13:26:44

43.696007, -116.4917279

Image



2023-12-04 13:26:46 MST

2023-12-04 13:26:46

43.696007, -116.4917279

Image



2023-12-04 13:26:57 MST

Building Exterior

2023-12-04 13:26:57

43.696007, -116.4917279

Image



2023-12-04 13:27:17 MST

Fence/Gate

2023-12-04 13:27:17

43.6960782, -116.4913902

Image



2023-12-04 13:27:37 MST

Landscaping

2023-12-04 13:27:37

43.6960782, -116.4913902

Image



2023-12-04 13:27:42 MST

Landscaping

2023-12-04 13:27:42

43.6960782, -116.4913902

Image



Landscaping

📅 2023-12-04 13:27:46

📍 [43.6960782, -116.4913902](#)

🖼️ [Image](#)



Landscaping

📅 2023-12-04 13:27:49

📍 [43.6960782, -116.4913902](#)

🖼️ [Image](#)

📁 Garage/Parking

📌 CONDITION

💬 COMMENTS

📁 Garage/Parking	📌 CONDITION	💬 COMMENTS
Cabinet/Counter	- - D	Dirty + The bottom of a drawer was missing and broken.
Driveway/Floor	- - D	Dirty
Garage Door	- S -	
Light Fixture	- S -	
Other Door/Knob/Lock	- - D	A gap was observed in the exterior garage door.
Switch/Outlet	- S -	



2023-12-04 13:31:52 MST

📅 2023-12-04 13:31:52

📍 [43.696205, -116.4917449](#)

🖼️ [Image](#)



2023-12-04 13:32:00 MST

📅 2023-12-04 13:32:00

📍 [43.696205, -116.4917449](#)

🖼️ [Image](#)





2023-12-04 13:32:06 MST

Cabinet/Counter

📅 2023-12-04 13:32:06

📍 [43.696205, -116.4917449](#)

🖼️ [Image](#)



2023-12-04 13:32:10 MST

Cabinet/Counter

📅 2023-12-04 13:32:10

📍 [43.696205, -116.4917449](#)

🖼️ [Image](#)



2023-12-04 13:32:11 MST

Cabinet/Counter

📅 2023-12-04 13:32:11

📍 [43.696205, -116.4917449](#)

🖼️ [Image](#)



2023-12-04 13:32:21 MST

Cabinet/Counter

📅 2023-12-04 13:32:21

📍 [43.696205, -116.4917449](#)

🖼️ [Image](#)



2023-12-04 13:32:26 MST

Cabinet/Counter

📅 2023-12-04 13:32:26

📍 [43.696205, -116.4917449](#)

🖼️ [Image](#)



2023-12-04 13:32:41 MST

Driveway/Floor

📅 2023-12-04 13:32:41

📍 [43.696205, -116.4917449](#)

🖼️ [Image](#)



2023-12-04 13:32:45 MST

Driveway/Floor

📅 2023-12-04 13:32:45

📍 [43.696205, -116.4917449](#)

🖼️ [Image](#)



2023-12-04 13:32:50 MST

Driveway/Floor

📅 2023-12-04 13:32:50

📍 [43.696205, -116.4917449](#)

🖼️ [Image](#)




2023-12-04 13:32:52 MST

Driveway/Floor

📅 2023-12-04 13:32:52

📍 [43.696205, -116.4917449](#)

🖼️ [Image](#)



2023-12-04 13:32:56 MST

Driveway/Floor

📅 2023-12-04 13:32:56

📍 [43.696205, -116.4917449](#)

🖼️ [Image](#)



2023-12-04 13:33:05 MST

Garage Door

📅 2023-12-04 13:33:05

📍 [43.696205, -116.4917449](#)

🖼️ [Image](#)




2023-12-04 13:33:09 MST

Light Fixture

📅 2023-12-04 13:33:09

📍 [43.696205, -116.4917449](#)

🖼️ [Image](#)




2023-12-04 13:33:12 MST

Light Fixture

📅 2023-12-04 13:33:12

📍 [43.696205, -116.4917449](#)

🖼️ [Image](#)




2023-12-04 13:33:22 MST

Other Door/Knob/Lock

📅 2023-12-04 13:33:22

📍 [43.6962097, -116.4915961](#)

🖼️ [Image](#)



2023-12-04 13:33:34 MST

Other Door/Knob/Lock

📅 2023-12-04 13:33:34

📍 [43.6962097, -116.4915961](#)

🖼️ [Image](#)



2023-12-04 13:33:45 MST

Switch/Outlet

📅 2023-12-04 13:33:45

📍 [43.6962097, -116.4915961](#)

🖼️ [Image](#)

📖 Keys/Remotes/Devices	📌 CONDITION	💬 COMMENTS
Keys	- - D	Missing keys
Other	- S -	
Remotes/Devices	- - D	Missing remotes
Swag	- S -	



Keys

📅 2023-12-04 13:43:41

📍 [43.6961764, -116.4917787](#)

🖼️ [Image](#)



Remotes/Devices

📅 2023-12-04 13:43:52

📍 [43.6961764, -116.4917787](#)

🖼️ [Image](#)

📖 Systems	🔧 CONDITION	💬 COMMENTS
Air Conditioning/Filter	- S -	
Breaker Box	- S -	
Evidence of Pest Issue	- S -	
Furnace	- S -	
Other	- S -	
Sewer Cleanout	- S -	
Sprinkler/Timer	- S -	
Thermostat	- S -	
Water Heater	- S -	
Water Softener	- S -	
Whole House Fan	- S -	



📅 2023-12-04 13:33:54

📍 [43.6962097, -116.4915961](#)

🖼️ [Image](#)

Additional Comments

**Final Comments**

To dispute any findings of this inspection please notify us within 3 business days.

**Agent / Inspector Signature**

A handwritten signature in black ink, appearing to be a stylized letter 'M' or similar character.

2023-12-04