
































Move Out



Property	Tenant(s)	Date	Agent / Inspector
		2022-03-31	

Move Out Condition Summary

 AREA	 DETAIL		 COMMENTS	 MEDIA
Front Yard/Exterior	Building Exterior	D	Damage to garage door and seal	 Image
Bathroom: bathroom1	Cabinet/Counter/Shelving	D	Dirty	 Image  Image  Image  Image  Image  Image  Image  Image
Bathroom: bathroom1	Tub/Shower	D	Dirty, personal property left behind	 Image  Image  Image  Image  Image
Bathroom 2: bathroom2	Flooring/Baseboard	D	Paint chipping on baseboard	 Image  Image
Bathroom 2: bathroom2	Tub/Shower	D	Dirty	 Image  Image
Bathroom 2: bathroom2	Wall/Ceiling	D	Paint chipping	 Image  Image  Image  Image
Bedroom: bedroom1	Flooring/Baseboard	D	Animal urine	 Image  Image
Bedroom: bedroom1	Window/Lock/Screen	D	Hole in screen	 Image  Image
Bedroom 2: bedroom2	Smoke / CO detector	D	Smoke detector beeping	 Image

AREA	DETAIL		COMMENTS	MEDIA
Bedroom 2: bedroom2	Window/Lock/Screen	D	Dirty	 Image  Image  Image  Image
Bedroom 3: bedroom3	Door/Knob/Lock	D	Paint chipping	 Image  Image  Image
Bedroom 3: bedroom3	Window/Lock/Screen	D	Dirty	 Image  Image  Image  Image
Dining Room	Flooring/Baseboard	D	Baseboard dirty	 Image  Image
Dining Room	Light Fixture/Fan	D	Bulb burnt out	 Image
Kitchen	Cabinets/Drawers	D	Dirty	 Image  Image  Image  Image  Image  Image  Image  Image  Image  Image  Image  Image  Image  Image  Image
Kitchen	Light Fixture	D	Bulb burnt out	 Image
Kitchen	Microwave	D	Dirty	 Image  Image  Image
Kitchen	Oven	D	Dirty	 Image  Image  Image  Image
Kitchen	Pantry / Shelves	D	Dirty	 Image  Image
Kitchen	Range/Fan/Hood/Filter	D	Dirty	 Image
Kitchen	Refrigerator	D	Dirty	 Image  Image  Image  Image  Image
Kitchen	Sink/Disposal	D	Dirty	 Image  Image

 AREA	 DETAIL		 COMMENTS	 MEDIA
Kitchen	Window/Lock/Screen	D	Dirty	 Image  Image
Laundry Room	Cabinet/Counter/Shelving	D	Dirty	 Image  Image  Image  Image  Image
Laundry Room	Door/Knob/Lock	D	Blue mark on door	 Image  Image  Image
Laundry Room	Faucet/Valve	D	Dirty	 Image
Laundry Room	Flooring/Baseboard	D	Baseboards dirty	 Image  Image
Laundry Room	Wall/Ceiling	D	Paint chipping, hole in wall, black marks on wall	 Image  Image  Image  Image  Image
Living Room	Flooring/Baseboard	D	Baseboard dirty	 Image  Image
Living Room	Wall/Ceiling	D	Paint chipping	 Image  Image  Image  Image
Living Room	Window/Lock/Screen	D	Paint chipping on door frame, dirty	 Image  Image  Image  Image  Image  Image
Office	Window/Lock/Screen	D	Dirty	 Image  Image
Back Yard/Exterior	Building Exterior	D	Weather stripping damaged	 Image
Back Yard/Exterior	Landscaping	D	Dog feces in yard, grass dry, weeds	 Image  Image  Image  Image  Image  Image  Image  Image
Back Yard/Exterior	Other	D	Bins full	 Image
Garage/Parking	Driveway/Floor	D	Dirty	 Image

 AREA	 DETAIL		 COMMENTS	 MEDIA
Systems	Water Heater	D	Rust	 Image

🔒 Move-Out Conditions

S=Satisfactory

D=Damaged

📖 Entry	🔒 CONDITION	💬 COMMENTS
Door/Knob/Lock	- S -	
Doorbell	- S -	
Flooring/Baseboard	- S -	
Light Fixture/Fan	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	



Door/Knob/Lock

📅 2022-03-31 10:17:20

📍 43.6447775, -116.4654308

🖼️ Image



Door/Knob/Lock

📅 2022-03-31 10:17:29

📍 43.6447775, -116.4654308

🖼️ Image



Doorbell

📅 2022-03-31 10:17:35

📍 43.6447775, -116.4654308

🖼️ Image




Flooring/Baseboard

📅 2022-03-31 10:17:46

📍 43.6447775, -116.4654308

🖼️ Image




Light Fixture/Fan

📅 2022-03-31 10:17:50

🔍 [43.6447775, -116.4654308](#)

🖼️ Image



📅 2022-03-31 10:17:16

🔍 [43.6447775, -116.4654308](#)

🖼️ Image



Switch/Outlet

📅 2022-03-31 10:17:58

🔍 [43.6447775, -116.4654308](#)

🖼️ Image




Wall/Ceiling

📅 2022-03-31 10:18:03

🔍 [43.6447775, -116.4654308](#)

🖼️ Image



Wall/Ceiling

📅 2022-03-31 10:18:07

🔍 [43.6447775, -116.4654308](#)

🖼️ Image



Wall/Ceiling

📅 2022-03-31 10:18:08

🔍 [43.6447775, -116.4654308](#)

🖼️ Image

📖 Front Yard/Exterior

📌 CONDITION

💬 COMMENTS

Building Exterior	- - D	Damage to garage door and seal
Landscaping	- S -	

Front Yard/Exterior	CONDITION	COMMENTS
Light Fixture	- S -	
Patio Cover	- S -	
Patio/Deck/Balcony	- S -	
Walk/Driveway	- S -	



Building Exterior

2022-03-31 11:15:11

43.6448448, -116.4655168

Image



Landscaping

2022-03-31 11:15:38

43.6448448, -116.4655168

Image



Light Fixture

2022-03-31 11:15:52

43.6448448, -116.4655168

Image



2022-03-31 11:14:59

43.6448448, -116.4655168

Image



Patio Cover

📅 2022-03-31 11:15:59

📍 43.6448448, -116.4655168

🖼️ Image



Patio/Deck/Balcony

📅 2022-03-31 11:16:06

📍 43.6448448, -116.4655168

🖼️ Image




Walk/Driveway

📅 2022-03-31 11:16:16

📍 43.6448448, -116.4655168

🖼️ Image



Walk/Driveway

📅 2022-03-31 11:16:21

📍 43.6448448, -116.4655168

🖼️ Image

📖 Bathroom: bathroom1	📌 CONDITION	💬 COMMENTS
Cabinet/Counter/Shelving	- - D	Dirty
Door/Knob/Lock	- S -	
Exhaust Fan	- S -	
Flooring/Baseboard	- S -	
Light Fixture	- S -	
Medicine Cabinet/Mirror	- S -	
Sink/Faucet	- S -	
Switch/Outlet	- S -	
Toilet	- S -	
Toilet Paper Holder	- S -	
Towel Rack	- S -	
Tub/Shower	- - D	Dirty, personal property left behind
Wall/Ceiling	- S -	




Cabinet/Counter/Shelving

📅 2022-03-31 10:53:43

📍 [43.6449991, -116.4651504](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2022-03-31 10:53:48

📍 [43.6449991, -116.4651504](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2022-03-31 10:53:53

📍 [43.6449991, -116.4651504](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2022-03-31 10:53:55

📍 [43.6449991, -116.4651504](#)

🖼️ [Image](#)




Cabinet/Counter/Shelving

📅 2022-03-31 10:53:59

📍 [43.6449991, -116.4651504](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2022-03-31 10:54:02

📍 [43.6449991, -116.4651504](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2022-03-31 10:54:06

🔍 [43.6449991, -116.4651504](#)

🖼️ [Image](#)




Cabinet/Counter/Shelving

📅 2022-03-31 10:54:10

🔍 [43.6449991, -116.4651504](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2022-03-31 10:54:31

🔍 [43.6449991, -116.4651504](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2022-03-31 10:54:38

🔍 [43.6449991, -116.4651504](#)

🖼️ [Image](#)



Exhaust Fan

📅 2022-03-31 10:54:43

🔍 [43.6449991, -116.4651504](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2022-03-31 10:54:50

🔍 [43.6449991, -116.4651504](#)

🖼️ [Image](#)



Light Fixture

📅 2022-03-31 10:55:00

📍 [43.6448039, -116.4654818](#)

🖼️ [Image](#)



Light Fixture

📅 2022-03-31 10:55:01

📍 [43.6448039, -116.4654818](#)

🖼️ [Image](#)



Medicine Cabinet/Mirror

📅 2022-03-31 10:55:05

📍 [43.6448039, -116.4654818](#)

🖼️ [Image](#)



📅 2022-03-31 10:55:37

📍 [43.6449991, -116.4651504](#)

🖼️ [Image](#)



Sink/Faucet

📅 2022-03-31 10:55:13

📍 [43.6448039, -116.4654818](#)

🖼️ [Image](#)



Sink/Faucet

📅 2022-03-31 10:55:28

📍 [43.6448039, -116.4654818](#)

🖼️ [Image](#)



Switch/Outlet

📅 2022-03-31 10:55:37

🔍 [43.6448039, -116.4654818](#)

🖼️ [Image](#)



Toilet

📅 2022-03-31 10:55:45

🔍 [43.6448039, -116.4654818](#)

🖼️ [Image](#)



Toilet

📅 2022-03-31 10:55:51

🔍 [43.6448039, -116.4654818](#)

🖼️ [Image](#)



Toilet Paper Holder

📅 2022-03-31 10:55:58

🔍 [43.6448039, -116.4654818](#)

🖼️ [Image](#)



Towel Rack

📅 2022-03-31 10:56:04

🔍 [43.6448039, -116.4654818](#)

🖼️ [Image](#)



Tub/Shower

📅 2022-03-31 10:56:09

🔍 [43.6448039, -116.4654818](#)

🖼️ [Image](#)




Tub/Shower

📅 2022-03-31 10:56:22

📍 [43.6448039, -116.4654818](#)

🖼️ [Image](#)



Tub/Shower

📅 2022-03-31 10:56:24

📍 [43.6448039, -116.4654818](#)

🖼️ [Image](#)



Tub/Shower

📅 2022-03-31 10:56:29

📍 [43.6448039, -116.4654818](#)

🖼️ [Image](#)




Tub/Shower

📅 2022-03-31 10:56:39

📍 [43.6448039, -116.4654818](#)

🖼️ [Image](#)




Wall/Ceiling

📅 2022-03-31 10:57:02

📍 [43.6449025, -116.4650001](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:57:04

📍 [43.6449025, -116.4650001](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:57:07

📍 43.6449025, -116.4650001

🖼️ Image

📖 Bathroom 2: bathroom2

🔧 CONDITION

💬 COMMENTS

Cabinet/Counter/Shelving	- S -	
Door/Knob/Lock	- S -	
Exhaust Fan	- S -	
Flooring/Baseboard	- - D	Paint chipping on baseboard
Light Fixture	- S -	
Medicine Cabinet/Mirror	- S -	
Shower Door/Rail/Curtain	- S -	
Sink/Faucet	- S -	
Switch/Outlet	- S -	
Toilet	- S -	
Toilet Paper Holder	- S -	
Towel Rack	- S -	
Tub/Shower	- - D	Dirty
Wall/Ceiling	- - D	Paint chipping
Window/Lock/Screen	- S -	



Cabinet/Counter/Shelving

📅 2022-03-31 10:44:17

🔍 [43.6448297, -116.4656288](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2022-03-31 10:44:22

🔍 [43.6448297, -116.4656288](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2022-03-31 10:44:34

🔍 [43.6448297, -116.4656288](#)

🖼️ [Image](#)



Exhaust Fan

📅 2022-03-31 10:44:41

🔍 [43.6448252, -116.4656231](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2022-03-31 10:44:47

🔍 [43.6448252, -116.4656231](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2022-03-31 10:44:52

🔍 [43.6448252, -116.4656231](#)

🖼️ [Image](#)



Light Fixture

📅 2022-03-31 10:45:05

🔍 [43.6448252, -116.4656231](#)

🖼️ [Image](#)



Medicine Cabinet/Mirror

📅 2022-03-31 10:45:08

🔍 [43.6448252, -116.4656231](#)

🖼️ [Image](#)



📅 2022-03-31 10:44:13

🔍 [43.6448297, -116.4656288](#)

🖼️ [Image](#)



Shower Door/Rail/Curtain

📅 2022-03-31 10:45:14

🔍 [43.6448252, -116.4656231](#)

🖼️ [Image](#)



Sink/Faucet

📅 2022-03-31 10:45:18

🔍 [43.6448252, -116.4656231](#)

🖼️ [Image](#)



Switch/Outlet

📅 2022-03-31 10:45:27

🔍 [43.6448252, -116.4656231](#)

🖼️ [Image](#)



Toilet

📅 2022-03-31 10:45:33

📍 [43.6448252, -116.4656231](#)

🖼️ [Image](#)



Toilet

📅 2022-03-31 10:45:37

📍 [43.6448252, -116.4656231](#)

🖼️ [Image](#)



Toilet Paper Holder

📅 2022-03-31 10:45:40

📍 [43.6448252, -116.4656231](#)

🖼️ [Image](#)



Towel Rack

📅 2022-03-31 10:45:45

📍 [43.6448252, -116.4656231](#)

🖼️ [Image](#)



Tub/Shower

📅 2022-03-31 10:45:49

📍 [43.6448252, -116.4656231](#)

🖼️ [Image](#)




Tub/Shower

📅 2022-03-31 10:46:10

📍 [43.6448252, -116.4656231](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:46:21

🔍 [43.6448252, -116.4656231](#)

🖼️ Image



Wall/Ceiling

📅 2022-03-31 10:46:24

🔍 [43.6448252, -116.4656231](#)

🖼️ Image



Wall/Ceiling

📅 2022-03-31 10:46:26

🔍 [43.6448252, -116.4656231](#)

🖼️ Image



Wall/Ceiling

📅 2022-03-31 10:46:33

🔍 [43.6448252, -116.4656231](#)

🖼️ Image



Window/Lock/Screen

📅 2022-03-31 10:46:45

🔍 [43.6448198, -116.4656107](#)

🖼️ Image

📖 Bedroom: bedroom1

🔧 CONDITION

💬 COMMENTS

Closet/Door/Track/Shelving	- S -	
Door/Knob/Lock	- S -	

Bedroom: bedroom1

CONDITION

COMMENTS

Flooring/Baseboard	- - D	Animal urine
Light Fixture/Fan	- S -	
Smoke / CO detector	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	
Window Covering	- S -	
Window/Lock/Screen	- - D	Hole in screen




Closet/Door/Track/Shelving

2022-03-31 10:51:24

43.6449287, -116.465585

[Image](#)



Door/Knob/Lock

2022-03-31 10:51:36

43.6449287, -116.465585

[Image](#)



Door/Knob/Lock

2022-03-31 10:51:41

43.6449287, -116.465585

[Image](#)



Flooring/Baseboard

2022-03-31 10:49:43

43.6448156, -116.4655908

[Image](#)



Flooring/Baseboard

📅 2022-03-31 10:51:50

🔍 [43.6449287, -116.465585](#)

🖼️ [Image](#)



Light Fixture/Fan

📅 2022-03-31 10:52:00

🔍 [43.6449287, -116.465585](#)

🖼️ [Image](#)



📅 2022-03-31 10:51:11

🔍 [43.6449287, -116.465585](#)

🖼️ [Image](#)



Smoke / CO detector

📅 2022-03-31 10:52:07

🔍 [43.6449287, -116.465585](#)

🖼️ [Image](#)



Switch/Outlet

📅 2022-03-31 10:52:13

🔍 [43.6449287, -116.465585](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:52:19

🔍 [43.6449287, -116.465585](#)

🖼️ [Image](#)




Wall/Ceiling

📅 2022-03-31 10:52:22

📍 [43.6449287, -116.465585](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:52:30

📍 [43.6449287, -116.465585](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:52:32

📍 [43.6449287, -116.465585](#)

🖼️ [Image](#)



Window Covering

📅 2022-03-31 10:52:48

📍 [43.6449287, -116.465585](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2022-03-31 10:53:09

📍 [43.6449991, -116.4651504](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2022-03-31 10:53:13

📍 [43.6449991, -116.4651504](#)

🖼️ [Image](#)

📖 Bedroom 2: bedroom2	🔧 CONDITION	💬 COMMENTS
Closet/Door/Track/Shelving	- S -	
Door/Knob/Lock	- S -	

📖 Bedroom 2: bedroom2

🔧 CONDITION

💬 COMMENTS

Flooring/Baseboard	- S -	
Light Fixture/Fan	- S -	
Smoke / CO detector	- - D	Smoke detector beeping
Switch/Outlet	- S -	
Wall/Ceiling	- S -	
Window Covering	- S -	
Window/Lock/Screen	- - D	Dirty



Closet/Door/Track/Shelving

📅 2022-03-31 10:40:48

📍 43.644824, -116.4655843

🖼️ Image



Closet/Door/Track/Shelving

📅 2022-03-31 10:40:56

📍 43.644824, -116.4655843

🖼️ Image



Closet/Door/Track/Shelving

📅 2022-03-31 10:41:06

📍 43.644824, -116.4655843

🖼️ Image




Door/Knob/Lock

📅 2022-03-31 10:41:56

📍 43.644824, -116.4655843

🖼️ Image



Door/Knob/Lock

📅 2022-03-31 10:42:03

📍 [43.644824, -116.4655843](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2022-03-31 10:42:09

📍 [43.644824, -116.4655843](#)

🖼️ [Image](#)



Light Fixture/Fan

📅 2022-03-31 10:42:14

📍 [43.644824, -116.4655843](#)

🖼️ [Image](#)



📅 2022-03-31 10:40:42

📍 [43.644824, -116.4655843](#)

🖼️ [Image](#)



Smoke / CO detector

📅 2022-03-31 10:42:20

📍 [43.644824, -116.4655843](#)

🖼️ [Image](#)



Switch/Outlet

📅 2022-03-31 10:42:32

📍 [43.644824, -116.4655843](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:42:38

🔍 [43.6448297, -116.4656288](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:42:43

🔍 [43.6448297, -116.4656288](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:42:48

🔍 [43.6448297, -116.4656288](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:42:52

🔍 [43.6448297, -116.4656288](#)

🖼️ [Image](#)



Window Covering

📅 2022-03-31 10:43:12

🔍 [43.6448297, -116.4656288](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2022-03-31 10:43:25

🔍 [43.6448297, -116.4656288](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2022-03-31 10:43:33

📍 43.6448297, -116.4656288

🖼️ Image



Window/Lock/Screen

📅 2022-03-31 10:43:35

📍 43.6448297, -116.4656288

🖼️ Image



Window/Lock/Screen

📅 2022-03-31 10:43:37

📍 43.6448297, -116.4656288

🖼️ Image

📖 Bedroom 3: bedroom3	📌 CONDITION	💬 COMMENTS
Closet/Door/Track/Shelving	- S -	
Door/Knob/Lock	- - D	Paint chipping
Flooring/Baseboard	- S -	
Light Fixture/Fan	- S -	
Smoke / CO detector	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	
Window Covering	- S -	
Window/Lock/Screen	- - D	Dirty



Closet/Door/Track/Shelving

📅 2022-03-31 10:34:16

🔍 [43.6447949, -116.4655461](#)

🖼️ [Image](#)



Closet/Door/Track/Shelving

📅 2022-03-31 10:34:26

🔍 [43.6447949, -116.4655461](#)

🖼️ [Image](#)




Closet/Door/Track/Shelving

📅 2022-03-31 10:34:35

🔍 [43.6447949, -116.4655461](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2022-03-31 10:34:41

🔍 [43.6447949, -116.4655461](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2022-03-31 10:34:46

🔍 [43.6447949, -116.4655461](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2022-03-31 10:34:51

🔍 [43.6447949, -116.4655461](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2022-03-31 10:35:05

📍 [43.6447949, -116.4655461](#)

🖼️ [Image](#)



Light Fixture/Fan

📅 2022-03-31 10:35:13

📍 [43.6447949, -116.4655461](#)

🖼️ [Image](#)



📅 2022-03-31 10:34:08

📍 [43.6447949, -116.4655461](#)

🖼️ [Image](#)



Smoke / CO detector

📅 2022-03-31 10:35:18

📍 [43.6447949, -116.4655461](#)

🖼️ [Image](#)



Switch/Outlet

📅 2022-03-31 10:35:22

📍 [43.6447949, -116.4655461](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:35:30

📍 [43.6447949, -116.4655461](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:35:35

📍 [43.6447949, -116.4655461](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:35:41

📍 [43.6447949, -116.4655461](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:35:46

📍 [43.6447949, -116.4655461](#)

🖼️ [Image](#)



Window Covering

📅 2022-03-31 10:36:01

📍 [43.6448732, -116.4657827](#)

🖼️ [Image](#)




Window Covering

📅 2022-03-31 10:36:03

📍 [43.6448732, -116.4657827](#)

🖼️ [Image](#)




Window/Lock/Screen

📅 2022-03-31 10:36:43

📍 [43.6448732, -116.4657827](#)

🖼️ [Image](#)



2022-03-31 10:36:46 MDT

Window/Lock/Screen

📅 2022-03-31 10:36:46

📍 [43.6448732, -116.4657827](#)

🖼️ [Image](#)



2022-03-31 10:36:49 MDT

Window/Lock/Screen

📅 2022-03-31 10:36:49

📍 [43.6448732, -116.4657827](#)

🖼️ [Image](#)



2022-03-31 10:36:56 MDT

Window/Lock/Screen

📅 2022-03-31 10:36:56

📍 [43.6448732, -116.4657827](#)

🖼️ [Image](#)

📖 Dining Room	📏 CONDITION	💬 COMMENTS
Flooring/Baseboard	- - D	Baseboard dirty
Light Fixture/Fan	- - D	Bulb burnt out
Smoke/CO Detector	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	



Flooring/Baseboard

📅 2022-03-31 10:29:08

🔍 [43.6448099, -116.4655651](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2022-03-31 11:05:05

🔍 [43.6448177, -116.4655322](#)

🖼️ [Image](#)



Light Fixture/Fan

📅 2022-03-31 10:29:15

🔍 [43.6448099, -116.4655651](#)

🖼️ [Image](#)



📅 2022-03-31 10:29:05

🔍 [43.6448099, -116.4655651](#)

🖼️ [Image](#)



Smoke/CO Detector

📅 2022-03-31 10:29:28

🔍 [43.6448099, -116.4655651](#)

🖼️ [Image](#)




Switch/Outlet

📅 2022-03-31 10:29:34

🔍 [43.6448099, -116.4655651](#)

🖼️ [Image](#)



Wall/Ceiling

2022-03-31 10:29:38

43.6448099, -116.4655651

Image

Hallway/Stairs

CONDITION

COMMENTS

Closet/Cabinet	- S -	
Flooring/Baseboard	- S -	
Light Fixture	- S -	
Smoke/CO Detector	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	



Closet/Cabinet

2022-03-31 10:47:03

43.6448198, -116.4656107

Image



Closet/Cabinet

2022-03-31 10:47:10

43.6448198, -116.4656107

Image



Flooring/Baseboard

📅 2022-03-31 10:47:18

📍 [43.6448198, -116.4656107](#)

🖼️ [Image](#)



Light Fixture

📅 2022-03-31 10:47:25

📍 [43.6448198, -116.4656107](#)

🖼️ [Image](#)



📅 2022-03-31 10:46:57

📍 [43.6448198, -116.4656107](#)

🖼️ [Image](#)



Smoke/CO Detector

📅 2022-03-31 10:47:37

📍 [43.6448198, -116.4656107](#)

🖼️ [Image](#)



Switch/Outlet

📅 2022-03-31 10:47:44

📍 [43.6448198, -116.4656107](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:47:50

📍 [43.6448198, -116.4656107](#)

🖼️ [Image](#)




Wall/Ceiling

📅 2022-03-31 10:47:53

📍 43.6448198, -116.4656107

🖼️ Image



Wall/Ceiling

📅 2022-03-31 10:47:57

📍 43.6448198, -116.4656107

🖼️ Image

📖 Kitchen

🔧 CONDITION

💬 COMMENTS

Cabinets/Drawers	- - D	Dirty
Counter	- S -	
Dishwasher	- S -	
Faucet/Plumbing	- S -	
Flooring/Baseboard	- S -	
Light Fixture	- - D	Bulb burnt out
Microwave	- - D	Dirty
Oven	- - D	Dirty
Pantry / Shelves	- - D	Dirty
Range/Fan/Hood/Filter	- - D	Dirty
Refrigerator	- - D	Dirty
Sink/Disposal	- - D	Dirty
Switch/Outlet	- S -	
Wall/Ceiling	- S -	
Window Covering	- S -	
Window/Lock/Screen	- - D	Dirty



Cabinets/Drawers

📅 2022-03-31 10:22:56

📍 [43.6448419, -116.4658027](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-03-31 10:23:03

📍 [43.644794, -116.465576](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-03-31 10:23:07

📍 [43.644794, -116.465576](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-03-31 10:23:10

📍 [43.644794, -116.465576](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-03-31 10:23:15

📍 [43.644794, -116.465576](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-03-31 10:23:20

📍 [43.644794, -116.465576](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-03-31 10:23:23

📍 [43.644794, -116.465576](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-03-31 10:23:27

📍 [43.644794, -116.465576](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-03-31 10:23:30

📍 [43.644794, -116.465576](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-03-31 10:23:35

📍 [43.644794, -116.465576](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-03-31 10:23:38

📍 [43.644794, -116.465576](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-03-31 10:23:43

📍 [43.644794, -116.465576](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2022-03-31 10:23:47

📍 43.644794, -116.465576

🖼️ Image



Cabinets/Drawers

📅 2022-03-31 10:23:51

📍 43.644794, -116.465576

🖼️ Image



Counter

📅 2022-03-31 10:24:03

📍 43.644794, -116.465576

🖼️ Image



Dishwasher

📅 2022-03-31 10:24:08

📍 43.644794, -116.465576

🖼️ Image



Dishwasher

📅 2022-03-31 10:24:12

📍 43.644794, -116.465576

🖼️ Image



Faucet/Plumbing

📅 2022-03-31 10:24:18

📍 43.644794, -116.465576

🖼️ Image



Flooring/Baseboard

📅 2022-03-31 10:24:49

📍 [43.644794, -116.465576](#)

🖼️ [Image](#)



Light Fixture

📅 2022-03-31 10:24:56

📍 [43.644794, -116.465576](#)

🖼️ [Image](#)



Microwave

📅 2022-03-31 10:25:08

📍 [43.644794, -116.465576](#)

🖼️ [Image](#)



Microwave

📅 2022-03-31 10:25:13

📍 [43.644794, -116.465576](#)

🖼️ [Image](#)



Microwave

📅 2022-03-31 10:25:16

📍 [43.644794, -116.465576](#)

🖼️ [Image](#)



📅 2022-03-31 10:22:45

📍 [43.6448419, -116.4658027](#)

🖼️ [Image](#)



Oven

📅 2022-03-31 10:25:31

📍 43.6447949, -116.46556

🖼️ Image



Oven

📅 2022-03-31 10:25:34

📍 43.6447949, -116.46556

🖼️ Image



Oven

📅 2022-03-31 10:25:38

📍 43.6447949, -116.46556

🖼️ Image



Oven

📅 2022-03-31 10:25:43

📍 43.6447949, -116.46556

🖼️ Image



Pantry / Shelves

📅 2022-03-31 10:25:54

📍 43.6447949, -116.46556

🖼️ Image



Pantry / Shelves

📅 2022-03-31 10:26:03

📍 43.6447949, -116.46556

🖼️ Image



Range/Fan/Hood/Filter

📅 2022-03-31 10:26:17

📍 [43.6447949, -116.46556](#)

🖼️ [Image](#)



Refrigerator

📅 2022-03-31 10:26:27

📍 [43.6447949, -116.46556](#)

🖼️ [Image](#)



Refrigerator

📅 2022-03-31 10:26:31

📍 [43.6447949, -116.46556](#)

🖼️ [Image](#)



Refrigerator

📅 2022-03-31 10:26:36

📍 [43.6447949, -116.46556](#)

🖼️ [Image](#)



Refrigerator

📅 2022-03-31 10:26:40

📍 [43.6447949, -116.46556](#)

🖼️ [Image](#)



Refrigerator

📅 2022-03-31 10:26:45

📍 [43.6447949, -116.46556](#)

🖼️ [Image](#)



Refrigerator

📅 2022-03-31 10:26:48

📍 [43.6447949, -116.46556](#)

🖼️ [Image](#)



Sink/Disposal

📅 2022-03-31 10:27:00

📍 [43.6447949, -116.46556](#)

🖼️ [Image](#)



Sink/Disposal

📅 2022-03-31 10:27:03

📍 [43.6447949, -116.46556](#)

🖼️ [Image](#)




Switch/Outlet

📅 2022-03-31 10:27:12

📍 [43.6447949, -116.46556](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:27:32

📍 [43.6448099, -116.465561](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:27:35

📍 [43.6448099, -116.465561](#)

🖼️ [Image](#)



Window Covering

📅 2022-03-31 10:27:50

📍 [43.6448099, -116.4655651](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2022-03-31 10:28:13

📍 [43.6448099, -116.4655651](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2022-03-31 10:28:18

📍 [43.6448099, -116.4655651](#)

🖼️ [Image](#)

📖 Laundry Room	📌 CONDITION	💬 COMMENTS
Cabinet/Counter/Shelving	- - D	Dirty
Door/Knob/Lock	- - D	Blue mark on door
Faucet/Valve	- - D	Dirty
Flooring/Baseboard	- - D	Baseboards dirty
Light Fixture/Fan	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- - D	Paint chipping, hole in wall, black marks on wall



Cabinet/Counter/Shelving

📅 2022-03-31 10:58:02

📍 [43.6449025, -116.4650001](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2022-03-31 10:58:07

📍 [43.6449025, -116.4650001](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2022-03-31 10:58:13

📍 [43.6449025, -116.4650001](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2022-03-31 10:58:23

📍 [43.6449025, -116.4650001](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2022-03-31 10:58:27

📍 [43.6449025, -116.4650001](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2022-03-31 10:58:36

📍 [43.6449025, -116.4650001](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2022-03-31 10:58:39

🔍 [43.6449025, -116.4650001](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2022-03-31 10:58:43

🔍 [43.6449025, -116.4650001](#)

🖼️ [Image](#)



Faucet/Valve

📅 2022-03-31 10:58:54

🔍 [43.6449025, -116.4650001](#)

🖼️ [Image](#)




Flooring/Baseboard

📅 2022-03-31 10:59:03

🔍 [43.6448069, -116.465462](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2022-03-31 10:59:07

🔍 [43.6448069, -116.465462](#)

🖼️ [Image](#)




Light Fixture/Fan

📅 2022-03-31 10:59:19

🔍 [43.6448069, -116.465462](#)

🖼️ [Image](#)



📅 2022-03-31 10:57:58

📍 [43.6449025, -116.4650001](#)

🖼️ [Image](#)



Switch/Outlet

📅 2022-03-31 10:59:24

📍 [43.6448069, -116.465462](#)

🖼️ [Image](#)




Wall/Ceiling

📅 2022-03-31 10:59:28

📍 [43.6448069, -116.465462](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:59:32

📍 [43.6448069, -116.465462](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:59:35

📍 [43.6448069, -116.465462](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:59:39

📍 [43.6448069, -116.465462](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 11:00:05

📍 [43.6448069, -116.465462](#)

🖼️ [Image](#)

📖 Living Room

📌 CONDITION

💬 COMMENTS

Flooring/Baseboard	- - D	Baseboard dirty
Light Fixture/Fan	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- - D	Paint chipping
Window Covering	- S -	
Window/Lock/Screen	- - D	Paint chipping on door frame, dirty



Flooring/Baseboard

📅 2022-03-31 10:30:06

📍 [43.6448041, -116.4654264](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2022-03-31 11:04:37

📍 [43.644918, -116.4649649](#)

🖼️ [Image](#)



Light Fixture/Fan

📅 2022-03-31 10:30:39

📍 [43.6448041, -116.4654264](#)

🖼️ [Image](#)



📅 2022-03-31 10:29:58

📍 [43.6448041, -116.4654264](#)

🖼️ [Image](#)



Switch/Outlet

📅 2022-03-31 10:30:49

📍 [43.6448041, -116.4654264](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:30:58

📍 [43.6448041, -116.4654264](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:31:01

📍 [43.6448041, -116.4654264](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:31:06

📍 [43.6448041, -116.4654264](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:31:14

🔍 [43.6448041, -116.4654264](#)

🖼️ [Image](#)



Window Covering

📅 2022-03-31 10:31:49

🔍 [43.6448041, -116.4654264](#)

🖼️ [Image](#)



Window Covering

📅 2022-03-31 10:31:52

🔍 [43.644816, -116.4655414](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2022-03-31 10:32:13

🔍 [43.644816, -116.4655414](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2022-03-31 10:32:18

🔍 [43.644816, -116.4655414](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2022-03-31 10:32:22

🔍 [43.644816, -116.4655414](#)

🖼️ [Image](#)




Window/Lock/Screen

📅 2022-03-31 10:32:32

📍 [43.644816, -116.4655414](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2022-03-31 10:33:01

📍 [43.644816, -116.4655414](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2022-03-31 10:33:06

📍 [43.644816, -116.4655414](#)

🖼️ [Image](#)

📖 Office	📍 CONDITION	💬 COMMENTS
Door/Knob/Lock	- S -	
Flooring/Baseboard	- S -	
Light Fixture/Fan	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	
Window Covering	- S -	
Window/Lock/Screen	- - D	Dirty



Door/Knob/Lock

📅 2022-03-31 10:37:58

📍 [43.6448732, -116.4657827](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2022-03-31 10:38:14

📍 [43.6447759, -116.4656476](#)

🖼️ [Image](#)



Light Fixture/Fan

📅 2022-03-31 10:38:19

📍 [43.6447759, -116.4656476](#)

🖼️ [Image](#)



📅 2022-03-31 10:37:42

📍 [43.6448732, -116.4657827](#)

🖼️ [Image](#)



Switch/Outlet

📅 2022-03-31 10:38:25

📍 [43.6447759, -116.4656476](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:38:35

📍 [43.6447759, -116.4656476](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:38:40

📍 [43.6447759, -116.4656476](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:38:46

📍 [43.6447759, -116.4656476](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2022-03-31 10:38:50

📍 [43.6447759, -116.4656476](#)

🖼️ [Image](#)



Window Covering

📅 2022-03-31 10:39:03

📍 [43.6447759, -116.4656476](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2022-03-31 10:39:17

📍 [43.6447759, -116.4656476](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2022-03-31 10:39:22

📍 [43.6447759, -116.4656476](#)

🖼️ [Image](#)

📖 Back Yard/Exterior

📌 CONDITION

💬 COMMENTS

Building Exterior	- - D	Weather stripping damaged
Fence/Gate	- S -	

📖 Back Yard/Exterior	📌 CONDITION	💬 COMMENTS
Hoses/Spigots	- S -	
Landscaping	- - D	Dog feces in yard, grass dry, weeds
Light Fixture	- S -	
Other	- - D	Bins full
Patio Cover	- S -	
Patio/Deck/Balcony	- S -	



2022-03-31 11:05:32 MDT

Building Exterior

📅 2022-03-31 11:05:32

📍 [43.6448177, -116.4655322](#)

🖼️ [Image](#)



2022-03-31 11:06:10 MDT

Fence/Gate

📅 2022-03-31 11:06:10

📍 [43.6448177, -116.4655322](#)

🖼️ [Image](#)



2022-03-31 11:07:25 MDT

Hoses/Spigots

📅 2022-03-31 11:07:25

📍 [43.6445926, -116.4654031](#)

🖼️ [Image](#)



2022-03-31 11:06:20 MDT

Landscaping

📅 2022-03-31 11:06:20

📍 [43.6448177, -116.4655322](#)

🖼️ [Image](#)



Landscaping

📅 2022-03-31 11:06:23

🔍 [43.6448177, -116.4655322](#)

🖼️ [Image](#)



Landscaping

📅 2022-03-31 11:06:54

🔍 [43.6448177, -116.4655322](#)

🖼️ [Image](#)



Landscaping

📅 2022-03-31 12:25:15

🔍 [43.6449167, -116.4653718](#)

🖼️ [Image](#)



Landscaping

📅 2022-03-31 11:06:50

🔍 [43.6448177, -116.4655322](#)

🖼️ [Image](#)




Landscaping

📅 2022-03-31 11:06:57

🔍 [43.6448177, -116.4655322](#)

🖼️ [Image](#)



Landscaping

📅 2022-03-31 12:25:50

🔍 [43.6449167, -116.4653718](#)

🖼️ [Image](#)



Landscaping

📅 2022-03-31 12:25:54

📍 [43.6449167, -116.4653718](#)

🖼️ [Image](#)



Light Fixture

📅 2022-03-31 11:09:15

📍 [43.6448317, -116.4654626](#)


🖼️ [Image](#)



📅 2022-03-31 11:06:04

📍 [43.6448177, -116.4655322](#)

🖼️ [Image](#)



Other

📅 2022-03-31 11:08:49

📍 [43.6445926, -116.4654031](#)

🖼️ [Image](#)



Patio Cover

📅 2022-03-31 11:09:08

📍 [43.6448317, -116.4654626](#)

🖼️ [Image](#)



Patio/Deck/Balcony

📅 2022-03-31 11:09:24

📍 [43.6448317, -116.4654626](#)




🖼️ [Image](#)

📁 Garage/Parking

🔧 CONDITION


💬 COMMENTS


Cabinet/Counter	- S -	
Driveway/Floor	- - D	Dirty

 Garage/Parking	 CONDITION	 COMMENTS
Garage Door	- S -	
Light Fixture	- S -	
Other Door/Knob/Lock	- S -	
Switch/Outlet	- S -	



Cabinet/Counter


 2022-03-31 11:01:00


 [43.6448248, -116.4654137](#)

 [Image](#)



Cabinet/Counter


 2022-03-31 11:01:06

 [43.6448248, -116.4654137](#)

 [Image](#)




Driveway/Floor


 2022-03-31 11:01:18

 [43.6448248, -116.4654137](#)

 [Image](#)



Garage Door

 2022-03-31 11:01:33

 [43.6448248, -116.4654137](#)

 [Image](#)



Garage Door

📅 2022-03-31 11:01:36

🔍 [43.6448248, -116.4654137](#)

🖼️ Image



Light Fixture

📅 2022-03-31 11:02:01

🔍 [43.6448248, -116.4654137](#)


🖼️ Image



📅 2022-03-31 11:00:21

🔍 [43.6448069, -116.465462](#)

🖼️ Image




Other Door/Knob/Lock

📅 2022-03-31 11:02:12

🔍 [43.6448248, -116.4654137](#)

🖼️ Image




Other Door/Knob/Lock

📅 2022-03-31 11:02:18

🔍 [43.6448248, -116.4654137](#)

🖼️ Image



Switch/Outlet

📅 2022-03-31 11:02:29

🔍 [43.6448248, -116.4654137](#)




🖼️ Image

📖 Systems

🔧 CONDITION


💬 COMMENTS

Air Conditioning/Filter	- S -	
Breaker Box	- S -	

 Systems	 CONDITION	 COMMENTS
Evidence of Pest Issue	- S -	
Furnace	- S -	16x25x4
Other	- S -	
Sewer Cleanout	- S -	
Sprinkler/Timer	- S -	
Thermostat	- S -	
Water Heater	- - D	Rust
Water Softener	- S -	
Whole House Fan	- S -	




Furnace


 2022-03-31 11:03:01

 [43.644918, -116.4649649](#)

 [Image](#)




 2022-03-31 11:02:40


 [43.6448248, -116.4654137](#)

 [Image](#)



Water Heater

 2022-03-31 11:03:42

 [43.644918, -116.4649649](#)

 [Image](#)


Additional Comments

Final Comments

To dispute any findings of this inspection please notify us within 3 business days.

Agent / Technician Signature

S



2022-03-31