

Move In

Property	Tenant(s)	Date	Agent / Inspector
		2024-02-01	

Move In Condition Summary

AREA	DETAIL		COMMENTS	MEDIA
Front Yard/Exterior	Landscaping	D	Leaves in planter	
Bathroom	Tub/Shower	D	Grout cracking in shower	 Image  Image  Image  Image
Bedroom	Wall/Ceiling	D	Holes in wall	 Image  Image  Image  Image  Image
Living Room	Window Covering	D	Broken wood slat	 Image  Image  Image  Image

🔑 Move-In Conditions

S=Satisfactory

D=Damaged

📖 Entry

🔑 CONDITION

💬 COMMENTS

Door/Knob/Lock	- S -	
Doorbell	- S -	
Flooring/Baseboard	- S -	
Light Fixture/Fan	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	



📅 2024-02-01 11:59:37

📍 [43.5756339, -116.1337014](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2024-02-01 11:59:45

📍 [43.5756339, -116.1337014](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2024-02-01 12:00:00

📍 [43.5756339, -116.1337014](#)

🖼️ [Image](#)



Doorbell

📅 2024-02-01 12:00:04

📍 [43.5756339, -116.1337014](#)

🖼️ [Image](#)




2024-02-01 12:00:16 MST
Flooring/Baseboard

📅 2024-02-01 12:00:16

📍 [43.5755582, -116.1340024](#)

🖼️ [Image](#)



2024-02-01 12:00:18 MST
Flooring/Baseboard

📅 2024-02-01 12:00:18

📍 [43.5755582, -116.1340024](#)

🖼️ [Image](#)



2024-02-01 12:00:39 MST
Switch/Outlet

📅 2024-02-01 12:00:39

📍 [43.5755582, -116.1340024](#)

🖼️ [Image](#)




2024-02-01 12:00:45 MST
Wall/Ceiling

📅 2024-02-01 12:00:45

📍 [43.5755582, -116.1340024](#)

🖼️ [Image](#)



2024-02-01 12:00:48 MST
Wall/Ceiling

📅 2024-02-01 12:00:48

📍 [43.5755582, -116.1340024](#)

🖼️ [Image](#)

📖 Front Yard/Exterior

📌 CONDITION

💬 COMMENTS

Building Exterior	- S -	
Fence/Gate	- S -	

Front Yard/Exterior	CONDITION	COMMENTS
Hoses/Spigots	- S -	
Landscaping	- - D	Leaves in planter
Light Fixture	- S -	
Mailbox/Keyed Location	- S -	
Other	- S -	
Patio Cover	- S -	
Patio/Deck/Balcony	- S -	
Porch/Stairs	- S -	
Sprinkler/Timer	- S -	
Walk/Driveway	- S -	



2024-02-01 12:14:01

43.5755949, -116.1337956

Image

Bathroom	CONDITION	COMMENTS
Cabinet/Counter/Shelving	- S -	
Door/Knob/Lock	- S -	
Exhaust Fan	- S -	
Flooring/Baseboard	- S -	
Light Fixture	- S -	
Medicine Cabinet/Mirror	- S -	
Shower Door/Rail/Curtain	- S -	
Sink/Faucet	- S -	
Switch/Outlet	- S -	
Toilet	- S -	
Toilet Paper Holder	- S -	
Towel Rack	- S -	

Bathroom

CONDITION

COMMENTS

Tub/Shower	- - D	Grout cracking in shower
Wall/Ceiling	- S -	
Window Covering	- S -	
Window/Lock/Screen	- S -	



2024-02-01 11:30:04 MST

📅 2024-02-01 11:30:04
📍 43.5756144, -116.1337065
🖼️ Image



2024-02-01 11:30:07 MST

Cabinet/Counter/Shelving
📅 2024-02-01 11:30:07
📍 43.5756144, -116.1337065
🖼️ Image



2024-02-01 11:30:10 MST

Cabinet/Counter/Shelving
📅 2024-02-01 11:30:10
📍 43.5756144, -116.1337065
🖼️ Image



2024-02-01 11:30:13 MST

Cabinet/Counter/Shelving
📅 2024-02-01 11:30:13
📍 43.5756144, -116.1337065
🖼️ Image



Cabinet/Counter/Shelving

📅 2024-02-01 11:30:17

📍 43.5756144, -116.1337065

🖼️ Image



Cabinet/Counter/Shelving

📅 2024-02-01 11:30:22

📍 43.5756144, -116.1337065

🖼️ Image




Cabinet/Counter/Shelving

📅 2024-02-01 11:30:25

📍 43.5756144, -116.1337065

🖼️ Image



Cabinet/Counter/Shelving

📅 2024-02-01 11:30:32

📍 43.5756144, -116.1337065

🖼️ Image



Door/Knob/Lock

📅 2024-02-01 11:30:43

📍 43.5756144, -116.1337065

🖼️ Image



Door/Knob/Lock

📅 2024-02-01 11:30:47

📍 43.5756144, -116.1337065

🖼️ Image



Exhaust Fan

📅 2024-02-01 11:30:54

📍 [43.5756144, -116.1337065](#)

🖼️ [Image](#)




Exhaust Fan

📅 2024-02-01 11:30:59

📍 [43.5756144, -116.1337065](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:31:04

📍 [43.5756144, -116.1337065](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:31:05

📍 [43.5756144, -116.1337065](#)

🖼️ [Image](#)




Flooring/Baseboard

📅 2024-02-01 11:31:08

📍 [43.5756144, -116.1337065](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:31:10

📍 [43.5756144, -116.1337065](#)

🖼️ [Image](#)



Light Fixture

📅 2024-02-01 11:31:15

🔍 [43.5756144, -116.1337065](#)

🖼️ [Image](#)



Light Fixture

📅 2024-02-01 11:31:17

🔍 [43.5756144, -116.1337065](#)

🖼️ [Image](#)



Light Fixture

📅 2024-02-01 11:31:19

🔍 [43.5756144, -116.1337065](#)

🖼️ [Image](#)



Light Fixture

📅 2024-02-01 11:31:21

🔍 [43.5756144, -116.1337065](#)

🖼️ [Image](#)



Light Fixture

📅 2024-02-01 11:31:27

🔍 [43.5756144, -116.1337065](#)

🖼️ [Image](#)



Medicine Cabinet/Mirror

📅 2024-02-01 11:31:33

🔍 [43.5756144, -116.1337065](#)

🖼️ [Image](#)




Shower Door/Rail/Curtain

📅 2024-02-01 11:31:39

📍 [43.5755126, -116.1336976](#)

🖼️ [Image](#)



Sink/Faucet

📅 2024-02-01 11:31:44

📍 [43.5755126, -116.1336976](#)

🖼️ [Image](#)



Sink/Faucet

📅 2024-02-01 11:31:48

📍 [43.5755126, -116.1336976](#)

🖼️ [Image](#)




Switch/Outlet

📅 2024-02-01 11:31:53

📍 [43.5755126, -116.1336976](#)

🖼️ [Image](#)




Toilet

📅 2024-02-01 11:32:01

📍 [43.5755126, -116.1336976](#)

🖼️ [Image](#)



Toilet

📅 2024-02-01 11:32:05

📍 [43.5755126, -116.1336976](#)

🖼️ [Image](#)



Toilet Paper Holder

📅 2024-02-01 11:32:10

📍 [43.5755126, -116.1336976](#)

🖼️ [Image](#)



Towel Rack

📅 2024-02-01 11:32:15

📍 [43.5755126, -116.1336976](#)

🖼️ [Image](#)



Towel Rack

📅 2024-02-01 11:32:16

📍 [43.5755126, -116.1336976](#)

🖼️ [Image](#)



Towel Rack

📅 2024-02-01 11:32:21

📍 [43.5755126, -116.1336976](#)

🖼️ [Image](#)



Towel Rack

📅 2024-02-01 11:32:25

📍 [43.5755126, -116.1336976](#)

🖼️ [Image](#)




Tub/Shower

📅 2024-02-01 11:32:31

📍 [43.5755126, -116.1336976](#)

🖼️ [Image](#)




Tub/Shower

📅 2024-02-01 11:32:39

📍 [43.5755126, -116.1336976](#)

🖼️ [Image](#)



Tub/Shower

📅 2024-02-01 11:32:42

📍 [43.5755126, -116.1336976](#)

🖼️ [Image](#)



Tub/Shower

📅 2024-02-01 11:32:54

📍 [43.5755126, -116.1336976](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:33:31

📍 [43.5755126, -116.1336976](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:33:34

📍 [43.5755126, -116.1336976](#)

🖼️ [Image](#)



Window Covering

📅 2024-02-01 11:33:37

📍 [43.5755126, -116.1336976](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2024-02-01 11:33:50

📍 [43.575476, -116.1337506](#)

🖼️ [Image](#)




Window/Lock/Screen

📅 2024-02-01 11:33:53

📍 [43.575476, -116.1337506](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2024-02-01 11:34:13

📍 [43.575476, -116.1337506](#)

🖼️ [Image](#)


📖 Bathroom 2

🔧 CONDITION


💬 COMMENTS

Cabinet/Counter/Shelving	- S -	
Door/Knob/Lock	- S -	
Exhaust Fan	- S -	
Flooring/Baseboard	- S -	
Light Fixture	- S -	
Medicine Cabinet/Mirror	- S -	
Sink/Faucet	- S -	
Switch/Outlet	- S -	
Toilet	- S -	
Toilet Paper Holder	- S -	
Towel Rack	- S -	
Tub/Shower	- S -	
Wall/Ceiling	- S -	


Window/Lock/Screen	- S -	
--------------------	-------	--



2024-02-01 11:44:55 MST
2024-02-01 11:44:55
[43.5757435, -116.134014](#)
[Image](#)




2024-02-01 11:45:00 MST
Cabinet/Counter/Shelving
2024-02-01 11:45:00
[43.5757435, -116.134014](#)
[Image](#)




2024-02-01 11:45:06 MST
Cabinet/Counter/Shelving
2024-02-01 11:45:06
[43.5757435, -116.134014](#)
[Image](#)



2024-02-01 11:45:12 MST
Cabinet/Counter/Shelving
2024-02-01 11:45:12
[43.5757435, -116.134014](#)
[Image](#)



2024-02-01 11:45:18 MST
Cabinet/Counter/Shelving
2024-02-01 11:45:18
[43.5757435, -116.134014](#)
[Image](#)



2024-02-01 11:45:58 MST
Door/Knob/Lock
2024-02-01 11:45:58
[43.5756075, -116.1337085](#)
[Image](#)



Door/Knob/Lock

📅 2024-02-01 11:46:05

🔍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)



Exhaust Fan

📅 2024-02-01 11:46:14

🔍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:46:17

🔍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)




Flooring/Baseboard

📅 2024-02-01 11:46:23

🔍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:46:25

🔍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)



Light Fixture

📅 2024-02-01 11:46:29

🔍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)



Medicine Cabinet/Mirror

📅 2024-02-01 11:46:32

📍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)



Sink/Faucet

📅 2024-02-01 11:46:43

📍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)



Sink/Faucet

📅 2024-02-01 11:46:50

📍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)



Switch/Outlet

📅 2024-02-01 11:46:54

📍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)



Toilet

📅 2024-02-01 11:46:59

📍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)



Toilet

📅 2024-02-01 11:47:03

📍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)



Toilet Paper Holder

📅 2024-02-01 11:47:07

🔍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)



Towel Rack

📅 2024-02-01 11:47:11

🔍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)



Towel Rack

📅 2024-02-01 11:47:15

🔍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)



Towel Rack

📅 2024-02-01 11:47:17

🔍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)



Tub/Shower

📅 2024-02-01 11:47:22

🔍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)




Tub/Shower

📅 2024-02-01 11:47:25

🔍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)




Wall/Ceiling

📅 2024-02-01 11:47:30

📍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:47:33

📍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)




Wall/Ceiling

📅 2024-02-01 11:47:34

📍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2024-02-01 11:47:39

📍 [43.5756075, -116.1337085](#)

🖼️ [Image](#)

📖 Bathroom 3: 1/2 Bath

📌 CONDITION

💬 COMMENTS

Exhaust Fan	- S -	
Flooring/Baseboard	- S -	
Light Fixture	- S -	
Medicine Cabinet/Mirror	- S -	
Sink/Faucet	- S -	
Switch/Outlet	- S -	
Toilet	- S -	
Toilet Paper Holder	- S -	
Towel Rack	- S -	
Wall/Ceiling	- S -	



📅 2024-02-01 11:53:32

📍 [43.5756328, -116.1337203](#)

🖼️ [Image](#)



📅 2024-02-01 11:53:36

📍 [43.5756328, -116.1337203](#)

🖼️ [Image](#)




Exhaust Fan

📅 2024-02-01 11:54:03

📍 [43.5755831, -116.1337387](#)

🖼️ [Image](#)




Flooring/Baseboard

📅 2024-02-01 11:54:06

📍 [43.5755831, -116.1337387](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:54:09

📍 [43.5755831, -116.1337387](#)

🖼️ [Image](#)



Light Fixture

📅 2024-02-01 11:54:14

📍 [43.5755831, -116.1337387](#)

🖼️ [Image](#)



Medicine Cabinet/Mirror

📅 2024-02-01 11:54:17

🔍 43.5755831, -116.1337387

🖼️ Image



Sink/Faucet

📅 2024-02-01 11:54:21

🔍 43.5755831, -116.1337387

🖼️ Image



Switch/Outlet

📅 2024-02-01 11:54:29

🔍 43.5755831, -116.1337387

🖼️ Image




Toilet

📅 2024-02-01 11:54:34

🔍 43.5755831, -116.1337387

🖼️ Image



Toilet

📅 2024-02-01 11:54:38

🔍 43.5755831, -116.1337387

🖼️ Image



Toilet Paper Holder

📅 2024-02-01 11:54:42

🔍 43.5755831, -116.1337387

🖼️ Image



Towel Rack

📅 2024-02-01 11:54:46

📍 [43.5755831, -116.1337387](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:54:50

📍 [43.5755831, -116.1337387](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:54:52

📍 [43.5755831, -116.1337387](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:54:54

📍 [43.5755831, -116.1337387](#)

🖼️ [Image](#)

📖 Bedroom

📌 CONDITION

💬 COMMENTS

Closet/Door/Track/Shelving	- S -	
Door/Knob/Lock	- S -	
Flooring/Baseboard	- S -	
Light Fixture/Fan	- S -	
Smoke / CO detector	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- - D	Holes in wall
Window Covering	- S -	
Window/Lock/Screen	- S -	



📅 2024-02-01 11:34:54
📍 [43.575476, -116.1337506](#)
🖼️ [Image](#)



📅 2024-02-01 11:35:01
📍 [43.575476, -116.1337506](#)
🖼️ [Image](#)



📅 2024-02-01 11:35:07
📍 [43.575476, -116.1337506](#)
🖼️ [Image](#)



📅 2024-02-01 11:35:14
📍 [43.575476, -116.1337506](#)
🖼️ [Image](#)



Closet/Door/Track/Shelving
📅 2024-02-01 11:34:29
📍 [43.575476, -116.1337506](#)
🖼️ [Image](#)



Closet/Door/Track/Shelving
📅 2024-02-01 11:34:30
📍 [43.575476, -116.1337506](#)
🖼️ [Image](#)



Closet/Door/Track/Shelving

📅 2024-02-01 11:34:32

🔍 [43.575476, -116.1337506](#)

🖼️ Image



Door/Knob/Lock

📅 2024-02-01 11:35:25

🔍 [43.575476, -116.1337506](#)

🖼️ Image



Door/Knob/Lock

📅 2024-02-01 11:35:33

🔍 [43.575476, -116.1337506](#)

🖼️ Image



Flooring/Baseboard

📅 2024-02-01 11:35:42

🔍 [43.5756091, -116.133652](#)

🖼️ Image



Flooring/Baseboard

📅 2024-02-01 11:35:44

🔍 [43.5756091, -116.133652](#)

🖼️ Image



Flooring/Baseboard

📅 2024-02-01 11:35:46

🔍 [43.5756091, -116.133652](#)

🖼️ Image




Flooring/Baseboard
📅 2024-02-01 11:35:48
📍 [43.5756091, -116.133652](#)
🖼️ [Image](#)




Flooring/Baseboard
📅 2024-02-01 11:35:49
📍 [43.5756091, -116.133652](#)
🖼️ [Image](#)



Flooring/Baseboard
📅 2024-02-01 11:35:50
📍 [43.5756091, -116.133652](#)
🖼️ [Image](#)




Light Fixture/Fan
📅 2024-02-01 11:35:55
📍 [43.5756091, -116.133652](#)
🖼️ [Image](#)



Smoke / CO detector
📅 2024-02-01 11:35:58
📍 [43.5756091, -116.133652](#)
🖼️ [Image](#)



Switch/Outlet
📅 2024-02-01 11:36:05
📍 [43.5756091, -116.133652](#)
🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:36:12

🔍 [43.5756091, -116.133652](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:36:15

🔍 [43.5756091, -116.133652](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:36:17

🔍 [43.5756091, -116.133652](#)

🖼️ [Image](#)




Wall/Ceiling

📅 2024-02-01 11:36:19

🔍 [43.5756091, -116.133652](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:36:24

🔍 [43.5756091, -116.133652](#)

🖼️ [Image](#)



Window Covering

📅 2024-02-01 11:36:29

🔍 [43.5756091, -116.133652](#)

🖼️ [Image](#)




2024-02-01 11:36:49 MST
 Window/Lock/Screen
 📅 2024-02-01 11:36:49
 🔍 43.5756091, -116.133652
 🖼️ Image



2024-02-01 11:36:54 MST
 Window/Lock/Screen
 📅 2024-02-01 11:36:54
 🔍 43.5756091, -116.133652
 🖼️ Image

📖 Bedroom 2	🔧 CONDITION	💬 COMMENTS
Closet/Door/Track/Shelving	- S -	
Door/Knob/Lock	- S -	
Flooring/Baseboard	- S -	
Light Fixture/Fan	- S -	
Smoke / CO detector	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	
Window Covering	- S -	
Window/Lock/Screen	- S -	



2024-02-01 11:37:25 MST
 📅 2024-02-01 11:37:25
 🔍 43.5756091, -116.133652
 🖼️ Image



2024-02-01 11:37:32 MST
 📅 2024-02-01 11:37:32
 🔍 43.5756091, -116.133652
 🖼️ Image



📅 2024-02-01 11:37:38
📍 [43.5756091, -116.133652](#)
🖼️ [Image](#)



📅 2024-02-01 11:37:44
📍 [43.5756086, -116.1336778](#)
🖼️ [Image](#)




Closet/Door/Track/Shelving
📅 2024-02-01 11:37:50
📍 [43.5756086, -116.1336778](#)
🖼️ [Image](#)



Closet/Door/Track/Shelving
📅 2024-02-01 11:37:59
📍 [43.5756086, -116.1336778](#)
🖼️ [Image](#)



Closet/Door/Track/Shelving
📅 2024-02-01 11:38:09
📍 [43.5756086, -116.1336778](#)
🖼️ [Image](#)



Door/Knob/Lock
📅 2024-02-01 11:38:16
📍 [43.5756086, -116.1336778](#)
🖼️ [Image](#)



Door/Knob/Lock

📅 2024-02-01 11:38:21

🔍 [43.5756086, -116.1336778](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:38:25

🔍 [43.5756086, -116.1336778](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:38:27

🔍 [43.5756086, -116.1336778](#)

🖼️ [Image](#)




Flooring/Baseboard

📅 2024-02-01 11:38:28

🔍 [43.5756086, -116.1336778](#)

🖼️ [Image](#)




Flooring/Baseboard

📅 2024-02-01 11:38:29

🔍 [43.5756086, -116.1336778](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:38:32

🔍 [43.5756086, -116.1336778](#)

🖼️ [Image](#)



Light Fixture/Fan

📅 2024-02-01 11:38:37

🔍 [43.5756086, -116.1336778](#)

🖼️ [Image](#)



Smoke / CO detector

📅 2024-02-01 11:38:41

🔍 [43.5756086, -116.1336778](#)

🖼️ [Image](#)




Switch/Outlet

📅 2024-02-01 11:38:46

🔍 [43.5756086, -116.1336778](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:38:50

🔍 [43.5756086, -116.1336778](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:38:53

🔍 [43.5756086, -116.1336778](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:38:55

🔍 [43.5756086, -116.1336778](#)

🖼️ [Image](#)



Window Covering

📅 2024-02-01 11:38:58

📍 43.5756086, -116.1336778

🖼️ Image



Window/Lock/Screen

📅 2024-02-01 11:39:07

📍 43.5756086, -116.1336778

🖼️ Image

📖 Bedroom 3

🔗 CONDITION

💬 COMMENTS

Closet/Door/Track/Shelving	- S -	
Door/Knob/Lock	- S -	
Flooring/Baseboard	- S -	
Light Fixture/Fan	- S -	
Smoke / CO detector	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	
Window Covering	- S -	
Window/Lock/Screen	- S -	



📅 2024-02-01 11:39:43

📍 43.5756086, -116.1336778

🖼️ Image



📅 2024-02-01 11:39:48

📍 43.5756086, -116.1336778

🖼️ Image




📅 2024-02-01 11:39:54
📍 [43.5755704, -116.133712](#)
🖼️ [Image](#)



📅 2024-02-01 11:40:00
📍 [43.5755704, -116.133712](#)
🖼️ [Image](#)



Closet/Door/Track/Shelving
📅 2024-02-01 11:40:12
📍 [43.5755704, -116.133712](#)
🖼️ [Image](#)



Closet/Door/Track/Shelving
📅 2024-02-01 11:40:15
📍 [43.5755704, -116.133712](#)
🖼️ [Image](#)



Closet/Door/Track/Shelving
📅 2024-02-01 11:40:16
📍 [43.5755704, -116.133712](#)
🖼️ [Image](#)



Door/Knob/Lock
📅 2024-02-01 11:40:22
📍 [43.5755704, -116.133712](#)
🖼️ [Image](#)



Door/Knob/Lock

📅 2024-02-01 11:40:28

🔍 [43.5755704, -116.133712](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:40:41

🔍 [43.5755704, -116.133712](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:40:43

🔍 [43.5755704, -116.133712](#)

🖼️ [Image](#)




Flooring/Baseboard

📅 2024-02-01 11:40:44

🔍 [43.5755704, -116.133712](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:40:47

🔍 [43.5755704, -116.133712](#)

🖼️ [Image](#)




Light Fixture/Fan

📅 2024-02-01 11:40:52

🔍 [43.5755704, -116.133712](#)

🖼️ [Image](#)



Smoke / CO detector

📅 2024-02-01 11:40:55

📍 [43.5755704, -116.133712](#)

🖼️ [Image](#)



Switch/Outlet

📅 2024-02-01 11:41:00

📍 [43.5755704, -116.133712](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:41:05

📍 [43.5755704, -116.133712](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:41:07

📍 [43.5755704, -116.133712](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:41:13

📍 [43.5755704, -116.133712](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:41:15

📍 [43.5755704, -116.133712](#)

🖼️ [Image](#)



Window Covering

📅 2024-02-01 11:41:20

📍 [43.5755704, -116.133712](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2024-02-01 11:41:29

📍 [43.5755704, -116.133712](#)

🖼️ [Image](#)

📖 Bedroom 4

📌 CONDITION

💬 COMMENTS

Closet/Door/Track/Shelving	- S -	
Door/Knob/Lock	- S -	
Flooring/Baseboard	- S -	
Light Fixture/Fan	- S -	
Smoke / CO detector	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	
Window Covering	- S -	
Window/Lock/Screen	- S -	



📅 2024-02-01 11:42:09

📍 [43.5756224, -116.1337021](#)

🖼️ [Image](#)



📅 2024-02-01 11:42:16

📍 [43.5756224, -116.1337021](#)

🖼️ [Image](#)



📅 2024-02-01 11:42:22

📍 [43.5756224, -116.1337021](#)

🖼️ [Image](#)



📅 2024-02-01 11:42:30

📍 [43.5756224, -116.1337021](#)

🖼️ [Image](#)




Closet/Door/Track/Shelving

📅 2024-02-01 11:42:34

📍 [43.5756224, -116.1337021](#)

🖼️ [Image](#)



Closet/Door/Track/Shelving

📅 2024-02-01 11:42:43

📍 [43.5756224, -116.1337021](#)

🖼️ [Image](#)



Closet/Door/Track/Shelving

📅 2024-02-01 11:42:50

📍 [43.5756224, -116.1337021](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2024-02-01 11:42:58

📍 [43.5756224, -116.1337021](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2024-02-01 11:43:02

📍 [43.5756224, -116.1337021](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:43:07

📍 [43.5756224, -116.1337021](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:43:09

📍 [43.5756224, -116.1337021](#)

🖼️ [Image](#)




Flooring/Baseboard

📅 2024-02-01 11:43:11

📍 [43.5756224, -116.1337021](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:43:13

📍 [43.5756224, -116.1337021](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:43:17

📍 [43.5756224, -116.1337021](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:43:19

📍 [43.5756224, -116.1337021](#)

🖼️ [Image](#)




Light Fixture/Fan

📅 2024-02-01 11:43:41

📍 [43.5756224, -116.1337021](#)

🖼️ [Image](#)



Smoke / CO detector

📅 2024-02-01 11:43:50

📍 [43.5756224, -116.1337021](#)

🖼️ [Image](#)



Switch/Outlet

📅 2024-02-01 11:43:56

📍 [43.5757435, -116.134014](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:44:01

📍 [43.5757435, -116.134014](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:44:03

📍 [43.5757435, -116.134014](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:44:05

🔍 [43.5757435, -116.134014](#)

🖼️ Image



Wall/Ceiling

📅 2024-02-01 11:44:07

🔍 [43.5757435, -116.134014](#)

🖼️ Image



Window Covering

📅 2024-02-01 11:44:11

🔍 [43.5757435, -116.134014](#)

🖼️ Image



Window/Lock/Screen

📅 2024-02-01 11:44:21

🔍 [43.5757435, -116.134014](#)

🖼️ Image



Window/Lock/Screen

📅 2024-02-01 11:44:31

🔍 [43.5757435, -116.134014](#)

🖼️ Image

📖 Dining Room

🔧 CONDITION

💬 COMMENTS

Flooring/Baseboard	- S -	
Light Fixture/Fan	- S -	

 Dining Room	 CONDITION	 COMMENTS
Switch/Outlet	- S -	
Wall/Ceiling	- S -	
Window Covering	- S -	
Window/Lock/Screen	- S -	



2024-02-01 11:55:46 MST

 2024-02-01 11:55:46
 [43.5755831, -116.1337387](#)
 Image



2024-02-01 11:55:51 MST

Flooring/Baseboard
 2024-02-01 11:55:51
 [43.5755831, -116.1337387](#)
 Image



2024-02-01 11:55:57 MST

Flooring/Baseboard
 2024-02-01 11:55:57
 [43.5755831, -116.1337387](#)
 Image



2024-02-01 11:56:06 MST

Light Fixture/Fan
 2024-02-01 11:56:06
 [43.5756363, -116.1337315](#)
 Image



Switch/Outlet

📅 2024-02-01 11:56:37

📍 [43.5756363, -116.1337315](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:56:41

📍 [43.5756363, -116.1337315](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:56:43

📍 [43.5756363, -116.1337315](#)

🖼️ [Image](#)



Window Covering

📅 2024-02-01 11:56:55

📍 [43.5756363, -116.1337315](#)

🖼️ [Image](#)



Window Covering

📅 2024-02-01 11:57:09

📍 [43.5756363, -116.1337315](#)

🖼️ [Image](#)

📖 Kitchen

🔧 CONDITION

💬 COMMENTS

Cabinets/Drawers	- S -	
Counter	- S -	

 Kitchen	 CONDITION	 COMMENTS
Dishwasher	- S -	
Faucet/Plumbing	- S -	
Flooring/Baseboard	- S -	
Light Fixture	- S -	
Microwave	- S -	
Oven	- S -	
Pantry / Shelves	- S -	
Range/Fan/Hood/Filter	- S -	
Refrigerator	- S -	
Sink/Disposal	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	



2024-02-01 12:01:30 MST

 2024-02-01 12:01:30

 [43.5755582, -116.1340024](#)

 [Image](#)



2024-02-01 12:01:38 MST

Cabinets/Drawers

 2024-02-01 12:01:38

 [43.5755582, -116.1340024](#)

 [Image](#)



2024-02-01 12:01:41 MST

Cabinets/Drawers

 2024-02-01 12:01:41

 [43.5755582, -116.1340024](#)

 [Image](#)



2024-02-01 12:01:47 MST

Cabinets/Drawers

 2024-02-01 12:01:47

 [43.5755582, -116.1340024](#)

 [Image](#)



Cabinets/Drawers

📅 2024-02-01 12:01:56

📍 [43.5755582, -116.1340024](#)

🖼️ [Image](#)




Cabinets/Drawers

📅 2024-02-01 12:02:00

📍 [43.5755582, -116.1340024](#)

🖼️ [Image](#)



Cabinets/Drawers

📅 2024-02-01 12:02:03

📍 [43.5755582, -116.1340024](#)

🖼️ [Image](#)




Counter

📅 2024-02-01 12:02:17

📍 [43.5755582, -116.1340024](#)

🖼️ [Image](#)



Counter

📅 2024-02-01 12:02:20

📍 [43.5756992, -116.1336085](#)

🖼️ [Image](#)



Counter

📅 2024-02-01 12:02:23

📍 [43.5756992, -116.1336085](#)

🖼️ [Image](#)



Dishwasher

📅 2024-02-01 12:02:28

📍 [43.5756992, -116.1336085](#)

🖼️ [Image](#)



Dishwasher

📅 2024-02-01 12:02:33

📍 [43.5756992, -116.1336085](#)

🖼️ [Image](#)




Faucet/Plumbing

📅 2024-02-01 12:02:40

📍 [43.5756992, -116.1336085](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 12:02:44

📍 [43.5756992, -116.1336085](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 12:02:46

📍 [43.5756992, -116.1336085](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 12:02:50

📍 [43.5756992, -116.1336085](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 12:02:54

📍 43.5756992, -116.1336085

🖼️ Image



Flooring/Baseboard

📅 2024-02-01 12:02:59

📍 43.5756992, -116.1336085

🖼️ Image



Light Fixture

📅 2024-02-01 12:03:05

📍 43.5756992, -116.1336085

🖼️ Image



Microwave

📅 2024-02-01 12:03:15

📍 43.5756992, -116.1336085

🖼️ Image



Microwave

📅 2024-02-01 12:03:18

📍 43.5756992, -116.1336085

🖼️ Image



Oven

📅 2024-02-01 12:03:24

📍 43.5756992, -116.1336085

🖼️ Image



Oven

📅 2024-02-01 12:03:35

📍 [43.5756992, -116.1336085](#)

🖼️ [Image](#)



Oven

📅 2024-02-01 12:03:41

📍 [43.5756992, -116.1336085](#)

🖼️ [Image](#)




Pantry / Shelves

📅 2024-02-01 12:03:49

📍 [43.5756992, -116.1336085](#)

🖼️ [Image](#)



Pantry / Shelves

📅 2024-02-01 12:03:51

📍 [43.5756992, -116.1336085](#)

🖼️ [Image](#)



Range/Fan/Hood/Filter

📅 2024-02-01 12:03:57

📍 [43.5756992, -116.1336085](#)

🖼️ [Image](#)



Refrigerator

📅 2024-02-01 12:04:05

📍 [43.5756992, -116.1336085](#)

🖼️ [Image](#)



Refrigerator

📅 2024-02-01 12:04:13

📍 [43.5756992, -116.1336085](#)

🖼️ [Image](#)



Refrigerator

📅 2024-02-01 12:04:20

📍 [43.5756992, -116.1336085](#)

🖼️ [Image](#)



Refrigerator

📅 2024-02-01 12:04:23

📍 [43.5756689, -116.1336815](#)

🖼️ [Image](#)



Sink/Disposal

📅 2024-02-01 12:04:31

📍 [43.5756689, -116.1336815](#)

🖼️ [Image](#)




Switch/Outlet

📅 2024-02-01 12:04:47

📍 [43.5756689, -116.1336815](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 12:04:52

📍 [43.5756689, -116.1336815](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 12:04:58

📍 [43.5756689, -116.1336815](#)

🖼️ [Image](#)

📖 Laundry Room

🔧 CONDITION

💬 COMMENTS

Cabinet/Counter/Shelving	- S -	
Door/Knob/Lock	- S -	
Faucet/Valve	- S -	
Flooring/Baseboard	- S -	
Light Fixture/Fan	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	



📅 2024-02-01 11:50:49

📍 [43.5754142, -116.1337135](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2024-02-01 11:50:52

📍 [43.5754142, -116.1337135](#)

🖼️ [Image](#)



Cabinet/Counter/Shelving

📅 2024-02-01 11:50:58

🔍 [43.5754142, -116.1337135](#)

🖼️ [Image](#)



Door/Knob/Lock

📅 2024-02-01 11:51:10

🔍 [43.5754142, -116.1337135](#)

🖼️ [Image](#)




Door/Knob/Lock

📅 2024-02-01 11:51:15

🔍 [43.5754142, -116.1337135](#)

🖼️ [Image](#)




Faucet/Valve

📅 2024-02-01 11:51:24

🔍 [43.5754142, -116.1337135](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:51:28

🔍 [43.5754142, -116.1337135](#)

🖼️ [Image](#)



Light Fixture/Fan

📅 2024-02-01 11:51:32

🔍 [43.5754142, -116.1337135](#)

🖼️ [Image](#)



Switch/Outlet

📅 2024-02-01 11:51:37

📍 [43.5754142, -116.1337135](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:51:41

📍 [43.5754142, -116.1337135](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:51:43

📍 [43.5754142, -116.1337135](#)

🖼️ [Image](#)

📖 Living Room

📌 CONDITION

💬 COMMENTS

Fireplace Equipment	- S -	
Flooring/Baseboard	- S -	
Light Fixture/Fan	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	
Window Covering	- - D	Broken wood slat
Window/Lock/Screen	- S -	



📅 2024-02-01 11:57:21
📍 [43.5756363, -116.1337315](#)
🖼️ [Image](#)




Fireplace Equipment
📅 2024-02-01 11:57:28
📍 [43.5756363, -116.1337315](#)
🖼️ [Image](#)



Light Fixture/Fan
📅 2024-02-01 11:57:46
📍 [43.5756363, -116.1337315](#)
🖼️ [Image](#)




Switch/Outlet
📅 2024-02-01 11:57:52
📍 [43.5756363, -116.1337315](#)
🖼️ [Image](#)



Wall/Ceiling
📅 2024-02-01 11:57:57
📍 [43.5756363, -116.1337315](#)
🖼️ [Image](#)



Wall/Ceiling
📅 2024-02-01 11:57:59
📍 [43.5756363, -116.1337315](#)
🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:58:02

🔍 [43.5756363, -116.1337315](#)

🖼️ [Image](#)



Window Covering

📅 2024-02-01 11:58:09

🔍 [43.5756339, -116.1337014](#)

🖼️ [Image](#)



Window Covering

📅 2024-02-01 11:58:11

🔍 [43.5756339, -116.1337014](#)

🖼️ [Image](#)



Window Covering

📅 2024-02-01 11:58:13

🔍 [43.5756339, -116.1337014](#)

🖼️ [Image](#)



Window Covering

📅 2024-02-01 11:58:18

🔍 [43.5756339, -116.1337014](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2024-02-01 11:58:38

🔍 [43.5756339, -116.1337014](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2024-02-01 11:58:52

📍 [43.5756339, -116.1337014](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2024-02-01 11:59:04

📍 [43.5756339, -116.1337014](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2024-02-01 11:59:16

📍 [43.5756339, -116.1337014](#)

🖼️ [Image](#)

📖 Office

📌 CONDITION

💬 COMMENTS

Closet/Door/Track/Shelving	- S -	
Door/Knob/Lock	- S -	
Flooring/Baseboard	- S -	
Light Fixture/Fan	- S -	
Switch/Outlet	- S -	
Wall/Ceiling	- S -	
Window Covering	- S -	
Window/Lock/Screen	- S -	



📅 2024-02-01 11:52:00

📍 [43.5756328, -116.1337203](#)

🖼️ [Image](#)



📅 2024-02-01 11:52:01

📍 [43.5756328, -116.1337203](#)

🖼️ [Image](#)




Closet/Door/Track/Shelving

📅 2024-02-01 11:52:11

📍 [43.5756328, -116.1337203](#)

🖼️ [Image](#)



Closet/Door/Track/Shelving

📅 2024-02-01 11:52:22

📍 [43.5756328, -116.1337203](#)

🖼️ [Image](#)



Flooring/Baseboard

📅 2024-02-01 11:52:31

📍 [43.5756328, -116.1337203](#)

🖼️ [Image](#)



Light Fixture/Fan

📅 2024-02-01 11:52:35

📍 [43.5756328, -116.1337203](#)

🖼️ [Image](#)



Switch/Outlet

📅 2024-02-01 11:52:40

📍 [43.5756328, -116.1337203](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:52:45

📍 [43.5756328, -116.1337203](#)

🖼️ [Image](#)



Wall/Ceiling

📅 2024-02-01 11:52:46

📍 [43.5756328, -116.1337203](#)

🖼️ [Image](#)



Window Covering

📅 2024-02-01 11:52:49

📍 [43.5756328, -116.1337203](#)

🖼️ [Image](#)



Window/Lock/Screen

📅 2024-02-01 11:52:55

📍 [43.5756328, -116.1337203](#)

🖼️ [Image](#)

📖 Back Yard/Exterior

🔧 CONDITION

💬 COMMENTS

Building Exterior	- S -	
Fence/Gate	- S -	

Back Yard/Exterior

CONDITION

COMMENTS

Hoses/Spigots	- S -	
Landscaping	- S -	
Light Fixture	- S -	
Other	- S -	
Patio Cover	- S -	
Patio/Deck/Balcony	- S -	
Pool/Heater/Equipment	- S -	
Porch/Stairs	- S -	
Spa/Cover/Equipment	- S -	
Sprinkler/Timer	- S -	
Walkway	- S -	



2024-02-01 12:05:19 MST

📅 2024-02-01 12:05:19

📍 [43.5756689, -116.1336815](#)

🖼️ Image




2024-02-01 12:05:20 MST

📅 2024-02-01 12:05:20

📍 [43.5756689, -116.1336815](#)

🖼️ Image



2024-02-01 12:05:22 MST

📅 2024-02-01 12:05:22

📍 [43.5756689, -116.1336815](#)

🖼️ Image

Garage/Parking

CONDITION

COMMENTS

Cabinet/Counter	- S -	
Driveway/Floor	- S -	

 Garage/Parking	 CONDITION	 COMMENTS
Garage Door	- S -	
Light Fixture	- S -	
Switch/Outlet	- S -	



 2024-02-01 11:48:58

 [43.5755563, -116.1337309](#)

 [Image](#)



 2024-02-01 11:49:00

 [43.5755563, -116.1337309](#)

 [Image](#)



Cabinet/Counter

 2024-02-01 11:49:06

 [43.5755563, -116.1337309](#)

 [Image](#)



Cabinet/Counter

 2024-02-01 11:49:12

 [43.5755563, -116.1337309](#)

 [Image](#)



Driveway/Floor

 2024-02-01 11:49:16

 [43.5755563, -116.1337309](#)

 [Image](#)



Driveway/Floor

 2024-02-01 11:49:17

 [43.5755563, -116.1337309](#)

 [Image](#)



Driveway/Floor

📅 2024-02-01 11:49:19

📍 [43.5755563, -116.1337309](#)

🖼️ [Image](#)



Driveway/Floor

📅 2024-02-01 11:49:21

📍 [43.5755563, -116.1337309](#)

🖼️ [Image](#)



Garage Door

📅 2024-02-01 11:49:31

📍 [43.5755563, -116.1337309](#)

🖼️ [Image](#)



Garage Door

📅 2024-02-01 11:49:36

📍 [43.5755563, -116.1337309](#)

🖼️ [Image](#)



Light Fixture

📅 2024-02-01 11:49:40

📍 [43.5755563, -116.1337309](#)

🖼️ [Image](#)



Light Fixture

📅 2024-02-01 11:49:43

📍 [43.5755563, -116.1337309](#)

🖼️ [Image](#)



Switch/Outlet

📅 2024-02-01 11:49:52

📍 [43.5755563, -116.1337309](#)

🖼️ [Image](#)

📖 Keys/Remotes/Devices

🔗 CONDITION

💬 COMMENTS

Keys	- S -	
Other	- S -	
Remotes/Devices	- S -	
Swag	- S -	



📅 2024-02-01 12:11:36

📍 [43.5756611, -116.1337397](#)

🖼️ [Image](#)

📖 Systems

🔗 CONDITION

💬 COMMENTS

Air Conditioning/Filter	- S -	
Breaker Box	- S -	
Evidence of Pest Issue	- S -	
Furnace	- S -	
Other	- S -	
Sewer Cleanout	- S -	
Sprinkler/Timer	- S -	

📖 Systems	🔧 CONDITION	💬 COMMENTS
Thermostat	- S -	
Water Heater	- S -	
Water Softener	- S -	
Whole House Fan	- S -	



📅 2024-02-01 11:50:03

📍 [43.5754142, -116.1337135](#)

🖼️ [Image](#)

Additional Comments

Final Comments

To dispute any findings of this inspection please notify us within 3 business days.

Agent / Inspector Signature